



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE			Ref: CC4/ASM22008484/Kpa3q2 Date: 31/01/2023 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 7209U	Veh. Inspected	GBL 2970A
	Policy No.	P2465679	Coverage (\$)	0.00
	Claim No.	S2M04A34	Excess (\$)	0.00
	Assign From		Assign Date	31/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	NISSAN NV200	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	VM20164601	Colour	METALLIC GREY
	Odometer	73541 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/70 R14	MICHELIN	9 mm
	L/H Front Tyre	185/70 R14	MICHELIN	9 mm
	R/H Rear Tyre	185/70 R14	MICHELIN	9 mm
	L/H Rear Tyre	185/70 R14	MICHELIN	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/08/2022	Inspection Date	02/09/2022
	Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	