

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

8 S	XA INSURANCE F	PTF LTD			
SII		12 215	Ref:	CS/ASM22008488/Acy3m4	
ΑT	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	11/11/2022	
	TTN: OH VALE		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
In	sured Veh.	YP 211C	Veh. Inspected	SME 8064H	
Po	olicy No.	GA588986	Coverage (\$)	0.00	
CI	laim No.	S2M04A37	Excess (\$)	0.00	
As	ssign From	OH VALE	Assign Date	31/08/2022	
2.	Vehicle Particulars & Condition				
Ma	ake & Model	HONDA CIVIC	c.c	1597	
Er	ngine No.	HIDDEN	Year of Reg.	2018	
CI	hassis No.	MRHFC5650JT001501	Colour	BLUE	
0	dometer	44523 KM	Steering	IN ORDER	
Br	rakes	IN ORDER	Modification	SPORTS RIM	
G	eneral	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
R/	/H Front Tyre	215/45 R16	HANKOOK	6 mm	
L/	/H Front Tyre	215/45 R16	HANKOOK	6 mm	
R/	/H Rear Tyre	215/45 R16	HANKOOK	6 mm	
L/	/H Rear Tyre	215/45 R16	HANKOOK	6 mm	
4.	Description of Damages				
T⊦	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.				
DA	DAMAGES SEE DETAILS.				
5.	General Information				
Ad	ccident Date	30/08/2022	Inspection Date	31/08/2022	
Sı	urvey held at	UNIMOTOR COMPANY			
		1 KAKI BUKIT AVE 6, #01-94 (AUTOBAY @ KAKI BUKIT) SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
ES	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days				