ASS. RECOBY: Steve		
	· AS	SIGNMENT
From:	Date:	Veh No: SNG 5988 Yr Regn: 15/6/0027
Eslimated Cost:	•	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD ITP WS ITP RES I OD	RES / EVA / INV / MV	Truck / Traller or
To Inspect Vehicle No:	•	Make: TOUCH, HOTTIN c.c 7487
at Workshop m/s	And the second s	Colour, Black A/C: Insured / Std / NI / NA
		Sp.Reading 3813 T/Radio: Insured / Std / NI / NA
		Eng/No:
-		CNO: TTEAP3BH 40 JOO 1204
Claims No.		Gen. Cond: Pool / Fair / Poor / Burnt
	Excess:	Steering: Inorder / Jaimmed / Leaked / Burnt or
Sum Insured:	Excess.	Brake: Ingragr / Jammed / Leaked / Burnt or
(Client's Record)		Modi: Nii / SRIM / STD A/RIM or
Make of Veh:	·	- Orlet pil
(Policy Condition)		. R:
Remark: The veh had com	•	
repair at the time	of inspection.	TOYO I YOKO or .
Bal. or Market Value:		Fron! Rear
IDAC Accident Rport	Consistent?: Yes or No	R/Bal. 5 mm R/Bal. 5 mm
GIA / PR Seen:	Consistent?: Yes or No	UBal. 5 mm UBal. 5 mm
Est Repairs:	days Res.: Yes or No	D.O.A. 1918/12
Lum Sum:	% · 3 Val.: Yes or No	Survey held at BOYNE (
-	ė. upe	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. /	Vehicle: IN.	7 OUT
Date:Pe	rson Contacted:	The U/C / Chassis frame / Body Structure affected due to ceilision.
Date / Time   Action /	Instruction	
ЈУ	1-101V.	,
·		
	····	
<u></u>		
Dale/Time, File Pass to?	: Preli. Report	Days Of Repair:
70	: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Final Kapole	Transportation:
Daterrane, 1 no Netoni Wi	٨	dd Fee: : Site Insp (\$ )_s +Rs_si
. =	<i>1</i> -50	
	•	
Repair Formai :		: Tech, Invs (\$) others
Lump Sum / I.B.f: (	₩ <u></u> }	:Weel:end (#)
		TOTAL
	·. 150	The state of the s
		· · · · · · · · · · · · · · · · · · ·



**Borneo Motors** 

Inchcape

Co. Reg No.: 196700086Z GST Reg No.: MR-8500000-9 No. 2 PANDAN CRESCENT SINGAPORE 128462, Tel no.: 6631 1188 Stere (LKK) Mch. 14/9/72,19.00 P/P



**TOYOTA** 

**ESTIMATE** 

Account Details		Account No.			Customer Details						
THIRD PARTY CLAIM				Document No.		M/S Sky Property Pte Ltd 360 Orchard Road #07-03 International Building Singapore 238869					
		and the second second	Document Date 14/09/2022		Mobile: 97766485						
Year	ear Model Variant Reg.		Reg. Date	Reg. No.	Kilome	eters V	/ip No.	Order No. / Remarks			
022	022 AXUH80R ANXGB 2P		15/06/2022	SNG5988P 0		0 1	7235	65/DS/S	65/DS/SNG5988P		
С	Chassis No. Engine No.		Terms	SA / Counter	Vehicle		hicle In	Collected On			
JTEAC	D3BH40J001204	A25A5704054	60	Francis Cher T	s	//	0.00	//		0.00	
Cd		Job/Parts Des	cription			Qty	Unit Price	Disc %		Amount	
z	BP-SUNDRY SUN T/P INS. : T/P VEH. : SHB2I ACC DATE : 29.0								30	50.00	
	BY: BP-LAB2 REPAIR TAIL-GATE DENTED. REPLACE AND REALIGN REAR BUMPER BP-RES2 SPRAY PAINT ON TAIL-GATE AND REAR BUMPER SPP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE PER PANEL APPLICATION ON TAIL-GATE AND REAR BUMPER  10  11  12  13						900.00 1475.00				
4 S							183.18				
6 B 7 1 8 2 9 3 10 4	B BP-LAB2 DRILL HOLE TO INSTALL REVERSE SENSOR. B BP-MECH2 RESET AND REPROGRAMME ECU. 1 T75442-48170 PLATE, BACK DOOR / (1997) 2 T75445-48140 PLATE, BACK DOOR / (1997) 3 T52159-48966 COVER, RR BUMPER / (1997) 4 T52169-48160 COVER, RR BUMPER, / (1997) 5 T89348-48320 C1 RETAINER, ULTRASONIC / (1997)					1.00 1.00 1.00 1.00 2.00	57.50 59.10 549.70 455.70 36.00			180.00 180.00, 57.50 59.10 549.70 455.70 72.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd  Customer's Sig		er's Signature	e Charge Summary		,	Total		4,162.18			
	LKK Auto Con Strains hence notify the Repairer of the following:  • To resurvey before/after spray painting • To display damaged part(s) during the strains of the strains		ting	Labour		1,194.00 2,785.00 183.18	Less	Less		291.35 0.00	
No illegal modification(s) is allowed     Supplementary item(s) and a sufficient Prejudice. E			tion Prejudice* basis	basis		0.00 0.00 A		Amount Due		4,453.53	
		and opproval from Insu	rance Company  Custome	er Copy							

# **SINGAPORE ACCIDENT STATEMENT**

1. Please report correctly the details of the accident to speed up the claims process.

2. This Form must be completed by the Policyholder and/or the Actual Driver.

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

3. Information provided into the east during the distribution of policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and the GIA Records Management Centre established by the General Insurance Centre of Singapore (GIA) for archiving of this report of the Insurance Centre of Singapore (GIA) for archiving of the General Insurance Centre of Singapore (GIA) for archiving of the General Insurance Centre of Singapore (GIA) for archiving of the General Insurance Centre of Singapore (GIA) for archiving of Singapore (GIA) for archiving Centre

# ACCIDENT STATEMENT

Date of Submission Reported by

Date of Accident

Exact Location of Accident Additional Location Information

Country/State of Loss

29/08/2022 15:50 (SGT)

Driver

29/08/2022 10:43 (SGT)

Singapore

HOLLAND ROAD TRAFFIC LIGHT TO PIERCE ROAD

Singapore

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SNG5988P

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No

Alternative Phone No

Yes

SKY PROPERTY PTE LTD

2XXXXX342M

LYDIA.WONG@MARRISONHOTEL.COM

(Phone) +65-63388353

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Transmission

CC

Toyota Harrier

No - Reporting only

Private car Auto

2500

INSURANCE COMPANY

Name of Insurance Company

Policy Number / Cover Note Number

AIG Asia Pacific Insurance Pte. Ltd.

7220067937

DRIVER

Name of Driver

NRIC No Date Of Birth

Occupation Accident report SB0K228T000B REYNOLD SAMEL LAM

TXXXX056G 04/11/2000 Indoor

Page 1 of 21



Date Of Driving Pass Driving experience

Gender Mobile Number Alt. Phone Number

Email Address Address

Address complement

Postcode Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions

Weather Conditions Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident

Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?

Was any other vehicle or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

Translator's name Translator's ID

Translator's phone number

Translator's email

Original language used in the statement

DETAILS OF POLICE ACTION

Was the accident reported to the police? Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

Yes No

25/03/2021

Male

249692

Employee

No

No

Clear

Dry

No

No

Yes

1

No

No

No

2

1 YEAR AND 5 MONTHS

8 CUSCADEN WALK #28-01

Collision - Head to Rear

REYNOLDLAM041100@GMAIL.COM

(Phone) +65-83998638

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour

Vehicle Category Name of Driver NRIC No SHB2P

.

-Taxi JINIM SXXXX382I

Accident report SB0K228T000B

Page 2 of 21



 Contact Number
 (Phone) +65-87982527

 Address

 Address complement

 Postcode

 Insurance Company Name

 Nature Of Damage

 Details of property damaged in accident

 No. Of Passenger (Including Driver)





### SKETCH PLAN

## IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process
- This Form must be completed by the Policyholder and/or the Actual Driver
- Information provided must be as <u>fruitful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

## 5. Any false reporting may be referred to the Traffic Police Department for investigation.

- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8 Consent under the Personal Data Protection Act (PDPA)

t understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ('GIA') may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of.

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims.

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me,

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims

#### (collectively the 'Purposes')

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder & Sigha Qa Sate & Time

29/68/2672 4:42 Oriver's Signature (8 driver's not the policyholdon) / Date

Witnessed by Reporting Centre Personnel (Name as in NRIC//D card)

Sketch Plan

Holland Round

A-Dun (at B-third party (at 1)

Accident report SB0K228T000B

Page 4 of 21



bescribe circumstance of the Accident  The weather was dee clear and the road way was dry. I was stationary at the traffic light along Hilland Road and there was a taxis behind my car which was stationary as well. " Wentle light turn green, the car infront of me cauld not make the to a bus and thus I had to remain stationary as well. However, the taxis behind moved forward and collided into Mire from the back.

If We declare the foregoing particulars are true in every respect.

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)