

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: **\$600.00**  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: YR 68744 Yr Regn: 12/5/22  
 Type: M.Car / M.Cycle / Bus / Van /  Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Dym 150 c.c. 1755  
 Colour: Silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 9485 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JHHA6KVK690K 00 2262  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: NI / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 175/75R15  
 R: 1

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 99k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front Rear  
 R/Bal. 4 mm R/Bal. 4 mm  
 L/Bal. 4 mm L/Bal. 4 mm  
 D.O.A. 18/8/22 D.O.I. 31/8/22  
 Survey held at Hua Hong  
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or  
Front RH  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
09/12/2022	Finalise P/P \$ 9,751.25 @ 10 days (Red \$1,732.80/15%)

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Report Format: \_\_\_\_\_  
 Lump Sum / L.S. (\$) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$) \_\_\_\_\_  
 : Interview (\$) \_\_\_\_\_  
 : Tech. Invs (\$) \_\_\_\_\_  
 : Weekend (\$) \_\_\_\_\_  
 Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS. \$ \_\_\_\_\_  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH1412
Vehicle No.	: YQ6874U
Make & Model	: TOYOTA DYNA 150 5MT

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
<b>PARTS (LIST ITEMS)</b>				
1	Front Windscreen rubber seal / TN		\$100.00	
1	Wiper arm rh / BT		\$70.00	
1	Wiper arm cover rh / MIS		\$10.00	
1	Wiper panel / DD		\$140.00	
1	Front panel / DD		\$450.00	
1	Front side panel rh / MIS		\$95.00	
1	Front side panel clips @4*\$3 / MC		\$12.00	
1	Center grille assy / BR		\$280.00	
1	Center grille logo badge / MC		\$45.00	
1	Center grille clips @10*\$3 / MC		\$30.00	
1	Headlamp rh / BR		\$290.00	
1	Front bumper / BR		\$220.00	
1	Front bumper fog lamp cover rh / BR		\$60.00	
1	Front bumper side bracket rh / BT		\$100.00	
1	Side mirror rh / CUT		\$75.00	
1	Front door rh / DD		\$580.00	
1	Front door lower hinge rh / BT		\$45.00	
1	Front door window side garnish rh / CUT		\$50.00	
1	Front door weatherstrip / CRM		\$90.00	
1	Front door lower rubber seal / TN		\$35.00	
1	Step up garnish / BR		\$120.00	
1	Step up garnish bracket / BT		\$120.00	
1	Wheel arch rubber seal Rh / TN		\$25.00	
1	Wheel arch front mudflap panel rh / DD		\$130.00	
1	Wheel arch rear mudflap rh / CRM		\$90.00	
1	Wheel arch rear mudflap lower rubber shield rh / TN		\$90.00	
1	Wheel arch rear mudflap bracket rh / BT		\$180.00	
1	Air cleaner box / BR		\$270.00	
1	Brake air vacuum box / DD		\$180.00	
1	Brake air vacuum box sensor / BR		\$70.00	
1	Steering rack control box / ?		\$1,800.00	

1	Front absorber rh ?				\$70.00	
1	Front lower arm ?				\$240.00	
1	Front lower arm ball joint ?				\$75.00	
1	Front upper arm ?				\$320.00	
1	Front knuckle arm ?				\$240.00	
1	Rack end rh / 07				\$75.00	
1	Tie rod end Rh / 07				\$75.00	
1	Front door pillar RH (Repair refer to labour)				\$0.00	
1	Front floor panel (Repair refer to labour)				\$0.00	
1	A pillar RH (Repair refer to labour)				\$0.00	
		<b>Part Items Total:</b>			<b>\$6,947.00</b>	
			15%		<b>\$1,042.05</b>	
					<b>\$7,989.05</b>	
<b>SPECIAL NETT ITEMS</b>						
1	Front bumper clips / NR				\$35.00	
1	Front panel sealant / NR				\$60.00	
1	IU Sticker / NR				\$10.00	
		<b>SN Items Total:</b>			<b>\$105.00</b>	
		<b>Total Parts:</b>			<b>\$8,094.05</b>	



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref	: WH1412
Vehicle No.	: YQ6874U
Make & Model	: TOYOTA DYNA 150 5MT

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	<b>LABOUR</b> To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1400.00	1200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	1400.00	1000
3	To remove and repair/refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To remove and replace Front windscreen	100.00	/
5	To remove and replace front undercarriage RH	200.00	/
6	To remove and refit/replace front door RH fitting, trimmings, garnish, window glass and lock mechanism	150.00	50
7	To carried out wheel alignment	80.00	/
<b>Labour Total :</b>		<b>3390.00</b>	
<b>TOTAL (PARTS &amp; LABOUR):</b>		<b>11484.05</b>	

Steve (LKK)  
31/8/22, 11.00

OD- L1 / LL  
EXPERI- ?  
PIP  
by RL y  
10 dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Signature: \_\_\_\_\_ is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	30/08/2022 11:40 (SGT)
Reported by	Both
Date of Accident	18/08/2022 23:30 (SGT)
Exact Location of Accident	Near Esplanade Stn Exit F, Singapore 189768
Additional Location Information	JUNCTION OF BRAS BASAH ROAD AND BEACH ROAD
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... YQ6874U

### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	FT GLOBAL PTE LTD
Company Reg No	2XXXXX088M
Email Address	FTGLOBALACCS@GMAIL.COM
Mobile Phone No	(Phone) +65-63391187
Alternative Phone No	+65-88581339

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2800

### INSURANCE COMPANY

Name of Insurance Company	Lonpac Insurance Bhd
Policy Number / Cover Note Number	Z/22/VC00/113342

### DRIVER

Name of Driver	HOH KWAN HUNG
Work Permit No	GXXXX149R
Date Of Birth	13/09/1989
Occupation	Outdoor

Date Of Driving Pass	27/11/2013
Driving experience	8 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-86544179
Alt. Phone Number	-
Email Address	FTGLOBALACCS@GMAIL.COM
Address	62 CIRCUIT ROAD
Address complement	#01-301
Postcode	370062
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Clementi Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18008729999
Alt. Police Station Phone No	(Fax) +65-68728039
Police Station Address	No. Singapore 129858
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN AND POLICE REPORT NO. T/20220819/2033

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	VIDEO WAS WITH TRAFFIC POLICE

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	-
Vehicle Manufacturer	-
Vehicle Model	-

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	NA / Unknown
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

**INJURED PERSONS DETAILS**

INJURED 1

Name of injured person	HOH KWAN HUNG
Gender	-
Phone No	(Phone) +65-86544179
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	-
Were seat belts worn?	-
Was this injured conveyed to hospital by ambulance?	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

*[Handwritten signature]*


Driver's Signature (if driver is not the policyholder) / Date & Time



LIM HUNN EN G

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

REFER TO POLICE REPORT NO. T/20220819/J033

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time



LIM HUNG ENG

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)





Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

Report No. T/20220819/2033

**CONTINUATION OF REPORT**

Driver Name	HOH KWAN HUNG	ID No.	G8251149R
Related Vehicle	YQ6874U (Lorry)	Contact No.	86544177
Hospital/Clinic	PARKWAY EAST HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	19/08/2022	Date Discharge	19/08/2022
No. of Days granted Medical Leave	02	Degree of Injury	NIL

**Brief Details.**

On 18/08/2022 at about 2330hrs, I was driving my company lorry, YQ6874U (Silver Toyota Dyna) at along Beach Road as I was going back home. While I was driving somewhere nearby to the junction of Bras Basah Road and Beach Road when I suddenly blackout for a short moment. When I opened my eyes, I realized that my lorry is at the pedestrian walkway stopped by the lamp-post. I got out of my vehicle and called up my Manager to inform her on the accident. I told her that I was having massive headache and I would leave and get medical attention at the nearest hospital near to my residential address.

Subsequently Traffic Police contacted my company and told me to lodge a report on what had happened during the accident and she was given a reference incident number, A/20220819/0126 for me to lodge a Police Report.



**SINGAPORE  
POLICE FORCE**



T/20220819/2033

Police Station Of Origin:  
Clementi N.P.C  
20 Clementi Avenue 5 SINGAPORE 129858  
Tel No: 1800-8729999

3 of 3

Report No. T/20220819/2033

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report: D / SGT 3 JASMI BIN JUMA'AT 
Signature Of Interpreter: Not applicable
Officer In Charge Of Case: TP / AEIT / SI ANG YI TING, STEPHANIE Contact No.: 65476414

NP168

Signature Of Informant: 
Date/Time: 19/08/2022 12:11
Classification Of Case:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	088M
Vehicle Details	
Vehicle No.:	YQ6874U
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Aug 2022
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2022
Engine No.:	1GD8899252
Chassis No.:	JHHAGV4690K002262
Maximum Power Output:	-
Open Market Value:	\$31,609.00
Original Registration Date:	12 May 2022
First Registration Date:	12 May 2022
Transfer Count:	0
Actual ARF Paid:	\$1,581.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 May 2032
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$36,152.00
COE Rebate Amount:	\$35,154.00
<b>Total Rebate Amount:</b>	<b>\$35,154.00</b>

The information contained herein is correct as at 19 Aug 2022

OK