OS/11/1) Wef REF:	961k
	GNMENT
From: Date:	Veh No: SMH 8514K Yr Regn: 2019 1 FEB
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: TOYOTA PRIMS PLUS (1) c.c 1798
at Workshop m/s My Con Consulting	Colour WHITE A/C: Insured / Std / NI / NA
of GO, JLN LAM HUAT	Sp.Reading 277641 T/Radio: Insured / Std / NI / NA
Insured: PUS	Eng/No:
Policy No.	C/No: JTD ZS3EU90J036570
ClaimsNo.	Gen. Cond: Good / Pair/ Poor / Burnt
Sum Insured: Excess:	Steering: Voorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 205 borus
(Policy Condition)	R:1
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF FIRENZA
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 28/06/22 D.O.I. 31/08/22
Lum Sum: % 3 Val.: Yes or No	Survey held at My CAR CONSULTANT
	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT	하다 하다는 것은 사람이 하는 사람들이 되었다. 그들은 사람들이 사용하는 사람들이 되었다면 하는 것이 되었다.
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
REPAIR LIMIT-72K	
중에 맞았다. 그 그는 그 그는 그림에는 그렇게 그 그 그는 사람들이 없는 것이다. 그 없는 것이 없었다.	Days Of Repair:
Date/Time, File Pass to? : Prell. Report	Resurvey No. of Trip: Survey Fee:
Final Panort	
; Final Report	Transportation:
i) : Final Report	Transportation:
() : Final Report Date/Time, File Return to?	Transportation:
1) : Final Report Date/Time, File Return to?	Transportation:



## MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

### **Estimation**

Date:

31/8/2022

Vehicle:

SMH8514K

Make / Model:

**TOYOTA PRIUS** 

**Chassis No:** 

**ALLIANZ** 

No.	Description	Unit	Unit Price		Unit Price Amour		
	Parts Replacement:						
1	TAILGATE My remir	1	\$	1,359.00	\$	1,359.00	
2	TAILGATE LOGO 🛩 🔀	1	\$	96.00	\$	96.00	
3	TAILGATE EMBLEM PRIUS 🗸 🖊	1	\$	96.00	\$	96.00	
4	TAILGATE EMBLEM HYBRID ~~/	1	\$	96.00	\$	96.00	
5	TAILGATE WEATHERSTRIP 🗡	1	\$	258.00	\$	258.00	
6	TAILGATE LOCK 🗡	1	\$	480.00	\$	480.00	
7	TAILGATE WINDSCREEN GLASS MOULDING 🗲	1	\$	198.00	\$	198.00	
8	TAILLAMP LH 🗡	1	\$	480.00	\$	480.00	1
9	REAR BUMPER EM	1	\$	798.00	\$	798.00	1
10	REAR BUMPER SIDE RETAINER 🗡	2	\$	128.00	\$	256.00	
11	REAR BUMPER LAMP 🗡	2	\$	480.00	\$	960.00	1
12	REAR BUMPER BRACKET	2	\$	112.00	\$	224.00	
13	REAR BUMPER LOWER LIP Cut /	1	\$	698.00	\$	698.00	1
14	REAR BUMPER UNDER COVER ★	1	\$	64.00	\$	64.00	1
15	REAR END PANEL 🗡	1	\$	656.00	\$	656.00	1
16	REAR END PANEL TOP GARNISH 🗡	1	\$	288.00	\$	288.00	1
17	REAR FLOOR PANEL TOP BOARD 🗡	1	\$	312.00	\$	312.00	1
					\$	7,319.00	1
100			Less 25%		\$	1,829.75	1
		1		Total	\$	5,489.25	1
	S/Nett items:				100	1,000	1
1	REAR REVERSE SENSOR Cod	1 SET	\$	250.00	\$	250.00	200
2	REAR BUMPER CLIP ~	1 SET	\$	80.00	\$	80.00	
3	REAR END PANEL GARNISH CLIP 🗡	1 SET	\$	30.00	\$	30.00	1
4	END PANEL SEALANT X	1	\$	50.00	\$	50.00	1
5	REAR WINDSCREEN GLASS SEALANT 🗶	2	\$	60.00	\$	120.00	1
	,				\$	530.00	1

	Labour to:				
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$	89.00
2	TO REMOVE AND REFIT REVERSE SENSOR	1	\$ 150.00	\$	150.00
3	REMOVE AND REFIX REAR UPHOLSTERY	1	\$ 150.00	\$	150.00
4	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	1	\$ 150.00	S	150.00
5	REMOVE AND REFIX REAR WINDSCREEN GLASS	1	\$ 180.00	\$	180.00
6	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$	200.00
7	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,200.00	Ś	1,200.00
8	PANEL BEATING ON AFFECTED AREAS	1	1,200.00	\$	1,200.00
i d				\$	3,310.00

		placement Amount		6,019.25 3,310.00	
	Tota	al Amount	\$	9,329.25	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ram 4 2000068

4 days

4/8

31/08/22/01650

Resy after repair

SC1R226S0001-01 / City Auto Pte Ltd ENTRY DATE & TIME: 28/06/2022 15:29 (SGT) SUBMITTED BY: Jason Quak VERSION: 2 (26/08/2022 13:23 (SGT))

# **©** SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### **ACCIDENT STATEMENT**

Date of Submission28/06/2022 15:29 (SGT)Reported byDriverDate of Accident28/06/2022 09:30 (SGT)Exact Location of AccidentSingaporeAdditional Location InformationALONG AYECountry/State of LossSingapore

#### **DETAILS OF OWN VEHICLE**

Tovota

1800

Vehicle Registration Number SMH8514K

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

2XXXXX961K

Email Address

Mobile Phone No

Alternative Phone No

Yes

LUMENS AUTO PTE LTD

2XXXXX961K

KOKHOW.TAY@LUMENS.SG

(Phone) +65-87781765

**VEHICLE PARTICULARS** 

Manufacturer

Model Prius

Variant 
Exact purpose for which vehicle was being used at time of accident 
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party

Vehicle Category Private hire

Transmission Auto

**INSURANCE COMPANY** 

Name of Insurance Company
Policy Number / Cover Note Number

Tokio Marine Insurance Singapore Ltd
21MM000792-ROO

DRIVER

CC

Name of Driver NRIC No Date Of Birth Occupation

TAN KUAN JIN SXXXX661Z 02/09/1950 Outdoor

Date Of Driving Pass 04/01/2010 Driving experience 12 YEARS AND 5 MONTHS Gender Male Mobile Number (Phone) +65-82653126 Alt. Phone Number **Email Address** ANDY.QUEK@LUMENS.SG Address BLK840, CHOA CHU KANG ST 64 #15-09 Address complement Postcode 860640 Is the driver the policyholder? If No, Relationship of the Driver with the Insured No Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear **Weather Conditions** Clear **Road Surface** Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER SKETCH PLAN' ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SMJ8451Y

Accident report SC1R226S0001

Indiress
Address complement
Address complement
Postcode
Insurance Company Name
Insurance Of Damage
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Rease report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the haurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handing and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date

CITY AUTO PTE LTD Blk 8 Sin Ming Road

#01-58/60/62 Sin Ming Ind Est Singapore 575643 Tel: 6453 1235 Fax: 6453 7944 (Claims Section)

Witnessed by Reporting Centre Personnel



Describe Circumstances of the Accident WV MOUS COOUN BM NOV

#### Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Oale & Time

CITY AUTO PTE LTD #01-58/60/62 Sin Ming Road #01-58/60/62 Sin Ming Ind Est Singapore 575643 Tel: 6453 1235 Fax: 6453 7944

(Claims Section)
Witnessed by Reporting Centre Personnel

Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particulars	
wner ID Type:	Company
wner ID: /ehicle Details	961K
ehicle No.:	SMH8514K
ehicle to be Exported:	No
ntended Deregistration Date:	31 Aug 2022
ehicle Make:	TOYOTA
ehicle Model:	PRIUS PLUS (AUTO)
Primary Colour:	White
Manufacturing Year:	2018
ingine No.:	2ZR0C87965
Chassis No.:	JTDZ53EU90J036570
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$30,006.00
Original Registration Date:	12 Feb 2019
First Registration Date:	12 Feb 2019
Transfer Count:	
Actual ARF Paid: Intended PARF Rebate Details	\$24,009.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Feb 2029
PARF Rebate Amount: Intended COE Rebate Details	\$18,006.00
COE Expiry Date:	11 Feb 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Períod (Years):	10
QP Paid:	\$34,509.00
COE Rebate Amount:	\$22,256.00
Total Rebate Amount:	\$40,262.00
Total Rebate Amount: information contained herein is correct as at 31 Aug 2022	\$40,262.00

# **Toyota Prius Plus Hybrid 1.8A**

Overview Financial Accessories Similar Research Photos Map								
Price	\$111,888							
Depreciation ⑦	\$15,600 /yr View models with similar depre	Reg Date	24-Jan-2019 (6yrs 4mths 23days COE left)					
Mileage	37,000 km (10.3k /yr)	Manufactured ⑦	2018					
Road Tax (2)	\$976 /yr	Transmission	Autō					
Dereg Value ⑦	\$38,624 as of today (change)	Fuel Type	Petrol-Electric					
COE ①	\$32,200	OMV ①	\$30,006					
Engine Cap	1,798 cc	ARF ⑦	\$24,009					
Curb Weight 🕜	1,500 kg	Power	100.0 kW (134 bhp)					
Type of Vehicle	MPV	No. of Owners	2					