

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT SOMPO INSURANCE SINGAPORE PL SOMPO INSURANCE SINGAPORE PL Ref: CS3/SMO22008538/Kvg Date: 09/09/2022 SINGAPORE LAND TOWERSINGAPORE 048623	/3m4	
50 RAFFLES PLACE #03-03 Date: 09/09/2022 SINGAPORE LAND TOWERSINGAPORE 048623		
0.1. 010		
Code: SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)		
Insured Veh. FBQ 7579M Veh. Inspected GBL 6248B		
Policy No. Coverage (\$) 0.00		
Claim No. CMTD2203047/GPL Excess (\$) 0.00		
Assign From GRACE TEO Assign Date 01/09/2022		
2. Vehicle Particulars & Condition		
Make & Model NISSAN NV350 (A) c.c 1998		
Engine No. HIDDEN Year of Reg. 2021		
Chassis No. JN1MA2E26Z0000201 Colour SILVER		
Odometer 18506 KM Steering IN ORDER		
Brakes IN ORDER Modification NIL		
General GOOD		
3. Conditions of Tyres		
Size Make Balance		
R/H Front Tyre 195 R15X8 YOKOHAMA 8 mm		
L/H Front Tyre 195 R15X8 YOKOHAMA 8 mm		
R/H Rear Tyre 195 R15X8 YOKOHAMA 8 mm		
L/H Rear Tyre 195 R15X8 YOKOHAMA 8 mm		
4. Description of Damages		
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.		
5. General Information		
Accident Date 31/08/2022 Inspect Date / Time 05/09/2022 (11:48 AM)		
Survey held at SAU HOCK MOTOR SERVICES		
BLK 10 ANG MO KIO INDUSTRIAL PARK 2A (AVE 5) #02-14 AMK AUTOPOINT SINGAPORE 568047.		
5a. Remarks		
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,0	00	
5b. Estimate Days of Repair		
ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days		

Report Ref No. CS3/SMO22008538/Kvy3m4

Inspected By

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser