

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC22004435/Bcy3e2-1	
	300 BEACH ROAD #17-04/07 THE CO) NCOURSESINGAPORE 199555		Date:	15/11/2022	
				Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	XE 2621J	Veh. Inspected		SLM 6702H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	22/22/22/VC00/025777	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		01/09/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL 1.5S	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	RU11117549	Colour		BLUE	
	Odometer	105167 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/55 R17	KUMHO		5 mm	
	L/H Front Tyre	215/55 R17	KUMHO		5 mm	
	R/H Rear Tyre	215/55 R17	KUMHO		5 mm	
	L/H Rear Tyre	215/55 R17	KUMHO		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/05/2022	Inspection Dat	е	12/05/2022	
	Survey held at	SIN HENG LONG MOTOR WOR	K			
		BLK 5032 ANG MO KIO INDUSTRIAL PARK 2 #01-287/305 SINGAPORE 569535				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		10 Worl	king Days	