

Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

Your Ref : To be advised

Our Ref: CLLC.PD.062.2022

lod@centrollc.com.sg

29 APRIL 2022

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01 AXA Tower

Singapore 068811

WITHOUT PREJUDICE

Attn: Manager/Motor Claims Department

Dear Sirs,

3019995523



ACCIDENT ON 21.03.2022 ALONG HENDERSON ROAD INVOLVING MOTOR VEHICLES SLP 8598M AND SHA 1056H

We act for FORTE AUTO LEASING PTE LTD, the owner of the motor vehicle SLP 8598M involved in the captioned accident.

From our insurance search, you are the insurer of motor vehicle SHA 1056H.

We are instructed by our client to claim damages against your insured in connection with a road traffic accident on 21.03.2022 along HENDERSON ROAD involving our client's motor vehicle no SLP 8598M and motor vehicle no SHA 1056H was driven by your insured and/or your insured's servant and/or agent at the material time.

We are instructed that the accident was caused by your insured and/or your insured's servant and/or agent negligent driving and/or management of the motor vehicle. As a result of the accident, our client's motor vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-



Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939

a)	Cost of repairs	\$ 9,620.00
b)	Loss of use/ rental	\$ 2,000.00
c)	Loss of use (PRI) \$200X2 days	\$ 400.00
d)	Survey report fee	\$ 609.00
e)	Colour copies \$1.00X25	\$ 25.00
f)	LTA search fee	\$ 7.49
g)	GIA reports fee	\$ 29.00
h)	Costs contribution	\$ 1,000.00
		<u>\$13,690.49</u>

A copy each of the following supporting documents marked [X] is enclosed:-

- [x] GIA reports
- [x] Repairers bill and evidence of payment
- [] Excess bill/receipt
- [] Vehicle Registration Card
- [] COE/PARF Certificate
- [] Names and addresses of witnesses
- [] Photographs of damage to our client's motor vehicle
- [x] Photocopied photographs of damage to our client's motor vehicle
- [] Rental Agreement, Invoice and receipt for rental
- [x] Supporting documents for all other expenses claimed

Please take note that you should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against your insured without further notice to you.

Yours faithfully,



P KAMALA DEWI
CENTRO-LEGAL LAW CORPORATION
Enc.

Centro-Legal Law Corporation

ADVOCATES AND SOLICITORS

151 Chin Swee Road
#02-21 Manhattan House
Singapore 169876
Tel: 6235 0633
Fax: 6235 6939

Please note that we have notified your insurers. Please inform them of the claim. If your insurers are not the above-named and if you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which, our client will have no alternative but to commence proceedings against you without further notice to you or your insurer.

Please also note that if you have a counterclaim arising out of the accident, you are also required to send us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

INVOICE

To. M/s. Forte Auto Leasing Pte Ltd
C/o. 53, Ubi Ave 1, #05-44
Paya Ubi Industrial Park
Singapore 408934

Invoice No. : HA/2204-11

Date : 18/04/2022

Descriptions	Amount (SGD)
Services rendered for appraiser / inspection report :-	
Survey Fee	
Photographs	
Transport Fees	
Re-inspection Fees	
Total :	SGD : \$ 609.00
SGD Dollar : Six Hundred Nine Dollars Only.	
Our Reference : PAS/TP/0460322	
Vehicle No. : SLP8598M	
Make & Model : Mazda 3 1.5	
Your Claim No. : Third Party Claim	

Notes:

All cheque payment should be Crossed and made payable to "PROMINENT APPRAISER SERVICES PTE LTD".

Please indicate our "INVOICE NO." on the reverse side of the cheque.

Should you have any enquiries, please do not hesitate to contact us.



For PROMINENT APPRAISER SERVICES PTE LTD



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0460322

Date of Report : 18/04/2022

To : M/s. Forte Auto Leasing Pte Ltd
C/o. 53, Ubi Ave 1, #05-44
Paya Ubi Industrial Park
Singapore 408934

Date of Assignment : 25/03/2022
Report requested by : M/s. Forte Auto Leasing Pte I
Date of Accident : 21/03/2022
Date of Inspection : 25/03/2022
Claim No. : Third Party Claim
Policy No. : -

PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SLP8598M
Make & Model : Mazda 3 1.5
Date of Registration : 21/06/2017
Colour : Met. Blue

Engine Capacity (cc) : 1496cc
Mileage (km) : 217013km
Chassis / Frame No. : JM6BN22A8H0158967
Engine No. : P520451572

TYRE CONDITION

Front LH : 6 mm
Make : Goodrich

Front RH : 6 mm
Make : Goodrich

Rear LH : 6 mm
Make : Toyo

Rear RH : 6 mm
Make : Grenlander

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good
Paintwork : Good
Handbrake : Serviceable
Footbrake : Serviceable
Steering : Serviceable
Apparent Engine Modification : Nil

PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Neo Automotive Pte Ltd
53, Ubi Ave 1, #05-44, Paya Ubi Industrial Park, Singapore 408934

ASSESSMENT

Repairer's Estimate : \$ 14,359.12
Revised Amount : \$ 12,024.88
Less Excess : \$ -
Recommended Reserve : \$ 9,620.00 (Lump Sum)

Estimated Normal Period of Repairs : 10 Working Days

Disclaimer: The information contained in this report is intended for exclusive use of the addressees (including any attachments) solely in relation to the loss occurrence in which the assessed vehicle involved. It is confidential and may be protected by legal privilege. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party. If you are not the intended recipient, please contact us immediately to arrange for its return and you should not disseminate, distribute, copy any information contained herein or use of this communication is strictly prohibited.



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SLP8598M

Report No. : PAS/TP/0460322

GENERAL REMARKS

WITHOUT PREJUDICE

THE ASSIGNMENT

The survey was conducted at M/s. Neo Automotive Pte Ltd, 53, Ubi Ave 1, #05-44, Paya Ubi Industrial Park, Singapore 408934.

(Subsequent inspections have been conducted)

POINT OF IMPACT

At the LHR portion. (The LHR roadwheel was also affected)

DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, LHR chassis member, LHR fender, LHR fender inn wheelhouse assy, LH taillamp, LHR reflectors, LHR door, LHR alloy rim, LHR wheel hub assy, LHR knuckle arm, LHR shock absorber, LHR lower arm, LHR trailing arm, LHR control arm, LHR lateral arm, etc.

Other parts were also found damaged. (See schedule for details)

ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$12,024.88.

CONCLUSION

The repairer has agreed to undertake the repairs at a lump sum of SGD \$9,620.00.


This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,

Prominent Appraiser Services Pte Ltd


Andrew How
Automobile Appraiser
MSAAA
Licensed Appraiser



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SLP8598M

Report No. : PAS/TP/0460322

APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition		Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	1 pc	Boot lid	Dented/Repair		\$ 1,092.60	\$ -
2	1 pc	Boot lid emblem (Logo)	Necessary		\$ 74.40	\$ 74.40
3	1 pc	Boot lid emblem (Mazda 3)	Necessary		\$ 53.40	\$ 53.40
4	1 pc	Boot lid emblem (SKYACTIV)	Necessary		\$ 63.30	\$ 63.30
5	1 pc	Boot reflector lamp LH	Broken		\$ 318.60	\$ 318.60
6	1 pc	Taillamp LH	Cracked		\$ 598.30	\$ 598.30
7	1 pc	Taillamp panel LH	Dented		\$ 377.80	\$ 377.80
8	1 pc	Rr bumper	Dented		\$ 1,074.80	\$ 1,074.80
9	1 pc	Rr bumper tow cover LH	Broken/Dislodged/Missing		\$ 38.40	\$ 38.40
10	1 pc	Rr bumper reflector LH	Broken		\$ 60.80	\$ 60.80
11	6 pcs	Rr bumper fastener	Necessary	\$ 3.20	\$ 19.20	\$ 19.20
12	1 pc	Rr bumper reinforcement	Dented		\$ 537.30	\$ 537.30
13	2 pcs	Rr bumper retainer R/L	Cracked/Necessary	\$ 36.10	\$ 72.20	\$ 72.20
14	1 pc	Rr end panel	Dented/Distorted		\$ 586.20	\$ 586.20
15	1 pc	Rr end panel garnish	Dented/Defaced		\$ 94.30	\$ 94.30
16	1 pc	Rr weatherstrip	Torn/Necessary		\$ 129.40	\$ 129.40
17	1 pc	Rr spare tyre tool sponge	Broken		\$ 148.00	\$ 148.00
18	1 pc	Rr windscreen moulding	Necessary		\$ 87.60	\$ 87.60
19	1 pc	Rr fender LH	Dented/Buckled		\$ 1,274.20	\$ 1,274.20
20	1 pc	Rr fender air vent LH	Dented/Cracked		\$ 71.30	\$ 71.30
21	1 pc	Rr fender inn wheelhouse assy LH	Dented/Distorted		\$ 1,092.60	\$ 1,092.60
22	1 pc	Rr floor side extension LH	Dented/Buckled		\$ 133.80	\$ 133.80
23	1 pc	Rr fender inner trim LH	Deformed/Distorted		\$ 98.40	\$ 98.40
24	6 pcs	Rr fender inner trim clip LH	Necessary	\$ 3.20	\$ 19.20	\$ 19.20
25	1 pc	Rr fender cowl LH	Torn/Deformed		\$ 114.30	\$ 114.30
26	5 pcs	Rr fender cowl clip LH	Necessary	\$ 3.00	\$ 15.00	\$ 15.00
27	1 pc	Rr fender lower side cover LH	Cracked/Torn		\$ 82.60	\$ 82.60
28	1 pc	Rr door LH	Dented/Repair		\$ 1,062.70	\$ -
29	1 pc	Rr alloy rim LH	Dented/Defaced		\$ 1,101.70	\$ 1,101.70
30	1 pc	Rr shock absorber LH	Bent/Jammed		\$ 319.40	\$ 319.40
31	1 pc	Rr wheel hub assy LH	Warped/Damaged		\$ 426.90	\$ 426.90
32	1 pc	Rr knuckle arm LH	Bent		\$ 671.30	\$ 671.30
33	1 pc	Rr lower arm LH	Bent		\$ 271.60	\$ 271.60
34	1 pc	Rr trailing arm LH	Bent		\$ 223.40	\$ 223.40
35	1 pc	Rr control arm LH	Bent		\$ 258.20	\$ 258.20
36	1 pc	Rr lateral arm LH	Bent		\$ 135.70	\$ 135.70
37	1 pc	Boot lid	Dented/Repair			(Refer labour no. 8 & 9)
38	1 pc	Rr chassis member LH	Dented/Repair			(Refer labour no. 8 & 9)
39	1 pc	Rr door LH	Dented/Repair			(Refer labour no. 8 & 9)
					\$ 12,798.90	\$ 10,643.60
					Less Discount : 20%	\$ 2,559.78 20%
					List Parts Sub-Total :	\$ 10,239.12 \$ 8,514.88
1	1 pc	Rr windscreen sealant	Necessary	S/N	\$ 50.00	\$ 40.00
2	1 pc	Rr fender panel sealant LH	Necessary	S/N	\$ 50.00	\$ 40.00
3	1 pc	Rr end panel sealant	Necessary	S/N	\$ 50.00	\$ 40.00
4	1 set	Rr reverse sensor	Dented/Damaged	S/N	\$ 200.00	\$ 200.00
5	1 pc	Rr tyre LH (Depreciate 20%)	Cut	S/N	\$ 250.00	\$ 200.00
6	1 bot	Brake fluid	Necessary	S/N	\$ 20.00	\$ 20.00
					Parts Total :	\$ 10,859.12 \$ 9,054.88



PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Mail Address: My Mail Box 886259 Singapore 919191.

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SLP8598M

Report No. : PAS/TP/0460322

S/No.	Labour Descriptions	Repairer's Estimate (\$\$)	Our Assessment (\$\$)
1	To remove and reinstall electrical wiring system for necessary repairs. To check rear electrical wiring system.	\$ 70.00	\$ 50.00
2	To remove and reinstall rear windscreen for necessary repairs.	\$ 120.00	\$ 120.00
3	To remove and reinstall rear interior trims, garnishes, seats, etc. for necessary repairs.	\$ 120.00	\$ 100.00
4	To remove and reinstall fuel tank, pipings, etc. for necessary repairs.	\$ 100.00	\$ 80.00
5	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 50.00	\$ 50.00
6	To remove, check and replace LHR undercarriage parts. (Include flush and bleed brakes system)	\$ 250.00	\$ 220.00
7	To conduct wheel alignment.	\$ 60.00	\$ 60.00
8	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,500.00	\$ 1,210.00
9	To spray painting, blending on affected and adjacent area.	\$ 1,200.00	\$ 1,050.00
10	To spray anti-rust coating on new and affected panels.	\$ 30.00	\$ 30.00
Labour Total :		<u>\$ 3,500.00</u>	<u>\$ 2,970.00</u>
Total (Parts & Labour) :		<u>\$ 14,359.12</u>	<u>\$ 12,024.88</u>



For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 9,620.00

Under normal circumstances, the repairs should be completed within a reasonable period of **10 Working Days**. (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)


99 Photographs were taken at the time of inspection.

N.B: By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.
























P13




P14





P15



P16








P₁₅



P₁₅







P₁₅








P₁₅



























PS



PS



PS



PS





SP0U22300007 / PROGRESSIVE CAR CARE PTE LTD
ENTRY DATE & TIME: 24/03/2022 16:07 (SGT)
SUBMITTED BY: Lim Xu Wen Wayne
VERSION: 1 (24/03/2022 16:07 (SGT))

Your NCD will be affected due to late reporting

SINGAPORE ACCIDENT STATEMENT

Pr Inspection
Neo Automotive Pte Ltd

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	24/03/2022 16:07 (SGT)
Date of Accident	21/03/2022 19:30 (SGT)
Exact Location of Accident	Henderson Rd, Singapore
Additional Location Information	NEAR SAFRA
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLP8598M

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	FORTE AUTO LEASING PTE LTD
Company Reg No	201631486C
Email Address	ALEX@BLAZEMOTORING.COM.SG
Mobile Phone No	(Phone) +65-88607088
Alternative Phone No	+65-88607088

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	3
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private hire
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	No
Policy Number	VFX/P2343358
Cover Note Number	-

DRIVER

Name of Driver	WANG HONGWEI
NRIC No	S8467478H

Date Of Birth	19/09/1984
Occupation	Outdoor
Date Of Driving Pass	09/02/2009
Driving experience	13 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-88607088
Alt. Phone Number	-
Email Address	ALEX@BLAZEMOTORING.COM.SG
Address	BLK 192C RIVERVALE DRIVE #13-950
Address complement	-
Postcode	543192
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	WANG MIN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN AND STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHA1056H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi

Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	WANG HONGWEI
Gender	Male
Phone No	(Phone) +65-88607088
Address	BLK 192C RIVERVALE DRIVE #13-950
Address Complement	-
Post Code	543192
Approximate Age Years Old	37
Injuries Sustained	2 DAY MC
Injured person in which vehicle?	SLP8598M
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN #2

Describe Circumstances of the Accident

I was turning and there was a handicapped person crossing the road. I stopped my vehicle and a taxi hit my car on the side.

Declaration

We declare the foregoing particulars are true in every respect.

If you wish to claim against your own policy, please be advised that your insurer may have a fourteen (14) days clause whereby the claim must be made within the stipulated timeframe from the day of occurrence. Kindly check with your insurer for more details.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SKETCH PLAN

SKETCH PLAN

IMPORTANT NOTICE

2. The Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to rescind policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false statements may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the G.A. Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of the report will be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made as above stated.
8. Consent under the Personal Data Protection Act (PDPA)
- Understand, know, judge, agree and consent that:
- (a) My name, my car and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and process my personal data and information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insureds (b) I have insured vehicle(s) involved in this accident (all insureds (b) I have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insured"), the insurer, law yer/s, firm, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations, relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the sums as well as on the external cover of envelopes/mail packages); and/or
- (v) carrying out applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) I have insured vehicle(s) involved in this accident and the insurer, law yer/s, firm, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyer/s, firm), which may be used outside of the above Purposes.

Sketch Plan

1574


Policyholder's Signature / Date: _____

8719

Driver's Signature (If driver is not the policyholder) / Date

பாண்டி

Witnessed by: Reporting Centre



Enquire Vehicle's Insurance Particulars

Enquire Vehicle's Insurance Particulars (As At 21 Mar 2022 / 19:30:00)

Vehicle Insurance Details

Vehicle No.:

SHA1056H

Make Description/Model:

HYUNDAI / AE IONIQ HEV FL 1.6 DCT

Insurance Company Name:

AXA INSURANCE PTE LTD

Business Transaction Reference No.:

20220325172459764901

Please retain the business transaction reference number for Enquire Vehicle Owner Details (if required).

Save as PDF

OK →

Print



Thank you

Kasturi D/o Devasahayam has successfully logged out.
Your last login date and time was 25 Mar 2022, 17:24:12.

To return to ONE.MOTORING, please click [here](#)

For security reasons, please **CLEAR YOUR CACHE** after each session.

Session Transaction History

S/No.	Asset Type	Asset ID	Asset Owner ID	Transaction Type	Transaction Amount(\$)
1	Vehicle	SHA1056H	-	18.19 Enquire Veh Owner Info (Others) by Law Firm	7.49