

ASS. REC. BY:

REF:

ASM / 2200-85431kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: FBR 5946U

Policy No.

Claims No. S2M049ZH

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 8120k

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SNE 7880 M Yr Regn: 04, 22

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Cerato c.c. 1591

Colour

M. Blue A/C: Insured / Std / NI / NA

Sp. Reading

2222 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KNAF1416M N 5139966

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal.

L/Bal.

D.O.A.

8 mm

8 mm

29/8/22

Rear

R/Bal.

L/Bal.

D.O.I.

8 mm

8 mm

1/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27/10/22 Kenneth informed final fig \$2280.48 (Red 3042.40, 57%)

Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Time, File Return to?

27/10/22-typist

ort Format: TP

p Sum / I.B.I: (\$ 2280.48

Days Of Repair: 4

Resurvey No. of Trlp: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Printers

Others

TOTAL



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

Kenneth.

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE  
#15-08 WESTGATE TOWER  
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

## ESTIMATE

NO : QUOT202208-000064(00)

DATE : 31/08/2022

POLICY NO : 999995580

VEH REG NO : SNE7880M

MAKE/MODEL : KIA CERATO 1.6(A) LX

CHASSIS NO : KNAF1416MN5139966

ENGINE NO : G4FGNH700526

REG. DATE : 2021

YOUR REF NO : FBR5946U

CLAIM TYPE : THIRD PARTY

TP INS. CO. : AXA INSURANCE SINGAPORE PTE LTD

ACCIDENT DATE : 29/08/2022

TP VEH REG NO : FBR5946U

*Not available  
Money B4 pain  
4 days*

## Estimate Repair Cost to Vehicle No : SNE7880M

| Description                                                                                                                                                                               | Quantity | Unit Price | Amount       |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|------------|--------------|
|                                                                                                                                                                                           |          | S\$        | S\$          |
| <b>LIST PRICE</b>                                                                                                                                                                         |          |            |              |
| 1 Rear fender - LH                                                                                                                                                                        | 1        | 1,349.63   | 1,349.63 X   |
| 2 Rear door - LH                                                                                                                                                                          | 1        | 1,278.31   | 1,278.31 ✓   |
| 3 Rear door outer handle - LH                                                                                                                                                             | 1        | 51.88      | 51.88 X      |
| 4 Rear sport rim - LH                                                                                                                                                                     | 1        | 345.60     | 345.60 X     |
|                                                                                                                                                                                           |          |            | 3,025.42     |
|                                                                                                                                                                                           |          | Less 10%   | 302.54       |
|                                                                                                                                                                                           |          |            | 2,722.88     |
| <b>SPECIAL NET</b>                                                                                                                                                                        |          |            |              |
| 5 Rear windscreen sealant                                                                                                                                                                 | 1        | 60.00      | 60.00 X      |
|                                                                                                                                                                                           |          |            | 60.00        |
| <b>LABOUR</b>                                                                                                                                                                             |          |            |              |
| 6 To remove and refit rear windscreen glass                                                                                                                                               | 1        | 150.00     | 150.00 X     |
| 7 To transfer LH rear damaged door interior mechanism and glass to new new door                                                                                                           | 1        | 150.00     | 150.00 60d   |
| 8 To panel beat & straighten LH door pillar, LH rear chassis frame, to cut and weld rear LH fender including replacement of parts and align where necessary, to refit and adjust the same | 1        | 1,000.00   | 1,000.00 30d |
| 9 To putty and spray paint on affected areas                                                                                                                                              | 1        | 1,000.00   | 1,000.00 48d |
| 10 To apply rust-proofing on replaced and repaired panels                                                                                                                                 | 1        | 120.00     | 120.00 3d    |
| 11 To computerise check wheel alignment                                                                                                                                                   | 1        | 120.00     | 120.00 X     |
|                                                                                                                                                                                           |          |            | 2,540.00     |

TOTAL S\$ 5,322.88

ADD GST @ 7% 372.60

GRAND TOTAL S\$ 5,695.48

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- To provide information
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

SINGAPORE DOLLAR FIVE THOUSAND SIX HUNDRED NINETY FIVE AND CENTS FORTY-EIGHT ONLY

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Actual Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                                 |                        |
|---------------------------------|------------------------|
| Date of Submission              | 30/08/2022 19:56 (SGT) |
| Reported by                     | Driver                 |
| Date of Accident                | 29/08/2022 11:20 (SGT) |
| Exact Location of Accident      | Singapore              |
| Additional Location Information | WOODLANDS STREET 41    |
| Country/State of Loss           | Singapore              |

### DETAILS OF OWN VEHICLE

Vehicle Registration Number SNE7880M

#### INSURED/POLICYHOLDER

|                          |                                              |
|--------------------------|----------------------------------------------|
| Is company?              | Yes                                          |
| Name Of Registered Owner | DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. |
| Company Reg No           | 1XXXXX778Z                                   |
| Email Address            | mohamed_faizal.mohd_yasin@mercedes-benz.com  |
| Mobile Phone No          | (Phone) +65-68498118                         |
| Alternative Phone No     | -                                            |

#### VEHICLE PARTICULARS

|                                                                              |             |
|------------------------------------------------------------------------------|-------------|
| Manufacturer                                                                 | Kia         |
| Model                                                                        | Cerato      |
| Variant                                                                      | 1.6(A) LX   |
| Exact purpose for which vehicle was being used at time of accident           | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | Yes         |
| Vehicle Category                                                             | Private car |
| Transmission                                                                 | Auto        |
| CC                                                                           | 1591        |

#### INSURANCE COMPANY

|                                   |                                      |
|-----------------------------------|--------------------------------------|
| Name of Insurance Company         | AIG Asia Pacific Insurance Pte. Ltd. |
| Policy Number / Cover Note Number | 999995580                            |

#### DRIVER

|                |            |
|----------------|------------|
| Name of Driver | A MANIRAJA |
| NRIC No        | SXXXX123Z  |
| Date Of Birth  | 06/11/1966 |
| Occupation     | Outdoor    |

REFER TO ATTACHED ACCIDENT DIAGRAM

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS DRIVING ALONG WOODLANDS STREET 41 AND SIGNALLED TO TURN LEFT TO ENTER INTO MY CARPARK. WHILE MAKING THE TURN, VEHICLE B TRIED TO SQUEEZE IN BETWEEN MY VEHICLE AND THE CURB; COLLIDING INTO THE LEFT PORTION OF MY VEHICLE. MY REAR LEFT PORTION WAS DENTED AND SCRATCHED. I WAS NOT INJURED BUT RIDER OF VEHICLE B SUFFERED SOME ABRASIONS.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

VERIFY BY AJAX MARS (ARC)  
REPORTING OFFICER  
MOHAMED SHARIL BIN SATAR

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.: