...CLAIM SUBFOLDER...(Pending for Survey Report)

THE REPAIRER HAS NOT SUBMITTED THEIR ESTIMATES

If you wish to work on the report, contact the repairer below to submit it.
You can authorize repairer submission after 5 days.

0 days have passed since assignment.
You can authorize the submission of the repairer's estimates in 119 HOURS.

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	31 Aug 2022 09:11		01 Sep 2022 16:03				**Pending for Survey Report** Cancel Case

Main | Reference | Claim Details | Documents | Show All

CLAIM SUBFOLDER DETAILS

Insured:	**COMFORTDELGRO RENT-A-CAR PTE LTD** , Co. Reg. No. : 198105775H		
Vehicle Reg. No.:	**SDK8800A**	Date of Loss :	13/08/2022 00:00 - :59 [**67** Months and **14** Days From LTA Reg Date (Man Yr)]
Claim Type:	**OD**	Policy/Cover Note No. :	D20MFL0000326_02 (Comprehensive)
		Excess:	
Repairer:	**ComfortDelGro Engineering Pte Ltd (Braddell)** 205 Braddell Road, 579701 Toa Payoh - Tel: 63837613		
Handling Insurer:	**India International Insurance Pte Ltd (HQ)** - Tel: 63476100 ... [Handled by **Gabriel Wee** - 63476100 ext 248]		
Adjuster:	**LKK Auto Consultants Pte Ltd (HQ)** - Tel: 6256-3561 ... [Handled by **KENNETH KONG**] ... [**Final Rpt** due 12/09/2022]		

ASSOCIATED MAIL RECEIVED View All | Compose Case Mail

There are no mail for this case.

ALL ASSOCIATED TASKS View All | Search Tasks | Create New Task | Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?

No results.

ALL ASSOCIATED FILE NOTES Create New

No.	Status Type	Viewer/ Assigned To	Note	Created On	Created By	1st Read By

No results.