

REF:

ASSIGNMENT

Veh No: SLE 7803K Yr Regn: 2016 / August

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Elantra. C.C. 1591

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading 1591670 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHD 841 CMHU 203062

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: inorder / Jammed / Leaked / Burnt or

Modif: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15.

R: 185/65 R15

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 29/08/22

*Survey held at MG solution

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

422B.

Preli. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Formed :

Arch Fee: : Site Insp (\$

: Interview (3)

Tech. Invs. (3)

1. Findings

M. Cifers