

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305527261
 REGN NO : SHC7652L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 14.11.2019
 DATE/TIME IN : 22.08.2022 09:55
 ACCIDENT DATE : 17.08.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2538-G MIRROR ASSY-O/S RR VIEW R 1 1,391.70 20.00 1,113.36

SUB-TOTAL : 1,113.36

JOB NATURE

0000 PB PANEL BEATING

120.00

0001 SP SPRAYPAINT CHARGE

120.00

SUB-TOTAL : 240.00

TOTAL : 1,353.36

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

1313.36

1 Day
 8/8
 (no Quf)
 22/8/22
 3pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: