

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHD7238U
 Make : HYUNDAI
 Model : IONIQ(G3)

Date: 17.08.2022
 Insurance: CHINA TAIPING
 MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER / <i>CCB</i>			\$459.40
10	REAR BUMPER CLIPS / <i>MC</i>			\$22.00
1	REAR BUMPER CENTRE MOULDING ASSY / <i>RTS</i>			\$451.25
1	REAR BUMPER REINFORCEMENT			\$394.80
2	REAR BUMPER REINFORCEMENT BRACKET LH RH ?		\$138.10	\$276.20
1	REAR BUMPER FOG LAMP X <i>YAN</i>			\$201.50
1	REAR BUMPER LICENCE LAMP X			\$85.30
1	ANTENNA ASSY SMARTKEY ?			\$40.50
2	REAR BUMPER SIDE BRACKET LH RH X <i>YAN</i>		\$55.80	\$111.60
1	REAR BUMPER LOWER CTR MOULDING X			\$155.00
1	BOOTLID / <i>Buc</i>			\$2,549.70
1	BOOTLID HYUNDAI PLATE			\$24.30
1	EMBLEM HYBRID / <i>Y MBL</i>			\$24.30
1	EMBLEM - IONIQ			\$31.30
1	REAR BUMPER TOWING COVER X <i>NN</i>			\$98.80
1	REAR PANEL X <i>Repair</i>			\$532.00
1	REAR PANEL GARNISH X <i>NN</i>			\$346.80
1	BOOT LID LAMP LH ?			\$822.00
1	REAR BUMPER CENTRE UNDER COVER / <i>DL</i>			\$225.00
SUB TOTAL				\$6,851.75
LESS 20%				\$1,370.35
DISCOUNTED TOTAL				\$5,481.40
REAR BUMPER RUBBER MAT / <i>MBL</i>				\$50.00
REAR NUMBER PLATE WITH TRIM COVER / <i>CCB</i>				\$55.00
BOOTLID COMFORT TEL NO STICKER / <i>Y MBL</i>				\$40.00
BOOTLID COMFORT LOGO STICKER / <i>Y MBL</i>				\$30.00
BOOTLID COMFORT APP STICKER				\$30.00
REAR BUMPER REVERSE SENSOR / <i>Dm</i>				\$180.00
NETT				\$385.00
Labour Charge				
PANEL BEATING				\$1,100.00
SPRAY PAINTING CHARGE				\$800.00
CHK ALL LIGHTING				\$60.00
TUFF KOTE				\$60.00
REMOVE/REFIX REVERSE SENSOR				\$80.00
TOTAL LABOUR				\$2,100.00
ESTIMATE TOTAL				\$7,966.40

*4 Days. Same Day
 45 30/8/22*

*700
 500
 200
 X NN
 40*

LKK Auto Consultants hence notify the Repairer of the following:
 • To repair the vehicle as per the estimate
 • To display damage (part/s) during resurvey
 • To provide status report to confirmation
 • Third party survey on "Without Prejudice" basis

ESTIMATE TOTAL

Acknowledged by the Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.