

ASS/REC BY:

Steve

CS/HLA 2200.8576/Eqy3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLA/1887K Yr Regn: 25/4/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Megane c.c. 1461

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 1472/3 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VFIRFB0035752.765.1

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or: Continental

Front Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 22/8/22 D.O.I. 12/9/22

Survey held at: Warran

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MVR-628

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I. (\$ _____)

SERVICE ESTIMATE

89449 - C00001 SL: SERVICE SALES - PC
 Mr Sim Shao Kwan Malcolm
 50 Bukit Batok Street 31
 #20-04
 Singapore 659442

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 1
 Inv.date. : 25/08/2022
 WIP No. . : 38610
 Veh.In/Out:
 *Tel.No. . : Mobile: 90475475
 Reg.No. . : SLN1887K
 Reg.date . : 25/04/2017
 Mileage . : 0
 Chassis No: VF1RFB00357527657

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Mr Sim Shao Kwan Mal

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE LHF DOOR, LHR DOOR, LHR FENDER, REAR BUMPER, LHS WING MIRROR COVER, "B" PILLAR DOOR TRIMS, BRACKETS, CLIPS, ETC.	0 550 x 6.5	4400.00	0		4,400.00 S	3575
800	TO BLEND AND SPRAY PAINT ON LHF DOOR, LHR DOOR, LHR FENDER, LHR FENDER INNER PANEL, LHS ROOF TOP SIDE PANEL, REAR BUMPER, LHS WING MIRROR COVER, ETC.	0 650 x 0.5	3250.00	0		3,250.00 S	/
802	TO TRANSFER LHF DOOR AND LHR DOOR MECHANISM	0	500.00	0		500.00 S	250
802	TO REPLACE LHR DOOR GLASS	0	550.00	0		550.00 S	/
0080	TO INSTALL LHR DOOR GLASS	0	280.00	0		280.00 S	/
SOLAR FILM							
802	TO REPLACE REAR WINDSCREEN	0	550.00	0		550.00 S	/
0080	TO INSTALL REAR WINDSCREEN	0	280.00	0		280.00 S	/
SOLAR FILM							

Steve (LKK)
 12/9/22, 4.30pm

P/P
 by BL y
 13 days
 OD - 11/11
 EXPIR. ?

SERVICE ESTIMATE

89449 - C00001 SL: SERVICE SALES - PC
 Mr Sim Shao Kwan Malcolm
 50 Bukit Batok Street 31
 #20-04

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2
 Inv.date. : 25/08/2022
 WIP No. : 38610
 Veh.In/Out:

Singapore 659442

*Tel.No. : Mobile: 90475475
 Reg.No. : SLN1887K
 Reg.date : 25/04/2017
 Mileage : 0
 Chassis No: VF1RFB00357527657

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Mr Sim Shao Kwan Mal

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REMOVE AND INSTALL INTERIOR PARTS	0	1650.00	0		1,650.00 S	1100 (photo disassemble)
802	TO REMOVE AND INSTALL REAR BOO COMPARTMENT PARTS	0	1100.00	0		1,100.00 S	550 (photo disassemble)
0031	TO REPLACE LHR RIM	0	50.00	0		50.00 S	
0033	WHEEL ALIGNMENT	0	280.00	0		280.00 S	
	DOOR FRT LH M4S x R	1.0 EA	2027.40			2,027.40 S	
	DOOR REAR LH M4S	1.0 EA	2027.40			2,027.40 S	
	WINDOW MOULDING FRT	1.0 EA	344.50			344.50 S	
	WINDOW MOULDING REAR	1.0 EA	346.60			346.60 S	
	WINDOW SEAL FRT LH O	1.0 EA	249.60			249.60 S	
	WINDOW SEAL RR LH OU	1.0 EA	272.20			272.20 S	
	MLDG-RR PLR,FR LH DO	1.0 EA	110.50			110.50 S	
	MLDG-RR LH DOOR FR P	1.0 EA	469.90			469.90 S	
	"C" PILLAR DOOR TOP	1.0 EA	56.10			56.10 S	
	WHEEL ARCH REAR LH M	1.0 EA	277.60			277.60 S	
	MUDGUARD-RR LH	1.0 EA	84.00			84.00 S	

SERVICE ESTIMATE

89449 - C00001 SL: SERVICE SALES - PC
 Mr Sim Shao Kwan Malcolm
 50 Bukit Batok Street 31
 #20-04

Singapore 659442

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Mr Sim Shao Kwan Mal

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 3
 Inv.date. : 25/08/2022
 WIP No. . : 38610
 Veh.In/Out:
 *Tel.No. . : Mobile: 90475475
 Reg.No. . : SLN1887K
 Reg.date . : 25/04/2017
 Mileage ... : 0
 Chassis No: VF1RFB00357527657

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	TAILAMP INNER SUPPOR ?	1.0 EA	532.80			532.80	S
	FENDER REAR LH M4S - DO	1.0 EA	2130.90			2,130.90	S
	NOISE DEADENING PAD - REC	2 4.0 EA	606.90			2,427.60	S
	WING MIRROR ASSY LH ?	1.0 EA	810.40			810.40	S
	WING MIRROR COVER LO X	1.0 EA	158.00			158.00	S
	WING MIRROR COVER TO X	1.0 EA	165.60			165.60	S
	BUMPER REAR M4S - BR ?	1.0 EA	952.70			952.70	S
	BUMPER REAR INNER SI ?	1.0 EA	231.30			231.30	S
	BUMPER REAR SIDE SUP ?	1.0 EA	350.80			350.80	S
	BUMPER REAR OUTER SI ?	1.0 EA	241.90			241.90	S
	TOW COVER RR M4S X	1.0 EA	94.00			94.00	S
	BUMPER PAD LOWER M4S X	1.0 EA	429.30			429.30	S
	ALLOY RIM 7 XJ 1 M4S - CUT	1.0 EA	628.50			628.50	S
	TYRE PRESSURE SENSOR - REC	1.0 EA	121.90			121.90	S
	WDW-MOBILE, RR LH DO - CUT	1.0 EA	490.50			490.50	S
	PRIMER - REC	1.0 EA	204.70			204.70	S
	WINDSCREEN SEALANT - REC	2.0 EA	134.00			268.00	S

SERVICE ESTIMATE

89449 - C00001 SL: SERVICE SALES - PC
 Mr Sim Shao Kwan Malcolm
 50 Bukit Batok Street 31
 #20-04

Singapore 659442

Closed by : Michelle Ong Siew Be
 Svc Consultant :
 Remarks : Mr Sim Shao Kwan Mal

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 4
 Inv.date. : 25/08/2022
 WIP No. . : 38610
 Veh.In/Out:
 *Tel.No. . : Mobile: 90475475
 Reg.No. . : SLN1887K
 Reg.date .: 25/04/2017
 Mileage .. : 0
 Chassis No: VF1RFB00357527657

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	WINDSCREEN REAR M4S ✓ <i>PRC</i>	1.0 EA	781.80			781.80	S

			Gross Total.	30,176.50
Labour Total	12,890.00		Net.....	30,176.50
Parts Total	17,286.50		GST @ 7.0%	2,112.36
Package Total	0.00		Total.....	32,288.85
			Paid.....	0.00
			Please Pay..	32,288.85

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	23/08/2022 10:01 (SGT)
Reported by	Both
Date of Accident	22/08/2022 07:49 (SGT)
Exact Location of Accident	Near 215 Pandan Loop, Singapore 128406
Additional Location Information	PANDAN LOOP CROSS JUNCTION
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN1887K
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SIM SHAO KWAN, MALCOLM
NRIC No	S1738026E
Email Address	MALCOLMSKSIM@GMAIL.COM
Mobile Phone No	(Phone) +65-90475475
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Renault
Model	Regane
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1598

INSURANCE COMPANY

Name of Insurance Company	HL Assurance Pte Ltd
Policy Number / Cover Note Number	MP 307194

DRIVER

Name of Driver	LIM SOO KEE
NRIC No	S6925539F
Date Of Birth	16/08/1969
Occupation	Indoor

Date Of Driving Pass
Driving experience
Gender

Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode

Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

25/02/1994
28 YEARS AND 6 MONTHS
Female
(Phone) +65-97963345
-
CURLYLASH@GMAIL.COM
BLK 91 WEST COAST VALE
#36-06
126755
No
Spouse
No

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Side Swipe
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other vehicle or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
Translator's name -
Translator's ID -
Translator's phone number -
Translator's email -
Original language used in the statement -

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

REFER TO SUMMARY AND SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YQ118J
Vehicle Manufacturer -
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Commercial vehicle
Name of Driver -
Contact Number -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]
Policyholder's Signature / Date & Time

[Signature]
Driver's Signature (if Driver is not the policyholder) / Date & Time

SUZANA BTE EPROG
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

At 7.45 am, I was on my way home driving along West Coast Highway in the direction towards West Coast Road. I was driving on the right most lane as I was going to turn into West Coast Vale where I stay. (Date: 22 Aug 2022)

Swayed into my lane and


I was driving straight on my lane, suddenly a truck hit me on the left side of my car. This happened just before the junction of West Coast Highway and Ardour Loop. At that time it was still green light, both our cars passed the traffic junction and stopped right after. (The other vehicle no. is YK118J)

At 12 noon, I was at Wah Hong Reporting Centre making the report, the other vehicle's driver's employer whatsapp me admitting to his driver's fault.


To clarify, the truck was travelling on the middle lane to my left before his vehicle hit my car. At that time I was still driving straight within my (right most) lane.

Declaration

We declare the foregoing particulars are true in every respect



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



SHANA BIE EDROS

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)