

Our Job Ref No 305527922 ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 01/09/22 Date ¥2. **FINALIZATION FORM** LKK Fax: Guo Qiang Attn : Mr Vehicle Reg No. : SHD7308B 27.08.2022 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-NTUC FBA8284R 1. The repair job shall bill to: 2. The finalized amount shall be: Spare Parts after List discount (a) Labour Charges (b) Total for Part-By-Part Repair Cost \$0.00 (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% \$1,400.00 Final Lumpsum Repair cost \$1,400.00 2 working days. 3. Estimated normal period for repairs: We shall treat the above amount as Correct and Confirmed if there is no reply from you within 4. 7 working days We confirm the estimates and 5. Thank you for your assistance. finalized amount Signature: Signature : : Ms. Loke YY Name Name : 62148355 Tel Date : 65468156 Fax For Official Use Only Document Confirm By Remarks Item Amount Attached (Signature) Yes or No YES 1. Rental Rate P/Day 2. Loss of Income Paid NO 3. Survey Fees \$7.49 / \$2.00 4. LTA Search Fee Medical Fees (on behalf

of driver, if applicable)

6 Overrun Remarks: