

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315



**AUTOMOBILE INSPECTION REPORT** 



AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD Ref: NS/INC22008586/Gcq2						
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	19-12-2022		
			Code:	INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SND 8467Y	Veh. In	spected	SHA 1033Z	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1186319-002	Excess	s (\$)	0.00	
	Assign From		Assign	Date	30/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI 140	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMGU093601	Colour	•	BLUE	
	Odometer	835538	Steerin	ng	IN ORDER	
	Brakes	IN ORDER	Modifie	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST L	AKE	6 mm	
	L/H Front Tyre	195/65 R15	WEST L	AKE	6 mm	
	R/H Rear Tyre	195/65 R15	WEST L	AKE	6 mm	
	L/H Rear Tyre	195/65 R15	WEST L	AKE	6 mm	
4.	1. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	5. General Information					
	Accident Date	28/08/2022	Inspec	tion Date	30/08/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORI	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				