

## **SMRT Accident Vehicle Repair Estimates**

Section A - Accident Details				
Registration Number	SG5427H			
Case Reference Number	BUS/08/22/7015			
Registration Date	7/2/2017			
Company Type	SMRT Buses Ltd			
Make	VOLVO B9TL DD			
Model	VOLVO			
Name of Driver	Zhou Xiaoyong			
Type of Accident	Side Swipe			
Accident Date and Time	24/8/2022 7:40 AM			
Accident Reported Date and Time	26/8/2022 10:58 AM			
Is Surveyor Required?	Yes			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number				
Special Instruction to ARC,if any	SG5427H - LEFT REAR PORTION SKA9864D (TP) - INSURED WITH ALLIANZ			
Prepared Date and Time	1/9/2022 1:54 PM			
Chassis Number	YV3S4P924HA180889			
Mileage				
Work Shop				
Repair Completion Date and Time				

	Section B - Summary of Rep	air Estimates			
Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable			
Total Labour Cost	\$1,325.00	\$0.00			
Total Spray Cost	\$772.00	\$0.00			
Total Spare Part Cost	\$0.00	\$0.00			
Total Other Cost	\$0.00	\$0.00			
TOTAL COST	\$2,097.00	\$0.00			
Lump Sum Total	\$0.00	\$0.00			
Number of Repair Days	4.0				
Prepared / Adjusted By	Kok Khoon Goh				
ARC / Surveyor Sign Off Date	01/09/2022 1:56 PM				
Signature	<i>b</i>	×			
Remarks					

Section C - Quotation and Accident Invoice Details					
Quotation Number		Invoice Number			
Quotation Date		Invoice Date			
Invoice Amount		Prepared Date			

## SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 01/09/2022
User ID : GohKK2



## **SMRT Accident Vehicle Repair Estimates**

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 01/09/2022
User ID : GohKK2

			Sect	tion D - Detail	ls of Repair E	stimates			
Part 1 - Labou	ır Works								
Job Scope			Quotation fro	Quotation from AR				Adjusted by Surveyor, if applicable	
TO REPAIR LH PORTION			\$1,325.00	\$1,325.00					
Total Labour			\$1,325.00	\$1,325.00					
Part 2 - Spray	Painting & Pa	anel Beating Rela	ted Works						
Job Scope		Quotation fro	Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$772.00	\$772.00					
Total Spray Painting & Panel Beating			\$772.00	\$772.00					
Part 3 - Other	Costs - Accid	ent and Accident	Repair Related Exper	ıse					
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Co	sts								
Part 4 - Spare	Parts / Materi	al Usage		•					
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
Total									
Added Spare	Parts / Materia	al Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									