

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22008620/Gqcm4		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date: Code:	06-01-2023 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SKW 8477D	Veh. Ir	spected	SHA 1225L	
	Policy No.		Covera	age (\$)	0.00	
	Claim No.	MT/1186165-003	Exces	,	0.00	
	Assign From		Assign	n Date	30/08/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HYUNDAI I40	c.c		1685	
	Engine No.	HIDDEN	Year o	f Reg.	2016	
	Chassis No.	KMHLB41UMHU097380	Coloui	r	BLUE	
	Odometer	766272	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65R15	WEST		6 mm	
	L/H Front Tyre	195/65R15	WEST		6 mm	
	R/H Rear Tyre	195/65R15	WEST		6 mm	
	L/H Rear Tyre	195/65R15	WEST	_AKE	6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	27/08/2022	Inspec	tion Date	30/08/2022	
	Survey held at COMFORTDELGRO ENGINEERING PTE LTD					
		59 LOYANG DRIVE SINGAPORE 508969				
5a.	a. Remarks					
	A)THE INSPECTION B)IN ACCORDANCE	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					