

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

MUC (P/P)

Date: 29.08.2022

Time: 16:30:59

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305528171
 REGN NO : SHC2017D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 16.01.2020
 DATE/TIME IN : 29.08.2022 14:35
 ACCIDENT DATE : 27.08.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2835-G LAMP ASSY-HEAD LH#	1	2,110.30	20.00	1,688.24	✓ Ser
0002 04-01-0104-2687-G MOULDING-FRONT BUMPER CTR	1	368.50	20.00	294.80	X Repi
				SUB-TOTAL :	1,983.04

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	150
0002 17-01	CHECK ALL LIGHTING	50.00	30
		SUB-TOTAL :	750.00

TOTAL : 2,733.04

MVA NAME & SIGNATURE
 DATE :

AUTHORISED : YES / NO
 SURVEYOR NAME & SIGNATURE
 DATE :

2218.24

2D cars
 P/P
 Gmo Q: 4
 30/8/22
 11 AM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: