

Our Job Ref No : 305528300

Date : 05/09/22				05/09/22			ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156			
FINA	LIZAT	TION F	ORM							
То	:	:LKK					Fax:			
Attn	Attn : Mr Guo Qiang									
Vehi	cle Re	g No.	: SHA	4624Z				30.08.2022		
The	survey	and e	estimates o	f the repairs of	the above-me	ntioned vehic	le are as follow	vs:-		
1.	The repair job shall bill to:			NTUC			SMT8462M			
2.	The	finaliz	ed amount	shall be:						
	(a)	Spa	re Parts af	ter List discoun	t					
	(b)	Lab	our Charge	es						
		Tota	al for Part-	By-Part Repai	r Cost			\$0.00		
3.4.	Final Lumpsum Repair cost \$4,650.00 Estimated normal period for repairs: 4 working days. We shall treat the above amount as Correct and Confirmed if there is no reply from you within									
	7 wo	rking	days							
5.	Thank you for your assistance.				A		e confirm the e alized amount			
	Signature :					Signature :				
	Name Ms. Loke YY				Na					
	Tel	Tel : 62148355				Date :				
	Fax : 65468156									
For C	fficial	Use (Only							
		Item		Amo	ount	Document Attached	Confirm By (Signature)	Remarks		

ltem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks	8:			