

Our Job Ref No : 305528391  
Date : 07.09.2022

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

**FINALIZATION FORM**

To : LKK Fax : \_\_\_\_\_  
Attn : GUO QIANG  
Vehicle Reg No. : SHA5953S 30.08.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC SLE4767B

2. The finalized amount shall be:

(a) Spare Parts after List discount \_\_\_\_\_

(b) Labour Charges \_\_\_\_\_

**Total for Part-By-Part Repair Cost** \_\_\_\_\_

(c.) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: \_\_\_\_\_  
**Final Lumpsum Repair cost** \$2,700.00

3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.  We confirm the estimates and finalized amount

Signature : \_\_\_\_\_  
Name : CHIANG  
Tel : 62148314  
Fax : 65468156

Signature : \_\_\_\_\_  
Name : \_\_\_\_\_  
Date : \_\_\_\_\_

**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_