

**COMFORTDELGRO
ENGINEERING**

Our Job Ref No : 305528392
Date 02.09.22

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK Fax : _____
Attn : Mr GUO QIANG
Vehicle Reg No. SHA7364D Date of Accident : 30.08.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SMW8205Z
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$841.12
 - (b) Labour Charges \$640.00
 - Total for Part-By-Part Repair Cost** \$1,481.12
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost _____
3. Estimated normal period for repairs: 5 working days.
4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : JUMANI
Tel : 62148315
Fax : 65468156

Signature : 
Name : GUO QIANG
Date : _____

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	----	NO		
3. Survey Fees	----	---		
LTA Search Fee	\$7.49 / \$2.00	YES		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305528392
REGN NO : SHA7364D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 28.01.2021
DATE/TIME IN : 30.08.2022 20:40
ACCIDENT DATE : 30.08.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00
0004	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0005	28-01-0104-2029-A	VEHICLE NUMBER PLATE REAR	1 N	50.00	10.00	45.00

SUB-TOTAL : 841.12

JOB NATURE

0000 L	PANEL BEAT (SHA7364D) TP	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 L	REFIX REVERSE SENSOR	40.00

SUB-TOTAL : 640.00

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305528392
REGN NO : SHA7364D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 28.01.2021
DATE/TIME IN : 30.08.2022 20:4
ACCIDENT DATE : 30.08.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 1,481.12

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :