



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



### AUTOMOBILE INSPECTION REPORT

INCOME INSURANCE LTD

Ref: NS/INC22008626/Gcm4

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

Date: 19-12-2022

Code: INC4

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMW 8205Z	Veh. Inspected	SHA 7364D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1186763-003	Excess (\$)	0.00
Assign From		Assign Date	31/08/2022

#### 2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AE IONIQ HEV 1.6	c.c	1580
Engine No.	HIDDEN	Year of Reg.	2021
Chassis No.	KMHC851CVLU192459	Colour	BLUE
Odometer	224321	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

#### 5. General Information

Accident Date	30/08/2022	Inspection Date	31/08/2022
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------