

ASS. REC BY: Toupin

REF: CTI

ASSIGNMENT

From: _____ Date: _____
 Estimate Cost: _____
OD / TP / IS / TP RES / OD RES / EVA / INV / MV
 To Inspect/ehicle No: _____
 at Works p m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: Lim TS
 Vehicle: IN / OUT

| | |
|-----|-----|
| | |
| N/S | O/S |
| | |

Veh No: SHC 1389L Yr Regn: 2018, Oct
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Hyundai C.C. 1580
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 44929 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMH0851 CVK41/4860
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or west/6ho
 Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 23/8/22
 Survey held at Comfort Garage
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|----------------------|
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) _____
 Date/Time, File Return to?
 2) _____
 Report Format: _____
 Lump Sum / I.B.R. (P) _____

Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. rvs (\$ _____)
 : Weekend (\$ _____)

Survey Fee: _____
 Transportation: _____
 S + RS. \$ _____
 Photos _____
 Others _____
 TOTAL _____

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 23.08.22

INSURANCE: CHINA TAIPING (CLS)

MODEL: Hyundai Ioniq

MVA: LIM T S

VEHICLE NO.: SHC1389L

| PART NO. | DESCRIPTION | QTY | UNIT PRICE | AMOUNT |
|----------|-----------------------------|-----|------------|-------------|
| | Frnt Fender RH | 1 | | \$ 588.80 |
| | Frnt Fender Blue-Drive RH | 1 | | \$ 26.60 |
| | DayLight RH | 1 | | \$ 642.50 |
| | DayLight Grille RH | 1 | | \$ 93.45 |
| | Frnt Bumper | 1 | | \$ 481.10 |
| | Frnt Bumper Upper Moulding | 1 | | \$ 368.50 |
| | Frnt Bumper Side Bracket RH | 1 | | \$ 35.00 |
| | Frnt Bumper Clips | 10 | \$ 2.20 | \$ 22.00 |
| | SUB TOTAL | | | \$ 2,257.95 |
| | LESS 20% | | | \$ 451.59 |
| | DISCOUNTED TOTAL | | | \$ 1,806.36 |
| | Frnt Fender Adv.Sticker RH | 1 | | \$ 100.00 |
| | Labour Charge | | | |
| | Panel Beating | | | \$ 800.00 |
| | Spray Painting Charge | | | \$ 600.00 |
| | Check Lightings | | | \$ 60.00 |
| | Tuff Kote | | | \$ 60.00 |
| | TOTAL LABOUR | | | \$ 1,520.00 |
| | ESTIMATE TOTAL | | | \$ 3,426.36 |

Ry
-
X
X
-
X
?
-

cut -
NETT
350
600
X
X

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Taiping 97495749
 in 23/8/22 C430 p
 CLS survey after repair
 Taipin Chhantorn
 Zebys

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4640269

JC No: 305527419

CUSTOMER
 MS COMFORT TRANSPORTATION PTE LTD
 CUSTOMER NO. 7010045
 ADDRESS 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 (R) 65508755 (O)
 (P)

| | |
|--|---|
| REGN NO: SHC1389L | MILEAGE |
| MAKE: HYUNDAI | FUEL E.....1/2.....F |
| MODEL IONIQ(G2) | DATE/TIME IN 23.08.2022 09:40 |
| YR OF MANU. 24.10.2018 | TARGET DATE |
| CHASSIS CODE KMHC851CVKU114860 | COMPLETION DATE/TIME: |

COUNT CARD NO.

Accident Date: 23.08.2022
 Nature: 3P 23.08.2022


LKK-

JOB DESCRIPTION

LS SNC
China 1429 J

NO LABOR CODE
 0010 PB

DESCRIPTION
 PANEL BEATING-SHC1389L-TP



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: **SHC1389L** LIMTS

Vehicle No.: **SHC1389L**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard