

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO **SHB66465**

24.08.2022

MAKE **REG.30.10.2018**

CHIANG/CHINA

MODEL **IONIQ G3**

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
2	REAR BUMPER SIDE BRACKET LH/RH		\$55.80 \$111.60
1	REAR BUMPER CENTRE MOULDING		\$451.25
2	REAR BUMPER REINFORCEMENT STAY LH/RH		\$138.10 \$276.20
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR FOG LAMP		\$201.50
2	REAR BUMPER REFLECTOR LH/RH		\$41.45 \$82.90
1	TOWING COVER		\$98.80
2	REAR NUMBER PLATE LAMP LH/RH		\$85.30 \$170.60
10	REAR BUMPER CLIPS		\$2.20 \$22.00
	SUB TOTAL		\$2,269.05
	20.00% DISCOUNTED TOTAL		\$453.81
			\$1,815.24
2	REAR FENDER ADVERTISEMENT LH/RH		\$100.00 \$200.00
1	REAR NUMBER PLATE W/HOLDER		\$55.00
1	REAR REVERSE SENSOR		\$180.00
			\$435.00
	Labour Charge		
	Panel Beating		350 \$550.00
	Spray Painting Charge		250 \$300.00
	Tuff Kote		X \$60.00
	Remove/refix Reverse sensor		30 \$60.00
	TOTAL LABOUR		\$970.00
	ESTIMATE TOTAL		\$3,220.24
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Taafm 97495749
 w/p 24/8/22 @ 4pm
 2 days
 c/s Resing after repair
 fanyfline@lkhauto.com

Job: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4651858

JC No: 305527526

Customer:
 COMFORT TRANSPORTATION PTE LTD
 7010045
 383 SIN MING DRIVE
 Singapore SINGAPORE 575717
 65508755
 (R) (P) (O)
 COUNT CARD NO. *[Handwritten]*


REGN NO: SHB6646S	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G2)	DATE/TIME IN 24.08.2022 09:00
YR OF MANU. 30.10.2018	TARGET DATE
CHASSIS CODE KMHC851CVKU115015	COMPLETION DATE/TIME:

Accident Date: 24.08.2022
 Nature: 3P 24.08.2022

JOB DESCRIPTION

/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Workshop Acknowledgement Slip

Exit Pass

Vehicle No.: **SHB6646S** **CHIANG**

Vehicle No.: **SHB6646S**

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle to be returned to Service Reception upon collection

To be kept by Security Guard