

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315





AUTOMOBILE INSPECTION REPORT						
INCOME INSURANCE LTD			Ref:	NS/INC22008641/Rqce2		
75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	21-10-2022		
_				INC4		
1.						
	Insured Veh.	SKV 2839M		nspected	SMB 36H	
	Policy No.		Covera	3 (.,)	0.00	
	Claim No.	MT/1185598-002	Exces		0.00	
	Assign From		Assign		02/09/2022	
2.						
	Make & Model	MERCEDES BENZ OC500LE	c.c		11967	
	Engine No.	HIDDEN	Year o		2008	
	Chassis No.	WEB63442021000097	Coloui	r	GREEN	
	Odometer	888753	Steeri	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	275/70 R22.5		NENTAL	8 mm	
	L/H Front Tyre	275/70 R22.5	CONTI	NENTAL	8 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	CONTI	NENTAL	8/8 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	CONTI	NENTAL	8/8 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	23/08/2022	Inspec	tion Date	02/09/2022	
	Survey held at	rvey held at STRIDES AUTOMOTIVE SERVICES PL.				
		60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days					