



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22008647/Kny3e2	
			Date: 11/01/2023	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	FBS 6232J	Veh. Inspected	SMB 1421Y
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203085/THE	Excess (\$)	0.00
	Assign From	MELVIN YE	Assign Date	05/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	MAN NL320F (A)	c.c	10518
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	WMAA22ZZ2E7002135	Colour	MULTI COLOUR
	Odometer	734574 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	GOODYEAR	8 mm
	L/H Front Tyre	275/70 R22.5	GOODYEAR	8 mm
	R/H Rear Tyre	275/70 R22.5 (D)	GOODYEAR	7/7 mm
	L/H Rear Tyre	275/70 R22.5 (D)	GOODYEAR	7/7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	31/08/2022	Inspection Date	05/09/2022
	Survey held at	310 MANDAI RD S 779404		
	Repairer	TOWER TRANSIT SINGAPORE PTE. LTD.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	