

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERAL	L INSURANCE (S) PL		Ref:	CS/AGI22008649/Uvy3e2
	(BUDGET DIRECT 190 CLEMENCEAU SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE		Date:	20/09/2022
				Code:	AGI
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJR 1698S	Veh. Inspected		SKW 5788B
	Policy No.	P10571469R00	Coverage (\$)		0.00
	Claim No.	C10016448/CD	Excess (\$)		0.00
	Assign From	SALIZAWATI HAIZAR	Assign Date		05/09/2022
2. Vehicle Particulars & Condition					
	Make & Model	HONDA VEZEL (A)	c.c		1496
	Engine No.	HIDDEN	Year of Reg.		2015
	Chassis No.	RU11103198	Colour		SILVER
	Odometer	146302 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	215/60 R16	DUNLOP		6 mm
	L/H Front Tyre	215/60 R16	DUNLOP		6 mm
	R/H Rear Tyre	215/60 R16	DUNLOP		6 mm
	L/H Rear Tyre	215/60 R16	DUNLOP		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	14/11/2021	Inspection Date	е	07/09/2022
	Survey held at	FASTECH AUTO PTE LTD			
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: