

ASS. REC. BY:

REF:

AGZ/ 22008654/KP

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

06/23

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKL 2882P

Yr Regn:

06, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Emme

c.c.

2362

Colour

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

142493

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ACR 50

0163420

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

2/9/22

D.O.A.

12/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report

Days Of Repair:

Resurvey No. of Trlp:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **Auto & General Insurance (Singapore) Pte Ltd**
190, Clemenceau Avenue, #03-01,
Singapore Shopping Centre,
Singapore 239924

Attn : Motor Claims Department
Tel : 6221 2111
Fax : 6725 0611

Estimate bill : TT 29 / 22 / TP / WT

Registration No : SKL2882P

Make / model : Toyota Estima

*Not to have
11 Pmg &
Penny Afa Pamy
5 days*

Date : 07 / 09 / 2022

Mileage :

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SMK4646Z AND SKL2882P ALONG
KPE ON 02 SEPTEMBER 2022 AT ABOUT 0830HRS.**

1pc	Rear boot		\$	1,619.00	✓
1pc	Rear boot lock		\$	330.00	✓
1pc	Rear boot rubber		\$	180.00	✓
1pc	Rear end panel		\$	630.00	✓
1pc	Rear end panel top garnish		\$	345.00	✓
1pc	Rear spare tyre wheel house		\$	1,049.00	✓
1pc	Rear bumper		\$	690.00	✓
2 4pcs	Rear bumper parktronic sensor	(Each \$280.00)	\$	1,120.00	✓
4pcs	Rear bumper parktronic sensor 'O' ring	(Each \$27.00)	\$	108.00	✓
4pcs	Rear bumper parktronic sensor holder	(Each \$34.00)	\$	136.00	✓
2pcs	Rear bumper towing cover	(Each \$45.00)	\$	90.00	X
2pcs	Rear bumper reflector	(Each \$66.00)	\$	132.00	X
1pc	Rear bumper sponge		\$	105.00	✓
	Sub A total :		\$	6,534.00	
	Less 25% discount :		\$	1,633.50	
	A total :		\$	4,900.50	
Special net items :					
1pc	Rear boot emblem		\$	56.00	✓
1pc	Rear boot 'Estima' designation		\$	56.00	✓
1pc	Rear boot 'Aeras' designation		\$	67.00	✓
1pc	Rear license smart plate & casing		\$	35.00	X
	B total :		\$	214.00	
	Remove and refit rear windscreen		\$	200.00	
	Total amount of Page 1 :		\$	5,314.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

(Authorised Signature)

William Tan



Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **Auto & General Insurance (Singapore) Pte Ltd**
190, Clemenceau Avenue, #03-01,
Singapore Shopping Centre,
Singapore 239924

Estimate bill : TT 29 / 22 / TP / WT

Registration No : SKL2882P

Make / model : Toyota Estima

Attn : Motor Claims Department
Tel : 6221 2111
Fax : 6725 0611

Mileage :

Date : 07 / 09 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SMK4646Z AND SKL2882P ALONG
KPE ON 02 SEPTEMBER 2022 AT ABOUT 0830HRS.**

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot, rear boot lock, rear end panel top garnish, rear bumper, rear bumper parktronic sensors, rear bumper parktronic sensor 'O' rings, rear bumper parktronic sensor holders, rear bumper towing covers, rear bumper reflectors, rear bumper sponge.

Heat / weld / cut / renew rear end panel, heay / weld cut / renew rear spare tyre wheel house, held weld / beating / pull / straighten / align rear chassis frame by Chassis Aligment jack.

Diagnostic and reset rear bumper parktronic sensor fault error by HHT

Under coating on rear damaged portion.

Putty / primer application, spray painting on rear boot, rear end panel, rear spare tyre wheel house, rear bumper, rear bumper parktronic sensors, rear bumper towing covers (Pearl White).

Balance amount brought from Page 1 :

Grand final amount :

\$ 1,200.00 *6001*

\$ 100.00 *501*

\$ 150.00 *601*

\$ 1,800.00 *8601*

\$ 5,314.50

\$ 8,564.50

Tropical Tech Automobile Services


(Authorised Signature)
William Tan



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/09/2022 14:53 (SGT)
Reported by	Both
Date of Accident	02/09/2022 08:30 (SGT)
Exact Location of Accident	KPE, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKL2882P
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	KOH SIONG HUAT
NRIC No	SXXXX091C
Email Address	SIONGHUAT@GMAIL.COM
Mobile Phone No	(Phone) +65-90012370
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Estima
Variant	ESTIMA AERAS 2.4 A
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2362


INSURANCE COMPANY

Name of Insurance Company	Auto & General Insurance (Singapore) Pte. Limited.
Policy Number / Cover Note Number	P10296715R02

DRIVER

Name of Driver	KOH SIONG HUAT
NRIC No	SXXXX091C
Date Of Birth	03/02/1979
Occupation	Indoor

Date of accident: 02/09/22 Time: 0830 Location: Kallang Payar Lebar Expressway
My Vehicle A: SKL 2882P Vehicle B: SMK 4646Z Vehicle C: SLH 1287Z
SKETCH PLAN D: JRM 6564



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Please Refer Attached Police Report

☐ Claim OD/TP at Ah Lim Motor ☒ Claim OD/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop: Tropical Success Auto Care

Email address: tsac303@singnet.com.sg

& myself: Siong hui@gmail.com

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AH LIM MOTOR COMPANY