

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	UNITED OVERSE	AS INSURANCE LTD		Ref:	CS/UOI22008677/Kvy3m4	
	146 ROBINSON R #02-01 UOI BUILD	OAD INGSINGAPORE 068909		Date:	16/09/2022	
				Code:	UOI2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFZ 2000D	Veh. Inspected	b	SLK 3900H	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	M11D16092209	Excess (\$)		0.00	
	Assign From	KATIE LEE	Assign Date		05/09/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MAZDA 2 (A)	c.c		1496	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	MM6DL2SAAGW191121	Colour		METALLIC PEARL WHITE	
	Odometer	122480 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/60 R16	YOKOHAMA		9 mm	
	L/H Front Tyre	195/60 R16	YOKOHAMA		9 mm	
	R/H Rear Tyre	195/60 R16	YOKOHAMA		9 mm	
	L/H Rear Tyre	195/60 R16	YOKOHAMA		9 mm	
4.	4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	03/09/2022	Inspection Da	te	06/09/2022	
	Survey held at	ALAN'S UNITED AUTO PTE LTI	D			
		BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					
	<u> </u>					