ASS. REC. BY: Kenneth

REF: ASM / 22008678 / Kp

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Thiam Heng Hwa

of 6807

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of Inspection.

N/S	O/S

Bal. or Market Value: $ 80k

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2-3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGK 9828D Yr Regn: 10/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or _____

Make: Hyundai Avante c.c 1591

Colour M. Gray A/C: Insured / Std / NI / NA

Sp.Reading 181287 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHD841CMLU010006

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi : Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 205/55R16

R: ——

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Turador

Front		Rear	
R/Bal.	5 mm	R/Bal.	3 mm
L/Bal.	5 mm	L/Bal.	3 mm
D.O.A.	31/8/22	D.O.I.	6/9/2022

Survey held at ✓ 10.15am

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	Make part by part, est not ready

...o, File Pass to? ☐ : Prell. Report

☐ : Final Report

...o, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp ($ _____)

☐ : Interview ($ _____)

☐ Tech Invs ($ _____)

☐ Weekend ($ _____)

Survey Fee:

Transportation: ___$ + RS. ___SI

Photos

Others

TOTAL

...ormat :

...m / I.B.I: ($ _____)