

ASSIGNMENT

Front: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S
N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL2 173E Yr Regn: 95/3/72
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Audi A5 Sportback c.c. 1984
Colour: White A/C: Insured / Std / NI / NA
Sp. Reading: 9606 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WAU7222F58NA010536
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: NII / S/Rim / STD A/Rim or
Tyre Size: F: 275/30ZR20
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front _____ Rear _____
R/Bal. 4 mm R/Bal. 4 mm
L/Bal. 4 mm L/Bal. 4 mm
D.O.A. 2/9/22 D.O.I. 5/9/22
Survey held at Premium
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>NIR- 230K</u>

Date/Time, File Pass to? ☐ : Prell. Report
☐ : Final Report
1) _____
Date/Time, File Return to? _____
2) _____
Report Format: _____
Lump Sum / L.B.A. (\$) _____

Days Of Repair: _____
Resurvey No. of Trip: _____
Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)
Survey Fee: _____
Transportation: _____
S + RS. \$ _____
Photos _____
Others _____
TOTAL _____

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0765/2022/EQ
DATE : 2-Sep-22
WIP : 40176

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 05/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR TOH TECK KIONG
ADDRESS : BLK 10 CHAI CHEE ROAD
#02-09
SINGAPORE 467010
TELEPHONE : HP +65 91771643
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7220030428
VEHICLE NO : **SLZ 173 E**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFS
MODEL YEAR : 25/3/2022
ENGINE NO : DEM 035964
CHASSIS NO : WAUZZZF58NA010536
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 1-Sep-22
PLACE OF ACCIDENT : PIE (CHANGI) ENTERING KPE (TPE),
IN THE START OF THE TUNNEL

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 173 E

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00 ✓	
2	TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	800.00 250	
3	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,600.00 ✓	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00 ✓	
5	TO REMOVE AND REINSTALL BOTH DOOR PANEL TRIM. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSY TO FACILITATE RESPRAY OF BOTH FRONT DOOR.	S/N \$	560.00 280	
TOTAL LABOUR CHARGES		(LH ch) ✓ :	\$ <u><u>4,640.00</u></u>	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 173 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO REPAIR BOTH FRONT DOORS AND BOTH UPPER A-PILLAR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 7,200.00 S x 500	1500
7	TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH FRONT DOORS AND BOTH UPPER A-PILLAR.	\$ 7,500.00 S x 550	2750
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	/
TOTAL LABOUR CHARGES		: \$ 19,724.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER / DEF	1	\$	2,493.00	
2	FRONT BUMPER SECURING STRIP / PC	2	\$	79.00	
3	FRONT BUMPER GRILLE - CENTER ?	1	\$	219.00	
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE ?	1	\$	293.00	
5	FRONT BUMPER SPOILER ?	1	\$	599.00	
6	RADIATOR AIR GUIDE - LH / RH ?	2	\$	144.00	
7	FRONT BUMPER CLOSING ELEMENT / BR	1	\$	293.00	
8	RADIATOR AIR GUIDE GRILLE - LH / RH X	2	\$	302.00	
9	RADIATOR AIR GUIDE GRILLE OUTER TRIM - LH / RH X	2	\$	108.00	
10	RADIATOR GRILLE TRIM - CENTER X	1	\$	127.00	
11	RADIATOR GRILLE / BR	1	\$	1,881.00	
12	RADIATOR GRILLE COVER CAP / MIS	1	\$	141.00	
13	RADIATOR GRILLE BRACKET / BR	1	\$	19.00	
14	FRONT CAMERA ?	1	\$	1,264.00	
15	FRONT BUMPER FOAM FILLER PIECE / BR	1	\$	163.00	
16	FRONT BUMPER CARRIER ?	1	\$	899.00	
17	FRONT BUMPER BRACKET - LH / RH / BR	2	\$	508.00	
18	FRONT BUMPER GUIDE SECTION - LH / RH ?	2	\$	82.00	
19	FRONT BUMPER TOP COVER / CRV	1	\$	143.00	
20	CAUTION SIGN STICKER / re	1	\$	16.00	
SUB TOTAL SPARE PARTS		:	\$	9,773.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	AIR CONDITIONER STICKER <i>nc</i>	1	\$ 9.00	
22	LOCK CARRIER <i>GR (BKK4)</i>	1	\$ 154.00	
23	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
24	FRONT PARKING AID SENSOR - INNER / OUTER <i>?</i>	4	\$ 1,062.00	
25	FRONT PARKING AID SEAL RING <i>nc</i>	4	\$ 10.00	
26	FRONT BUMPER WIRING SET <i>?</i>	1	\$ 449.00	
27	HORN HIGH TONE - LH <i>X</i>	1	\$ 134.00	
28	HORN LOW TONE - RH <i>?</i>	1	\$ 139.00	
29	HORN BRACKET - LH / RH <i>X</i>	2	\$ 66.00	
30	FRONT FENDER - LH / RH <i>?</i>	2	\$ 2,378.00	
31	FRONT FENDER ATTACHMENT PARTS <i>X</i>	1	\$ 55.00	
32	FRONT FENDER CLOSING ELEMENT - LH / RH <i>X</i>	2	\$ 166.00	
33	FRONT FENDER BRACKET - LH / RH <i>X</i>	2	\$ 82.00	
34	FRONT FENDER RIVET <i>X</i>	11	\$ 42.00	
35	FRONT FENDER BRACE - LH / RH <i>X</i>	2	\$ 264.00	
36	FRONT WHEEL HOUSING LINER - LH / RH <i>X</i>	2	\$ 598.00	
37	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i>	1	\$ 176.00	
38	FRONT WHEEL SPOILER - LH / RH <i>X</i>	2	\$ 164.00	
39	BONNET <i>DD</i>	1	\$ 3,491.00	
40	BONNET ATTACHMENT PARTS <i>X</i> <i>122</i>	1	\$ 128.00	
SUB TOTAL SPARE PARTS		:	\$ 9,631.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	BONNET HINGE - LH / RH ?	2	\$	932.00
42	BONNET IMPACT PROTECTION - CENTER / LH / RH ✓ N2	3	\$	93.00
43	BONNET SOUND ABSORBER ✓ CKY	1	\$	382.00
44	BONNET BOWDEN CABLE - CENTER ?	1	\$	64.00
45	BONNET RELEASE LEVER ?	1	\$	15.00
46	BONNET BOWDEN CABLE - CENTER ? ✓ BT	1	\$	64.00
47	BONNET BOWDEN CABLE COVER ?	1	\$	11.00
48	BONNET STRIKER - LH / RH ? ✓ BT	2	\$	112.00
49	BONNET LOCK ✓ BT	2	\$	455.00
50	FRONT FENDER TOP LEDGE COVER - LH / RH ?	2	\$	80.00
51	FRONT FENDER INNER LEDGE COVER - LH / RH ?	2	\$	98.00
52	HEADLIGHT - LH / RH ✓ BR	1 ✓	\$	16,344.00
53	HEADLIGHT HOSE ?	1	\$	42.00
54	HEADLIGHT COMPENSATING PIECE ? ✓ N2	2	\$	90.00
55	HEADLIGHT COMPENSATING PIECE	1	\$	47.00
56	LIFT CYLINDER BRACKET - RH ?	1	\$	17.00
57	LIFT CYLINDER - LH / RH ?	2	\$	434.00
58	LIFT CYLINDER CORRUGATED PIPE ?	1	\$	107.00
59	LOCK CARRIER ✓ BR	1	\$	1,478.00
60	COOLANT REGULATOR SUPPORT - LH / RH ?	2	\$	85.00
SUB TOTAL SPARE PARTS		:	\$	20,950.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	AIR COOLER CHARGE X	1	\$	654.00
62	A/C CONDENSER / BT	1	\$	683.00
63	A/C CONDENSER REFRIGERANT LINE ?	1	\$	186.00
64	A/C CONDENSER REFRIGERANT LINE ?	1	\$	381.00
65	A/C CONDENSER REFRIGERANT LINE ?	1	\$	277.00
66	OUTSIDE TEMPERATURE SENSOR BRACKET ?	1	\$	21.00
67	RADIATOR COOLANT / MC (photo)	1	\$	699.00
68	RADIATOR COOLANT FAN RING / BR	1	\$	277.00
69	RADIATOR FAN CONTROL UNIT ?	1	\$	2,012.00
70	RADIATOR AIR GUIDE - LH / RH CRH /	1/2	\$	72.00
71	RADIATOR AIR GUIDE - LH / RH CRH /	1/2	\$	38.00
72	RADIATOR AIR GUIDE - UPPER / CRH	1	\$	19.00
73	RADIATOR AIR GUIDE - LOWER X	1	\$	25.00
74	READY- MIX COOLANT / MC	6	\$	297.00
75	INTAKE AIR DUCT - RH / BR	1	\$	25.00
76	INTAKE AIR DUCT AIR GUIDE / BR	1	\$	61.00
77	INTAKE AIR DUCT HOSE / BR	1	\$	110.00
78	AIR FILTER ?	1	\$	418.00
79	FRONT FENDER TRIM - LH / RH / MC	1/2	\$	342.00
80	FRONT DOOR TRIM - LH / RH / MC	1/2	\$	342.00
SUB TOTAL SPARE PARTS		:	\$	6,939.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 173 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	FRONT WINDOW SLOT SEAL TRIM STRIP - LH / RH X	2	\$	892.00
82	FRONT ROOF MOLDING - LH / RH / in 1.2	1.2	\$	1,412.00
83	FRONT WATER DEFLECTOR STRIP - LH / RH X	2	\$	150.00
84	FRONT FENDER PROTECTION FILM - LH / RH ?	2	\$	40.00
85	FRONT NO PLATE / 07	S/N	\$	150.00
86	SUNDRIES 2		\$	500.00
TOTAL SPARE PARTS		:	\$	50,437.00
TOTAL LABOUR CHARGES		:	\$	19,724.00
GRAND TOTAL		:	\$	70,161.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

ster CLK
5/9/12, 4⁰⁰p

OD-M AL
EXcess - ?
P/P
Lj BL y
11 y s

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	02/09/2022 14:13 (SGT)
Reported by	Both
Date of Accident	01/09/2022 17:40 (SGT)
Exact Location of Accident	PIE, Singapore
Additional Location Information	PIE (CHANGI) ENTERING KPE (TPE), IN THE START OF THE TUNNEL
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLZ173E

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TOH TECK KIONG
NRIC No	SXXXX905G
Email Address	BRENDONTOH@GMAIL.COM
Mobile Phone No	(Phone) +65-92722685
Alternative Phone No	+65-91771643

VEHICLE PARTICULARS

Manufacturer	Audi
Model	A5
Variant	SPORTBACK 2.0 TFS
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1984

INSURANCE COMPANY

Name of Insurance Company	AIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	7220030428

DRIVER

Name of Driver	TOH TECK KIONG
NRIC No	SXXXX905G
Date Of Birth	25/04/1982

Occupation Indoor
 Date Of Driving Pass 04/03/2010
 Driving experience 12 YEARS AND 6 MONTHS
 Gender Male
 Mobile Number (Phone) +65-92722685
 Alt. Phone Number +65-91771643
 Email Address BRENDONTOH@GMAIL.COM
 Address BLK 10 CHAI CHEE ROAD
 Address complement #02-09
 Postcode 467010
 Is the driver the policyholder? Yes
 If No, Relationship of the Driver with the Insured -
 Does Driver Own Other Vehicles? No
 Vehicle Registration Number of Other Vehicle Owned by Driver -
 Insurance Company of Other Vehicle Owned by Driver -

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
 Weather Conditions Clear
 Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
 Number of vehicles involved in the accident 2
 Was anybody injured in the Accident? No
 Was any injured conveyed to hospital by ambulance? -
 Was any other vehicle or property damaged? Yes
 Number of Passengers (Including Driver) 1
 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No
 Translator's name -
 Translator's ID -
 Translator's phone number -
 Translator's email -
 Original language used in the statement -

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
 Was notice of intended Prosecution given? No
 If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

ON 1 SEPT 2022 AT ABOUT 5.40PM, WHILE I WAS DRIVING ALONG PIE (CHANGI) ENTERING TUNNEL OF KPE (TPE), WHILE AT THE START OF THE TUNNEL, THERE WAS A MASSIVE JAM AS SUCH, VEHICLES WERE GOING SLOW. WHILE I WAS DRIVING AND STOPPING DUE TO THE TRAFFIC CONDITION, THE LORRY IN FRONT BEARING GBD840Y SUDDENLY JAM BRAKE. I DIDN'T REACT IN TIME AND COLLIDED TO THE REAR OF THE LORRY. MY VEHICLE SLZ173E SUFFERED DAMAGES AT THE FRONT PORTION OF MY VEHICLE. THE SAID LORRY GBD840Y DID NOT HAVE ANY VISIBLE DAMAGE (AS SHOWN IN THE PHOTOS). PLEASE NOTE THE LORRY REAR DOOR ALREADY GOT A HOLE DAMAGE BEFORE THE COLLISION. NOT CAUSED BY ME. I HAVE VIDEO EVIDENCE AS PROOF AND THE DRIVER ALSO ACKNOWLEDGED. I WAS NO INJURED. THE DRIVER AND HIS PARTNER ALSO NOT INJURED. LTA ENFORCEMENT OFFICER CAME AND VERIFIED AS SUCH.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
 Was there any video captured by Car Camera? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD840Y

Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Gray
Name of Driver	Goods vehicle
Contact Number	MURUGESAN BOOPATHI BALA SUNDAR
Address	(Phone) +65-87767678
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Kian 2/4/22
12:17pm
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: SLZ173E

B: 98D 8404



Describe Circumstances of the Accident

On 1 Sept 2022 at or about 5.40 pm, while I was driving along PTE (Changi) entering tunnel of KPE (TPE), while at the start of the tunnel, there was a massive jam. As such, vehicles were going slow. While I was driving and stopping due to the traffic condition, the lorry in front bearing GBD 8404 suddenly jam brake. I didn't react in time and collided to the rear of the lorry.

My vehicle SLZ 173E suffered damages at the front portion of my vehicle. The said Lorry GBD 8404 did not have any visible damage (as shown in the photos). Please note the lorry rear door already got a hole damage before the collision, not caused by me. I have video evidence as proof and the driver also acknowledged.


I was not injured. The driver and his partner also not injured. LTA Enforcement officer came and waited as such.

Declaration

We declare the foregoing particulars are true in every respect

 26 Sept 2022
1222h11
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel