

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	AXA INSURANCE	PTE LTD	Ref:	CS/ASM22008752/Ucy3m4	
	8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811		Date:	14/09/2022	
	ATTN: KHOR SAW	/ THENG	Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHA 4204C	Veh. Inspected	SMN 1113Z	
	Policy No.	VFX/P2419138	Coverage (\$)	0.00	
	Claim No.	S2M04A7Z	Excess (\$)	0.00	
	Assign From	KHOR SAW THENG	Assign Date	06/09/2022	
2.	Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ CLA180 AMG LINE (A)	c.c	1595	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	WDD1173422N655952	Colour	GREY	
	Odometer	93177 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/40 R18	CONTINENTAL	6 mm	
	L/H Front Tyre	225/40 R18	CONTINENTAL	6 mm	
	R/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm	
	L/H Rear Tyre	225/40 R18	CONTINENTAL	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	01/09/2022	Inspection Date	06/09/2022	
	Survey held at	AUTOBAY PTE LTD			
		NO. 1 KAKI BUKIT AVE 6 #02-11 SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				
	<u> </u>				