

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT				
	INCOME INSURAN	ICE LTD	Ref:	CS/INC22008754/Ucy3m4
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date	15/09/2022
	ATTN: JEFF LIN S	LIE	Code	e: INC
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	SMS 4538K	Veh. Inspected	SKZ 1283B
	Policy No.		Coverage (\$)	0.00
	Claim No.	MT/1187257-002	Excess (\$)	0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	06/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA MOBILIO SV (A)	c.c	1497
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	MRHDD4870FP000432	Colour	SILVER
	Odometer	114762 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/65 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	185/65 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	185/65 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	185/65 R15	BRIDGESTONE	6 mm
4.	Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.			
	DAMAGES SEE DETAILS.			
		- · · · · - ·		3.0
5.	General Information			
	Accident Date	03/09/2022	Inspect Date / Time	06/09/2022 (11:03 AM)
	Survey held at	J-MART MOTOR PTE LTD		
		BLK 5 DEFU LANE 10 #01-578 DEFU INDUSTRIAL PARK C SINGAPORE 539186		
5a.	Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			