

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		DAMAGE ASSES	SMENT REPORT		
	INCOME INSURAN	NCE LTD	Ref:	CS/INC22008757/Ecy3e2	
	73 BRAS BASAH F #05-01 NTUC TRA 189556	ROAD DE UNION HOUSESINGAPORE	Date:	23/09/2022	
	ATTN: QUEK SWE	E KENG	Code	: INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMQ 5108Y	Veh. Inspected	SHC 272X	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1187352-001	Excess (\$)	0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	06/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AE IONIQ	c.c	1580	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	KMHC851CVLU178668	Colour	YELLOW	
	Odometer	289950 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	185/55 R15	DUNLOP	5 mm	
	L/H Front Tyre	185/55 R15	DUNLOP	5 mm	
	R/H Rear Tyre	185/55 R15	DUNLOP	5 mm	
	L/H Rear Tyre	185/55 R15	DUNLOP	5 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
	DAMAGES SEE DI	ETAILS.			
-					
5.	General Information				
	Accident Date	05/09/2022	Inspect Date / Time	06/09/2022 ( 01:57 PM )	
	Survey held at	•			
<b>-</b>	Repairer DING AUTOMOTIVE PTE LTD				
5a.	Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
	B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
	Estimate Days of Repair				
5b.		Estimate	Days of Repair		