

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN	ICE LTD	Ref:	CS/INC22008758/Ecy3m4	
	75 BRAS BASAH FINCOME CENTRE	ROAD SINGAPORE 189557	Date:	27/04/2023	
	ATTN: CYNTHIA A	NG	Code	: INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLG 349R	Veh. Inspected	SLG 7442H	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1185039-002	Excess (\$)	0.00	
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	06/09/2022	
2.	2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3	c.c	1496	
	Engine No.	HIDDEN	Year of Reg.	2016	
	Chassis No.	JM6BM42A8G0343563	Colour	WHITE	
	Odometer	159583 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	205/55R15	BRIDGESTONE	4 mm	
	L/H Front Tyre	205/55R15	BRIDGESTONE	4 mm	
	R/H Rear Tyre	205/55R15	BRIDGESTONE	4 mm	
	L/H Rear Tyre	205/55R15	BRIDGESTONE	4 mm	
4.	4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
				3.5	
5.	General Information				
	Accident Date	19/08/2022	Inspect Date / Time	07/09/2022 ( 07:03 PM )	
	Survey held at	NO. 4 JALAN BESUT SINGAPO			
	Repairer	LION CITY RENTALS PTE LTD			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days				
	•				