(08/11/13) wef REF:	369K	-
	SIGNMENT	
From: Date: Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV To inspect Vehicle No: SW SZYY A at Workshop m/s STRING (SMLT) of 60 wormann [MPK 84] Insured: [NC Policy No. Claims No. Sum Insured: Excess:	Veh No: SHB S244A Yr Regn: 70 17 / JAN Type: M.Car / M.Cycle / Bus / Van / Lorry / (ax) / Prime Mover / Truck / Trailer or Make: Tbyb PR PRIWD TAX c.c 1798 Colour MARGON A/C: Insured / Std / NI / NA Sp.Reading - T/Radio: Insured / Std / NI / NA Eng/No: C/No: JTD KN 3649 US 76886 (Gen. Cond: Good / Fair) / Poor / Burnt Steering: Morder / Jammed / Leaked / Burnt or	The state of the s
(Client's Record)	Brake: /norder / Jammed / Leaked / Burnt or	
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or	**
(Policy Condition) Remark: The veh had commenced its repair at the time of inspection. Bal. or Market Value: IDAC Accident Rport: Consistent?: Yes or No GIA / PR Seen: Consistent?: Yes or No Est. Repairs: days Res.: Yes or No Lum Sum: % 3 Val.: Yes or No CA / REV / REP. / 24 HRS Date / Time Action / Instruction	R: BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or	
용하면 보고 있는 사람들 <mark>요요요</mark> 전화가 있다면 사람들이 없다면 다시다고 있다.	Days Of Repair: Resurvey No. of Trip: Survey Fee: Transportation: S+RS_SI Interview (\$) Photos Trech. Invs (\$) Others	Control of the Contro



115/22, 5.00

Case Details

Case Reference Number: TAX/09/22/2007

Type of Repair : Accident Repair

Vehicle Registration Number : SHB5244A

Company Type : Strides Taxi Pte Ltd Estimation ID: EST-19275-ID

Assigned By: Taxi Claims Manager Team

Insurance Company Name : income insurance limited

Accident Date and Time: 02/09/2022 10:30 AM

Vehicle Age(In Months): -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

				SMRT Recomme	ndatio	n						Survey	or Approval	
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	0.00	Replace 🗸	der
Standard	Main			BUMPER CLIPS (10 PCS)	10	2.40	24.00	25.00	18.00	Replace	10	0.00	Replace ~	w/
Standard	Main			BUMPER REINFORCEMENT REAR	1	234.70	234.70	25.00	176.02	Replace	0	0	Check ~	7
Standard	Main			ARM SUB-ASSY. RR BUMPER RH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check 🗸	7
Standard	Main			ARM SUB-ASSY. RR BUMPER LH	1	157.90	157.90	25.00	118.43	Replace	0	0	Check ✓	?
Standard	Main			ANTENNA, ELECTRICAL LOWER REAR	1	208.10	208.10	10.00	187.29	Replace	0	0	Check 🗸	?
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check ✓	?
tandard	Main			BUMPER SIDE RETAINER RR/LH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Giv€ ✔	Xnn
tandard	Main			BUMPER SIDE RETAINER RR/RH	1	108.70	108.70	25.00	81.53	Replace	0	0	Not Giv€ ✓	Xnn

Standard	Main	BUMPER SEAL, RR LH	1	101.80	101.80	25.00	76.35	Replace	0	0	Not Give	•	Xng
Standard	Main	BUMPER SEAL, RR RH	1	74.40	74.40	25.00	55.80	Replace	0	0	Not Give	•	XM
Standard	Main	BUMPER LIP COVER RR/LH	1	93.90	93.90	25.00	70.43	Replace	0	0	Check	•	?
Standard	Main	BUMPER LIP COVER RR/RH	1		otal SPA6 F p Sum Disc			Replace	. 0	Surveyor Total 0 p Sum Dis (%)		•	?
Standard	Main	BUMPER LIP REAR	1	301.90 Fi	301.90 nal Spare F	25.00 Part Cost	226.42 8,750.78	Replace	0	0 Final Sur Total		•	?

9/5/22,	5:00	ΡМ
Stan	dard	Mai

/22, 5:00	I PIVI				4-41-	n ann 40	586.10	25.00	439.58	Replace	0		yor Approval Check	, ,
Standard BOM	Main Costing	Portion	Material	UNDER SOMERES SUMMER ASSY, RR FLOOR Part Name	endatio Qty	List	List Beigg(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity 0	Surveyor Final Price(\$)	Repair/Replace	Remark
Typedard	TWARE		Number	UNDER COVER RR SHIELD	1	66:98 Per Unit(\$)	66:40 ⁽⁴⁾	25.00		Replace	Fr	0.00	Replace V	54
Standard	Main			END PANEL	1	755.10	755.10	25.00	566.33	Керіасс	1		Not Give V	×Λν
Standard	Main			SPARE TYRE PANEL	1	755.10	755.10	25.00	566.33	Replace	0	0	Not Give	/ · ·
Standard	Main			TAILGATE ASY	1	1,260.70	1,260.70	25.00	945.53	Replace	0	0	Not Giv€ ♥	XAV
Standard	Main			TAILGATE DOOR GLASS MOULDING, RH	1	33.60	33.60	25.00	25.20	Replace	0	0	Not Giv€ ✓	XUY
Standard	Main			TAILGATE DOOR GLASS MOULDING, RH	1	33.60	33.60	25.00	25.20	Replace	0	0	Not Giv€ ♥	X11
Standard	Main			TAILGATE DOOR GLASS	1	1,273.10	1,273.10	25.00	954.82	Replace	0	0	Not Giv€ ✓	Xu
Standard	Main			MOULDING BACK WINDOW, LOWER NO.1	1	33.60	33.60	25.00	25.20	Replace	0	0	Not Giv€ ✓	X17
Standard	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	33.60	33.60	25.00	25.20	Replace	0	0	Not Giv€ ✓	X14
Standard	Main			TAILGATE LOWER WINDOW GLASS	1	827.50	827.50	25.00	620.63	Replace	0	0	Not Give 🕶	×17
Standard	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	31.30	31.30	25.00	23.48	Replace	0	0	Not Giv€ ✓	X17
Standard	Main		-	DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	22.30	22.30	25.00	16.73	Replace	0	0	Not Give 🗸 🔾	(nn
Standard	Main			TROUGH, BACK DOOR	1	126.80	126.80	25.00	95.10	Replace	0	0	Not Give 🗸 🕽	(17
Standard	Main			SEALANT W/SCREEN (3PCS)	3	37.00	111.00	0.00	111.00	Replace	0	0	Not Give 🗸)	(17
Standard	Main			TAILGATE DOOR HINGE LH/RH (2 PCS)	2	61.20	122.40	25.00	91.80	Replace	0	0	Not Give 🗸 🕽	(114
Standard	Main			TAILGATE DOOR STAY LH	1	253.40	253.40	25.00	190.05	Replace	0	0 1	Not Give > >	lng
Standard	Main			TAILGATE DOOR STAY RH	1	253.40	253.40	25.00	190.05	Replace	0	0	Not Give 🕶 🗙	ny
Standard	Main			TAILGATE DOOR LOCK	1	631.90	631.90	10.00	568.71	Replace	0	0 N	lot Give 🗸 🗶	11

Standard	Main	TAILGATE LOCK, COVER	1	20.70	20.70	25.00	15.52	Replace	0	0	Not Give	·Xnn
Standard	Main	STRIKER, BACK DOOR	1	55.80	55.80	25.00	41.85	Replace	0	0	Not Give	· XM
Standard	Main	TAILGATE DOOR WEATHER STRIP	1	402.50	402.50	25.00	301.88	Replace	0	0	Not Give	· Xny
Standard	Main	TAILGATE OUTSIDE GARNISH	1		tal Space P 5/4.60		19-938-47 20.00	Replace	0 Lu	Surveyor Total 0 Imp Sum Dis (%)	Not Give	· Xnn
Standard	Main	EMBLEM REAR	1	68.70 Fir	68.70 nal Spare P	25.00 art Cost	51.53 8,750.78	Replace	0	0 Final Sur Total	Not Give 0.00	· ×17

1-1	٦.	UU	М	W

				NAME PEAMET(FREETIDE	ndatio	n 59.20	59.20	25.00	44.40	Replace	0	0 Survey	or Approval	•	$\propto n\gamma$
Standard BOM Typedard	Main Costing Type	Portion	Material Number	Part Name NAME PLATE (PRUIS)	Qty 1	List 69.46 Per Unit(\$)	List 85.48(\$)	Dis(%) 25.00	Final P <u>5169</u> (\$)	Repair/ Replace	Surveyor Quantity 0	Surveyor Final Price(\$)	Repair/Repl	•	Remarks X19 X11
Standard	Main			NAME PLATE (TOYOTA)	1	59.20	59.20	25.00	44.40	Replace	0	0	Not Giv€		
Standard	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Giv€	•	Mn
Standard	Main			STICKER DECAL	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	•	Xun
One Time	Main			65558888 LICENSE PLATE LAMP (2 PCS)	2	40.80	81.60	10.00	73.44	Replace	0	0	Not Give		
One Time	Main			CAMERA ASSY, TELEVISION, RR	1	1,429.80	1,429.80	10.00	1,286.82	Replace	0	0	Not Giv€	~	XAT
One Time Key In	Main			3RD BRAKE LAMP	1	263.40	263.40	10.00	237.06	Replace	0	0	Not Give		Xan
One Time Key In	Main			SPOILER REAR	1	1,263.70	1,263.70	25.00	947.78	Replace	0	0	Not Give	~	Xnn
Key III						To	otal Spare I	Part Cost	10,938.47		Su	rveyor Total	0.00		
						Lum	p Sum Disc	ount (%)	20.00		Lump	Sum Dis (%)	20		
						Fi	inal Spare I	Part Cost	8,750.78		Fir	nal Sur Total	0.00		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,014.00	400	
Total:			1,014.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	o X19	
3	Main	TO RESPRAY REAR PANEL	180.00	100	
4	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	· Xva	
5	Main	TO RESPRAY REAR SPOILER	180.00	· X14	Dater of Collaboration of the personal collaboration of the collaboratio
6	i Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00		Environment (2) had beginn
	7 Main	TO RESPRAY TAIL GATE	378.00	0 X11	Leuter (i
-	Total:		1,656.00	300.00	the content of the co

.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	。×つつ	
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 X11	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40	
	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	· Xan	
	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	· X17	
	Main	TO REPLACE SUNDRY PARTS	100.00	. Lun	
al:			860.00	80.00	

Summary

Signature:

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	8,750.78	0.00
Total Labour Cost	1,014,00	400.00
Total Spray Painting	1,656.00	300.00
Other	860.00	80.00
Overall Total	12,280.78	780.00
ump Sum Repair Option		
ump Sum Total	12,300.00	800.00
Surveyor Approved Amount		800.00
lo of Repair Days*	7	4
demarks		lump sum repair / resurvey after repair
urveyor Name		Rasul
No illegal modification(s Supplementary item(s)	ollowing: r spray painting rt(s) during resurvey to confirmation a "Without Prejudice" basis) is allowed	Save Clear
Acknowledged by Repaire		

SS3D22930002 / Strides Automotive Services Pte Ltd (757705) ENTRY DATE & TIME: 05/09/2022 09:07 (SGT) SUBMITTED BY: SHANTI B THAIYAL NAYAGI (SMRT05) VERSION: 1 (05/09/2022 09:07 (SGT))

G SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be extended in the part of the insurance companies.

5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance description.

5. Any false reporting may be referred to the Police for investigation.

6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available.

ACCIDENT STATEMENT

Date of Submission Reported by **Date of Accident Exact Location of Accident**

Additional Location Information

Country/State of Loss

05/09/2022 09:07 (SGT)

Driver

02/09/2022 18:30 (SGT)

Admiralty St, Singapore

SLIP ROAD FROM ADMIRALTY STREET TOWARDS

SEMBAWANG DRIVE

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SHB5244A

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No

Email Address Mobile Phone No

Alternative Phone No

Yes

Toyota

Prius

Taxi

Auto

1800

Strides Taxi Pte Ltd 1XXXXX369K

AUTO-SVCS-TARC@SMRT.COM.SG

(Phone) +65-68662671

No - Claiming third party

VEHICLE PARTICULARS

Manufacturer

Model Variant

Exact purpose for which vehicle was being used at time of

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

Transmission CC

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number MS First Capital Insurance Ltd D-22099115MFSH

DRIVER

Name of Driver **NRIC No** Date Of Birth

LIO YOON FATT SXXXX177Z 24/04/1965



Occupation Outdoor **Date Of Driving Pass** 04/10/1982 39 YEARS AND 11 MONTHS Driving experience Gender Male (Phone) +65-68662672 Mobile Number Alt. Phone Number AUTO-SVCS-TARC@SMRT.COM.SG **Email Address** Address 11 Address complement Postcode Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Hirer Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions CLOUDY Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT I WAS STATIONARY ALONG THE SLIP FROM ADMIRALTY STREET TOWARDS SEMBAWANG DRIVE AS I WAS LOOKING OUT FOR THE ONCOMING TRAFFIC. SUDDENLY I FELT AN IMPACT AT THE REAR OF MY TAXI. A VEHICLE GBC6777M HAD COLLIDED ONTO THE REAR OF MY TAXI. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No **DETAILS OF OTHER VEHICLE PROPERTY 1 GBC6777M** Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant

Vehicle Colour

Vehicle Category Name of Driver Contact Number	Commercial vehicle TENG EE MENG		
Add a second	-		
Address complement	-		
Postcode	=		
Insurance Company Name Nature Of Damage	-		
o. Daillade	-		
Details of property damaged in accident No. Of Passenger (Including Driver)	-		
No. Of Passenger (Including Driver)	-		

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Actual Drivet.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Traffic Police Department for investigation.

- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a lee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the daims:
- (ii) investigating the accident and/or my claims:
- (aii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Actual Dropr's Signature (if driver is not the policyholder) / Date & Time

MN 3.9-2022 Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

Sketch Plan



vJun2022

ibe Circumstance of the Accident					
				na a time talang yan kana mana da a a a a a a a a a a a a a a a a a	and the second second
				and the second second second second	
	-				
The second secon			4.5	to an extension for the extension from the control of	
and the second process of the second district and the second seco					
				a temperandida di Santa di San	
Allendaria de la collega de la					in the proof of the header of the first
				The second second second second	and the second second is a similar of the
1.6 a file of protect or first colored			And the second s		
alatti (m. edus alike korgen). Om e estatati attaquisti				magnification (see, see "collecte") filtered photos one even held	A STATE OF THE PARTY OF THE PAR
				at same and the	
					COMMENT REPORT TO SHEET AND ADMINISTRATION OF MARKET
			American de	Martine and the second of the first standard and the	
					Anna Company
				The same of the following trades of the same of the sa	
			the second of the second		
the determinant of the second of the second of					
					The state of the s
					No. of Persons and Personal Printers and Personal Printers and Personal Per
					Produced State Control of the Contro
	A				
			The company of the second of t		
Declaration					
I/We declare the foregoing particulars are t	ue in every respect.				
1 some con	A //		Į.		
(*()×)	e hw 1	03/09/23	z L	1111	0
Policyholder's Signature / Date & Time Ai				3.0	9.2022
Della de altrete Signatura / Data & Tima A.	Must Dayote Cink store	A delice of the second			

Accident report \$\$3D22930002

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	在主意中的工艺工具。Company 图象工艺工艺和中国中创新的图像图象工艺工艺工艺和新闻
Owner ID:	369K
Vehicle No.:	SHB5244A
Vehicle to be Exported:	G B S S T T T T T T T S S S S S T T T T T
Intended Deregistration Date:	06 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6614918
Chassis No.:	JTDKN36U905768861
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	25 Jan 2017
First Registration Date:	25 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes we have the first that the first the first term of the first t
PARF Eligibility Expiry Date:	24 Jan 2025
PARF Rebate Amount:	\$3,500.00
COE Expiry Date:	24 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (1306hp)
COE Period(Years):	B B B B B B B B B B B B B B B B B B B
PQP Paid:	\$40,516.00
COE Rebate Amount:	\$12,062.00
Total Rebate Amount:	\$15,562.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Sep 2022