



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/11/2022

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1320E
Case Reference Number	BUS/08/22/5057
Registration Date	26/2/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Malik Bala Muniandy Bin Abdullah
Type of Accident	Side Swipe
Accident Date and Time	31/8/2022 8:00 AM
Accident Reported Date and Time	5/9/2022 10:56 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116184
Special Instruction to ARC,if any	SMB1320E - RIGHT CENTRE PORTION PENDING TP DETAILS
Prepared Date and Time	5/9/2022 1:34 PM
Chassis Number	WMAA22ZZ9D7001756
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,325.00
Total Spray Cost	\$786.00	\$616.00
Total Spare Part Cost	\$1,181.86	\$1,181.86
Total Other Cost	\$0.00	(\$388.20)
TOTAL COST	\$3,557.86	\$2,734.66
Lump Sum Total	\$0.00	\$2,750.00
Number of Repair Days	4.0	3.0
Prepared / Adjusted By	Jeong Choon Hwee	Rasul
ARC / Surveyor Sign Off Date	05/09/2022 1:39 PM	06/09/2022 3:03 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/11/2022

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,590.00				\$1,325.00		
Total Labour			\$1,590.00				\$1,325.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00				\$616.00		
Total Spray Painting & Panel Beating			\$786.00				\$616.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor			\$0.00				(\$388.20)		
Total Other Costs			\$0.00				(\$388.20)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
			SMRT STICKERS	1.00	\$200.00	0.00	\$200.00	Replace	Replace
6010166	GLASS	4001X01-GLASS5175	GLASS,SIDE:R3,FOR MAN A22 BUS	1.00	\$994.80	10.00	\$895.32	Replace	Replace
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	Replace
4006314	CONSUMABLE		ADHESIVE:DIRECT GLAZING	6.00	\$37.00	0.00	\$222.00	Replace	Replace
4006315	CONSUMABLE		ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	Replace
Total					\$1,391.80		\$1,477.32		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									