







# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

Account Details			Account No.		Customer Details		
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept			S1000006 / ICIII1		Mr S Selvaraju 150 Mei Ling Street #13-45 Singapore 141150  Mobile: 96363178		
			Document No. 0				
			Document Date 05/09/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ S3	02/11/2016	SLH4087P	0	17370	SLH4087P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
MR053REH104553141		1ZRX581847	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY TP INS:INDIA INTERNATIONAL INSURANCE TP VEH:SLM3518T DATE OF ACC:02.09.2022				50	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				200	200.00
3	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR					180.00
4	B	BP-LAB2 CHECK WIRING AND CONDUCT WATER TEST					122.40
5	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				360	720.00
6	B	BP-LAB2 REMOVE AND TRANSFER BOOTLID COMPONENTS ONTO NEW BOOTLID. R/I REAR REVERSE CAMERA TO FAC REPAIR.					540.00
7	B	BP-ECU2 TO RESET ECU AND REPROGRAMME					180.00
8	L	BP-LPO SUPPLY REGN PLATE (PO# )					80.00
9	B	BP-LAB2 REPLACE ACC DAMAGED PARTS @ 720 X 85				3600	4320.00
10	B	BP-RES2 RESPRAY ACC AFFECTED AREAS @ 590 X 5				2950	3540.00
11	1	SPZ061-12028 76 GREY METALLIC 2 REVERSE SENSOR	1.00	158.30			158.30
12	2	S52159-0Z904 COVER, RR BUMPER	1.00	602.60			602.60
13	3	S52161-0K040 PIECE, RR BUMPER	10.00	4.50			45.00
14	4	S52023-02190 REINFORCEMENT SUB-AS	1.00	432.50			432.50
15	5	S52181-02190 ARM, RR BUMPER, OUTE	1.00	73.70			73.70
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy





# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

Account Details	Account No.	Customer Details
India International Insurance P L	S1000006 / ICIII1	Mr S Selvaraju
64 Cecil Street	Document No.	150 Mei Ling Street
#06-02 IOB Building	0	#13-45
Singapore 049711	Document Date	Singapore 141150
Attn: Motor Claims Dept	05/09/2022	Mobile: 96363178

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZRE171R	GEXGKZ S3	02/11/2016	SLH4087P	0	17370	SLH4087P
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
MR053REH104553141	1ZRX581847	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	6	S52182-02160 ARM, RR BUMPER, OUTE ?	1.00	73.70		73.70
17	7	S52575-02140 RETAINER, RR BUMPER <i>an</i>	1.00	118.70		118.70
18	8	S52562-02250 RETAINER, RR BUMPER, <i>an</i>	1.00	65.60		65.60
19	9	S52576-02140 RETAINER, RR BUMPER <i>an</i>	1.00	118.70		118.70
20	0	S52563-02250 RETAINER, RR BUMPER, <i>an</i>	1.00	65.60		65.60
21	1	S58307-02380 PANEL SUB-ASSY, BODY <i>st</i>	1.00	727.70		727.70
22	2	S64401-02B71 PANEL SUB-ASSY, LUGG <i>st</i>	1.00	852.90		852.90
23	3	S64461-02220 WEATHERSTRIP, LUGGAG ?	1.00	190.10		190.10
24	4	S64503-02181 ARM SUB-ASSY, LUG CO ?	2.00	75.60		151.20
25	5	S64600-02080 LOCK ASSY, LUGGAGE C <i>bt</i>	1.00	432.50		432.50
26	6	S58387-02240 PLATE, RR FLOOR FINI <i>de</i>	1.00	261.60		261.60
27	7	T90467-08186 C0 CLIP <i>an</i>	2.00	3.00		6.00
28	8	S64771-02390 C0 COVER, SPARE WHEEL <i>an</i>	1.00	288.40		288.40
29	9	S75431-02090 EMBLEM, LUGGAGE COMP <i>an</i>	1.00	66.90		66.90
30	0	S75442-02330 PLATE, LUGGAGE COMPT <i>an</i>	1.00	44.40		44.40
31	1	S75442-02340 PLATE, LUGGAGE COMPT <i>an</i>	1.00	49.40		49.40
32	2	S76801-02E30 GARNISH SUB-ASSY, BA X	1.00	263.40		263.40
33	3	S81550-02780 LAMP ASSY, RR COMBIN <i>an</i>	1.00	410.80		410.80
34	4	S81560-02780 LAMP ASSY, RR COMBIN <i>an</i>	1.00	410.80		410.80
35	5	T81496-60010 GUIDE, RR <i>an</i>	2.00	3.90		7.80

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy





# Borneo Motors

Inchcape

Co. Reg No. : 196700086Z  
GST Reg No. : MR-8500000-9  
No. 2 PANDAN CRESCENT  
SINGAPORE 128462, Tel no.: 6631 1188



# TOYOTA

## ESTIMATE

Account Details		Account No.	Customer Details					
India International Insurance P L 64 Cecil Street #06-02 IOB Building Singapore 049711 Attn: Motor Claims Dept		S1000006 / ICIII1	Mr S Selvaraju 150 Mei Ling Street #13-45 Singapore 141150  Mobile: 96363178					
		Document No. 0						
		Document Date 05/09/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2016	ZRE171R	GEXGKZ S3	02/11/2016	SLH4087P	0	17370	SLH4087P	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
MR053REH104553141		1ZR581847	60	Thomas Pang W T	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
36	6	S81580-02551	LAMP ASSY, RR, RH	X	1.00	426.60		426.60
37	7	S81590-02551	LAMP ASSY, RR, LH	X	1.00	426.60		426.60
38	8	S81910-02170	REFLECTOR ASSY, REFL	X	1.00	65.00		65.00
39	9	S81920-02110	REFLECTOR ASSY, REFL	X	1.00	65.00		65.00
40	0	T89997-30070	ANTENNA, ELECTRICAL	X	1.00	208.10		208.10
<div style="border: 1px solid blue; padding: 5px; margin: 10px;"> <p><b>LKK Auto Consultants</b> hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: _____ Date: _____</p> </div> <div style="margin-top: 20px;"> <p><i>Resu</i> <i>Hp 90010068</i> <i>9 days</i> <i>P/P</i> <i>07/09/22 @ 1000</i> <i>Resu before paint</i></p> </div>								
For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 17,192.00		
		Please acknowledge receipt of vehicle		Parts	7,109.60	GST 7.00% 1,203.44		
				Labour	10,002.40			
				Sublet	80.00	Less 0.00		
				Lubrication/Fluid	0.00			
				Others	0.00	Amount Due 18,395.44		



# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	05/09/2022 09:03 (SGT)
Reported by	Driver
Date of Accident	02/09/2022 10:55 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE TOWARDS CHANGI BEFORE TOA PAYOH EXIT
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH4087P
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	S SELVARAJU
NRIC No	SXXXX316D
Email Address	S.ARJUNKUMAR@GMAIL.COM
Mobile Phone No	(Phone) +65-96363178
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

## INSURANCE COMPANY

Name of Insurance Company	AIIG Asia Pacific Insurance Pte. Ltd.
Policy Number / Cover Note Number	2100488799-01

## DRIVER

Name of Driver	S ARJUN KUMAR
NRIC No	SXXXX849I
Date Of Birth	23/11/1999
Occupation	Indoor



Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

20/08/2019  
3 YEARS AND 1 MONTH  
Male  
(Phone) +65-81124655  
-  
S.ARJUNKUMAR@GMAIL.COM  
BLK 150 MEI LING ST #13-45  
-  
141150  
No  
Child  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Chain Collision  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?  
Number of vehicles involved in the accident  
Was anybody injured in the Accident?  
Was any injured conveyed to hospital by ambulance?  
Was any other vehicle or property damaged?  
Number of Passengers (Including Driver)  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?  
Translator's name  
Translator's ID  
Translator's phone number  
Translator's email  
Original language used in the statement

No  
4  
No  
-  
Yes  
2  
No  
-  
-  
-  
-

#### PASSENGER 1

Name  
Gender

JEREMY TAN  
Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?  
Police Station Name  
Police Station Phone No  
Alt. Police Station Phone No  
Police Station Address  
Was notice of intended Prosecution given?  
If yes, against whom?

Yes  
Clementi Neighbourhood Police Post  
(Phone) +65-18007759999  
(Fax) +65-67764246  
Blk 427 Clementi Avenue 3 #01-456 Singapore 120427  
No  
-

#### CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

#### ATTACHMENT(S)

Are accident photos available for attachment?  
Was there any video captured by Car Camera?  
Reasons for not uploading a video of the accident

Yes  
Yes  
WITH TP

#### DETAILS OF OTHER VEHICLE PROPERTY 1



Vehicle Registration Number	SLM3518T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	-
Name of Driver	Private car
NRIC No	ONG CHEE HAO
Contact Number	SXXXX461I
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	QX2104T
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Government
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

#### DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SMN2887S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



TYPE OF CLAIM: ☐ OD ☐ OD/UL ☒ DS

MCA: TP

## MOTOR ACCIDENT REPORT

Date Of Report: 03/09/2022 Time: 10:55 1020 Date Of Accident: 02/09/2022 Time: 1055

Exact Location Of Accident: PIE near towards Changi, before LCA payoh exit.

Country/State of Loss: Singapore ☒ / Wilayah Persekutuan ☐ / Selangor Darul Ehsan ☐ / Negeri Sembilan ☐ / Melaka ☐ / Pahang ☐ / Johor ☐ / Perak ☐ / Kedah ☐ / Kelantan ☐ / Terengganu ☐ / Pulau Pinang ☐ / Perlis ☐ / Thailand ☐Who Reported the Accident? Owner ☐ Driver ☒ Both ☐Was this statement translated from another language?  
No ☒ Yes ☐ If yes, please fill ANNEX C

## OWN VEHICLE DETAILS (INSURED/POLICY HOLDER)

Vehicle Registration Number: SLH408TP

Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No: S1695316D

Name Of Registered Owner: S Selvaraju

Mobile Number: +65 96363178

Alternative No: +41797274138

Email Address:

S.arjunkumar@gmail.com

(Compulsory)

## Vehicle Particulars

Manufacturer: Toyota ☒ Lexus ☐ Suzuki ☐ Hino ☐

Model: Toyota Altis 1.6A

Exact Purpose for which vehicle was being used at time of accident: Normal Usage ☒ Other ☐ (please specify):Are you claiming under your own insurance policy for repair to your vehicle? Yes ☐ Reporting Only ☐Third Party ☒ If Liability Clearance UNSUCCESSFUL within 14 Days, I will revert to Own Insurance Policy ClaimVehicle Category: Private Car ☒ Commercial Vehicle ☐ Others ☐

## Insurance Company

Name of Insurance Company: AIG

Type Of Coverage: Comprehensive ☒ Third Party ☐ Third Party Fire and/or Theft ☐Fleet Policy: Yes ☐ No ☒

Policy / Cover Note No:

21004PF799-04

## DRIVER DETAILS AT POINT OF ACCIDENT

Name of Driver: S Arjun Kumar

NRIC/ Passport / FIN No: S99468491

Date Of Birth: 23/11/1999

Occupation: Indoor ☒ Outdoor ☐

Date Of Driving Pass: 20/8/2019

Gender: Male ☒ Female ☐

Mobile Number: +65 8124655

Fax No:

Alternative No:

Address: S. Arjunkumar@gmail.com B1K 150 Meiling Street #13-45 S11150

Postal Code: 141150

Email Address: S. Arjunkumar@gmail.com

Was driver an employee of the Insured's Company? Yes ☐ No ☒ State relationship of the driver with the insured: Son

Vehicle Registration Number of Driver's Own Vehicle (if applicable):

Insurance Company of Driver's Own Vehicle (if applicable):

## GENERAL INFORMATION OF THE ACCIDENT

Type Of Accident: Chain Collision

Weather Conditions: Clear ☒ Raining ☐ Others ☐ (If others, please state condition):Road Surface: Wet ☐ Dry ☒ Others ☐ (If others, please state condition):Was any body injured in the Accident? No ☒ Yes ☐Was any injured conveyed to hospital by ambulance? No ☒ Yes ☐Was any foreign vehicle involved in this accident? No ☒ Yes ☐ Vehicle No:

Vehicle type:

Number of vehicles involved in the accident: 4

Was there any witness? No ☒ Yes ☐ If yes, please furnish witness details column below

Witness Name:

Contact No.:

Email:

Was there any other vehicle or property damaged? No ☐ Yes ☒

with TP

Was there any video captured by Car Camera? No ☐ Yes ☒Are accident scene photos available for attachment? No ☐ Yes ☒Was the accident reported to the police? No ☐ Yes ☒ (If yes, please state which Police Station):Was notice of intended Prosecution given? No ☒ Yes ☐ (If yes, please state against whom):I have been approached by unknown person(s) soliciting/offering accident claims assistance. No ☒ Yes ☐

## PASSENGER 1

Number of Passengers in the above vehicle (Including Driver): 2

/ If more than 2 Pax Please fill ANNEX B

Name: Jeremy Tan

Gender: Male ☒ Female ☐

## DETAILS OF OTHER VEHICLE PROPERTY 1 (Please fill Annex A if more vehicles involved)

Vehicle Registration Number: SLM3518T

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Vehicle Category:

Name of Driver: ONG Chee Hao

NRIC/Passport/FIN Number: S83214611

Contact Number:

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:



## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number: QX2104T

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Name of Driver:

NRIC/Passport/FIN Number:

Contact Number:

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver):

## DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number: SWN 2887S

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Name of Driver:

NRIC/Passport/FIN Number:

Contact Number:

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver):

## DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number:

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Name of Driver:

NRIC/Passport/FIN Number:

Contact Number:

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver):

## DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number:

Vehicle Make/Model/Colour:

Details Of Properties Damage in Accident:

Name of Driver:

NRIC/Passport/FIN Number:

Contact Number:

Address:

Postal Code:

Insurance Company Name:

Nature Of Damage:

No. Of Passenger (Including Driver):

## DETAILS OF INJURED PERSON 2

Name:

Approximate Age:

Address:

Postal Code:

Injuries Sustained:

Injured person in which vehicle:

Were seat belt worn? Yes ☐ No ☐Were injured conveyed to hospital by ambulance? Yes ☐ No ☐

## DETAILS OF INJURED PERSON 3

Name:

Approximate Age:

Address:

Postal Code:

Injuries Sustained:

Injured person in which vehicle:

Were seat belt worn? Yes ☐ No ☐Were injured conveyed to hospital by ambulance? Yes ☐ No ☐

## DETAILS OF INJURED PERSON 4

Name:

Approximate Age:

Address:

Postal Code:

Injuries Sustained:

Injured person in which vehicle:

Were seat belt worn? Yes ☐ No ☐Were injured conveyed to hospital by ambulance? Yes ☐ No ☐

## DETAILS OF INJURED PERSON 5

Name:

Approximate Age:

Address:

Postal Code:

Injuries Sustained:

Injured person in which vehicle:

Were seat belt worn? Yes ☐ No ☐Were injured conveyed to hospital by ambulance? Yes ☐ No ☐



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

#### Sketch Plan



PIE (cheyi).


Describe Circumstance of the Accident


Refer to Police Report

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

  
Driver's Signature (if driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)





**SINGAPORE  
POLICE FORCE**



T/20220903/2048

Police Station Of Origin  
Clementi NPP  
427 Clementi Avenue 3 #01-456  
SINGAPORE 120427  
Tel No: 1800-7759999

1 of 4

Report No. T/20220903/2048

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made:  
03/09/2022 12:52

Video Report No.:  
E/20220902/0051

Station Diary No.:  
13

**Informant's Particulars**

Name of Informant: S ARJUN KUMAR			Address: APT BLK 150 MEI LING STREET #13-45 SINGAPORE 141150		
ID Type / ID No.: NRIC NO / S9940849I			Contact No.: Home/Office: Mobile: 81124655		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 22	Date of Birth: 23/11/1999	Type of Informant: Driver		
Race: Indian			Language: English	Institution / School Name: SINGAPORE MANAGEMENT UNIVERSITY	
Occupation: Student			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident: Non-Injury Police Vehicle	Drink Drive: No	Date/Time of Accident: 02/09/2022 10:55	Type of Location:
Location:  PAN-ISLAND EXPRESSWAY			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow:	Traffic Control:	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Side			Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX2104T	Car					0
SLH4087P	Car					0
SLM3518T	Car					0
SMN2887S	Car					0





**SINGAPORE  
POLICE FORCE**



T/20220903/2048

Police Station Of Origin  
Clementi NPP  
427 Clementi Avenue 3 #01-456  
SINGAPORE 120427  
Tel No: 1800-7759999

2 of 4

Report No: T/20220903/2048

**CONTINUATION OF REPORT**

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Driver</b>			
Name	S ARJUN KUMAR	ID No.	S9940849I
Related Vehicle	SLH4087P (Car)	Contact No.	81124655
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	ONG CHEE HAO	ID No.	S8321461I
Related Vehicle	SLM3518T (Car)	Contact No.	90252855
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 02/09/2022 at about 1055hrs, I was driving along PIE towards Changi before Kim Keat Link. I was driving behind a Police Car (QX2104T) and I could see that the Police car slowing down and stop. I also managed to stop behind the Police car. However, the car which was behind me (SLM3518T) did not stopped in time and collided into my car which made my car moved forward and hit into the Police car. I exited my car and exchanged details with the driver behind me. We also waited for arrival of Traffic Police. Our particulars were then taken by the Traffic Police.

Soon after, the Traffic Police officers requested the drivers of the 4 cars to follow him to the nearest carpark as we were causing a jam and to prevent any further accident. While we were making our way, as we were exiting PIE at the Kim Keat Link, I saw that the Police Car had moved out of the slip road and therefore I made a check for any incoming traffic. There was a motorcycle coming. Therefore, I stopped and out of a sudden I collided into the Police car which was in front of me. We exited the car to check if anybody was injured.

The Traffic Police then advised us to proceed to the carpark. I have in car camera and the SD card was taken by Traffic Police.





SINGAPORE  
POLICE FORCE



1073211102010

Police Station Of Origin  
Commiss NPP  
427 Clementi Avenue West 151  
SINGAPORE 121427  
Tel No: 1800-7750969

Report No: 12020700000000000000

CONTINUATION OF REPORT



**SINGAPORE  
POLICE FORCE**



T/20220903/2048

4 of 4

Police Station Of Origin:  
Clementi NPP  
427 Clementi Avenue 3 #01-456  
SINGAPORE 120427  
Tel No: 1800-7759999

Report No. T/20220903/2048

**CONTINUATION OF REPORT**

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT:** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature of Officer Recording The Report:

D /

SGT 3 MUHAMMAD SYAHMI BIN  
SENIN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

03/09/2022 12:52

Officer In Charge Of Case:

TP / DDGVT /

Classification Of Case:

Contact No.:

NP168



> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	316D
Vehicle No.:	SLH4087P
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Sep 2022
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 CVT
Primary Colour:	Grey
Manufacturing Year:	2016
Engine No.:	1ZRFX581847
Chassis No.:	MR053REH104553141
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$19,990.00
Original Registration Date:	02 Nov 2016
First Registration Date:	02 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$19,990.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Nov 2026
PARF Rebate Amount:	\$13,993.00
COE Expiry Date:	01 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$21,150.00
Total Rebate Amount:	\$35,143.00

The information contained herein is correct as at 08 Sep 2022

OK



# Toyota Corolla Altis 1.6A

Overview

Financial

Accessories

Similar

Research

Photos

Map



EDMUND  
MOTOR

Price **\$62,800**

Depreciation ⓘ \$14,000 /yr  
[View models with similar depre](#)

Reg Date 22-Jun-2016  
(3yrs 9mths 13days COE left)

Mileage 127,408 km (20.5k /yr)

Manufactured ⓘ 2015

Road Tax ⓘ \$742 /yr

Transmission Auto

Dereg Value ⓘ \$32,157 as of today ([change](#))

OMV ⓘ \$19,589

COE ⓘ \$51,301

ARF ⓘ \$19,589

Engine Cap 1,598 cc

Power 90.0 kW (120 bhp)

Curb Weight ⓘ 1,205 kg

No. of Owners ⓘ 3