

			CC	OMFORTDELGR		
Our	Job Re	ef No :305528979	EN	ENGINEERING		
Date	е	: 09.09.2022	ComfortDelGro Engineering Pte Lt 59 Loyang Drive Singapore 50896			
FIN	<b>ALIZA</b> 1	TON FORM				
То	:	LKK	Fax:			
Attn		GUO QIANG	_			
Veh	icle Re	g No. : SHC1338J		06.09.2022		
The	survey	and estimates of the repairs of the above-menti	ioned vehicle are as follows	:-		
Z	The	repair job shall bill to:	OKIO MARINE	SLH6539P		
2.	The	finalized amount shall be:				
	(a)	Spare Parts after List discount				
	(b)	Labour Charges		14		
		Total for Part-By-Part Repair Cost				
	(c.)	Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less; Final Lumpsum Repair cost		\$3,500.00		
<b>3</b> . <b>4</b> .	Estimated normal period for repairs:  4 working days.  We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days					
5.	Than	k you for your assistance.	We confirm the es	timates and		
	Signa	ture :	Signature :			
	Signa					
	Ŭ					

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid	2	N		
3. Survey Fees	240	=		
4. LTA Search Fee	\$7.49/\$2.00	YES		
Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

emarks:			