

Date: 07/09/2022
Vehicle No: SMR5275S
Model: HYUNDAI IONIQ HEV 1.6
Chassis: KMHC851CVLU200969 - 2019
Reg.Year: 2020

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SLR2003S
Date of Accident: 05/09/2022
Estimator: KIT
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		REPAIR
2	REAR FENDER RH	1		REPAIR
3	REAR RIM COVER RH	1		REPAIR
			SUB TOTAL	\$0.00
			LESS 20%	\$0.00
			PARTS TOTAL	\$0.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST ACCIDENT AREAS. \$200.00 ✓

LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS. \$600.00 480

LABOUR TOTAL \$800.00

KIT TOTAL \$800.00

*Not Authorized
Phenny After Being
2 days*