

ASS. REC. BY:

REF:

U021 2200-8789/K

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 856k

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLB 92287 Yr Regn: 04, 16Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis c.g. 1598Colour: M. P. White A/C: Insured / Std / NI / NASp. Reading: 46272 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MR053R E410 45 45628Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModl: ☒ Nil / S/Rlm / STD / Rlm orTyre Size: F: 205/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / XOKO or

Front

R/Bal. 5 mmL/Bal. 5 mmD.O.A. 3/9/22

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S & O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: \_\_\_\_\_

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$

Transportation:

☐ : Interview (\$

S + RS. SI

☐ : Tech Invs (\$

Frt / RS

☐ : Weekend (\$

Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

金興(興)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

No. : 32530

Your Reference : DH0M120051812002

Accident Date : 03-Sep-2022

Date : 07-Sep-2022

PAGE : 1

Our Ref : 022255 / CARIN

CHENG KAM YIN (MR)  
C/O UNITED OVERSEAS INSURANCE LIMITED  
146 ROBINSON ROAD  
#02-01  
UOI BUILDING  
Singapore 068909

NOT Notified  
11 By B  
Recovery After Paint  
5 days Ex B7501

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6L CVT(2016) SLB9228Z  
=====

1 pc	front bumper		Buclnu	220.00	c ✓
1 pc	o/s front bumper side retainer		DRY	40.00	c ✓
10 pcs	front bumper clip	@ S\$ 1.50	mu	15.00	c ✓
1 pc	o/s front bumper foglamp		mu	135.00	c X
1 pc	o/s front bumper foglamp cover		mu	90.00	c X
1 pc	front bumper centre lower grille		Red/rep	85.00	c ✓
1 pc	front bumper sponge		Py	60.00	c ?
1 pc	o/s front fender		mu	295.00	c ✓
1 pc	o/s front fender 'VVTi' emblem		mu	30.00	c ✓
1 pc	o/s front fender inner shield		CMS	70.00	c ✓
8 pcs	o/s front fender inner shield clip	@ S\$ 1.50	mu	12.00	c ✓
2 pcs	o/s front fender inner shield retainer clip	@ S\$ 6.00	mu	12.00	c ✓
2 pcs	o/s front fender inner shield retainer pin	@ S\$ 4.00	mu	8.00	c ✓
1 pc	wiper washer tank		Red	80.00	c ✓
1 pc	wiper washer tank motor			85.00	c ?
1 pc	o/s headlamp		Wt	650.00	c ✓
1 pc	o/s headlamp top chrome		mu	95.00	c X
1 pc	engine front under cover			90.00	c ?
				2,072.00	
Add 10% :				207.20	
				2,279.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

金興(龔)汽車私人有限公司

K. KIM HIN AUTO PTE LTD

160 Sin Ming Drive #02-18/19/20

Sin Ming AutoCity

Singapore 575722

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Your Reference : DH0M120051812002  
Our Ref : 022255

Page : 2  
No. : 32530

To remove, cut out damaged parts,  
panel beating, welding, align,  
refix and to renew affected parts.

680.00 *500*

To conduct front wheel alignment  
test.

*nr* 80.00 *X*

To putty and respray on affected  
portions.

750.00 *600*

To focus headlamps. To check front  
wiring and lighting operation.

30.00 *200*

Total :  
-----  
S\$ 3,819.20  
=====

Singapore Dollars Three Thousand Eight Hundred  
and Nineteen and Cents Twenty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	05/09/2022 19:38 (SGT)
Reported by	Both
Date of Accident	03/09/2022 22:40 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	CAR PARK AT SERANGOON NORTH AVENUE 1, BLOCK 106
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB9228Z
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHENG KAM YIN
NRIC No	SXXXX918I
Email Address	CHENGKAMYIN@NOK.COM.SG
Mobile Phone No	(Phone) +65-97162135
Alternative Phone No	+65-62801265

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	ALTIS
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1598

### INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Policy Number / Cover Note Number	DHOM120051812002

### DRIVER

Name of Driver	CHENG KE JING
NRIC No	SXXXX726A
Date Of Birth	06/02/1992
Occupation	Indoor

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Traffic Police Department for investigation.
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;


(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time




Actual Driver's Signature (if driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel  
(Name as in NRIC/ID card)

Khong Yee Tong

**Sketch Plan**





## Inquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Singapore NRIC

### Vehicle Details

918I

Vehicle No.:

Vehicle to be Exported:

SLB9228Z

Intended Deregistration Date:

No

Vehicle Make:

05 Sep 2022

Vehicle Model:

TOYOTA

Primary Colour:

TOYOTA COROLLA ALTIS 1.6L CVT

Manufacturing Year:

White

Engine No.:

2015

Chassis No.:

1ZRX552900

Maximum Power Output:

MR053REH104545628

Open Market Value:

90.0 kW (120 bhp)

Original Registration Date:

\$19,589.00

First Registration Date:

27 Apr 2016

Transfer Count:

27 Apr 2016

Actual ARF Paid:

0

### Intended PARF Rebate Details

PARF Eligibility:

\$19,589.00

PARF Eligibility Expiry Date:

Yes

PARF Rebate Amount:

26 Apr 2026

### Intended COE Rebate Details

COE Expiry Date:

\$12,732.00

COE Category:

26 Apr 2026

COE Period(Years):

A - Car up to 1600cc & 97kW (130bhp)

QP Paid:

10

COE Rebate Amount:

\$46,009.00

Total Rebate Amount:

\$16,754.00

\$29,486.00

The information contained herein is correct as at 05 Sep 2022

OK