

ASS. REC. BY:

REF:

MSG/22008825/KV

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

09 days

Res.: Yes or No

Lum Sum:

1.41 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKC8198P

Yr Regn:

03, 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Cerato

c.c.

1581

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

49246

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KNAP3416MK 5029829

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

2/9/22

D.O.I.

8/9/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got B1, maybe part by part, unable to locate the parts.

10/4 @ 14721.29 Cash 19/4/23

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS - SI

Fines

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	06/09/2022 17:55 (SGT)
Reported by	Both
Date of Accident	02/09/2022 21:20 (SGT)
Exact Location of Accident	Jurong Gateway Rd, Singapore
Additional Location Information	JURONG GATEWAY ROAD (BESIDE JEM)
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKC8198P
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	POH WEI REN
NRIC No	SXXXX058I
Email Address	XPWRX@HOTMAIL.COM
Mobile Phone No	(Phone) +65-97724617
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Cerato
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600

INSURANCE COMPANY

Name of Insurance Company	Allianz Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	SP2001255360-01

DRIVER

Name of Driver	POH WEI REN
NRIC No	SXXXX058I
Date Of Birth	30/06/1982
Occupation	Indoor

Date Of Driving Pass	09/07/2007
Driving experience	15 YEARS AND 2 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97724617
Alt. Phone Number	-
Email Address	XPWRX@HOTMAIL.COM
Address	BLK 210 SERANGOON CENTRAL #05-242
Address complement	-
Postcode	550210
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head on collision
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	NICOLE POH XUAN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Paya Lebar Neighbourhood Police Post
Police Station Address	Blk 114 Hougang Avenue 1 #01-1270 Singapore 530114
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP4034A
Vehicle Manufacturer	-

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	POH WEI REN
Gender	Male
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKC8198P
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

INJURED 2

Name of injured person	ANDREA NICOLE POH XUAN
Gender	Female
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKC8198P
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

INJURED 3

Name of injured person	-
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SLP4034A
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	Yes

SKETCH PLAN

VEH A: JC8198P
VEH B:
VEH C:

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or


(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


6th Sep 2022 16:48 hrs
Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



Describe Circumstance of the Accident

DATE OF ACCIDENT: 29/12/22

TIME OF ACCIDENT: 2126hrs

VEH A: 3K 8198P

VEH B:

VEH C:

I was travelling along Jersey Gateway road. I saw an oncoming vehicle driving straight towards my direction. I stopped and horn but he didn't stop. We crashed head-on. He then continue to move to the side and stopped after hitting the roadside curb.

Declaration

I/We declare the foregoing particulars are true in every respect.

 1648 hrs
6th Sep 2022
Policyholder's Signature / Date & Time

 6th Sep 2022 1648 hrs
Driver's Signature (if driver is not the policyholder) / Date & Time

 
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)



SINGAPORE POLICE FORCE

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999



T/20220904/2061

1 of 3

Report No. T/20220904/2061

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 04/09/2022 17:11		Vide Report No.:	Station Diary No.: 12
Informant's Particulars			
Name of Informant: POH WEI REN		Address: APT BLK 210 SERANGOON CENTRAL #05-242 SINGAPORE 550210	
ID Type / ID No.: NRIC NO / S82190581		Contact No.: Home/Office: Mobile: 97724617	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 40	Date of Birth: 30/06/1982	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Secondary school teacher		Driving Licence Information: Class: 2B,2A,3 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 02/09/2022 21:20	Type of Location: T-Junction
Location: JURONG EAST STREET 21				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head On			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKC8198P	Car	KIA	CERATO 1.6(A) EX	Grey	Totally Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKC8198P	ALLIANZ INSURANCE SINGAPORE PTE. LTD.	SP2001255360	21/03/2022	20/03/2023



**SINGAPORE
POLICE FORCE**



T/20220904/2061

2 of 3

Report No. T/20220904/2061

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

CONTINUATION OF REPORT

Brief Details.

On this date this time I met with an accident opposite Ng Teng Fong Hospital. My car, plate number: SKC8198P was hit head on against another car.

I was injured and was conveyed to Ng Teng Fong Hospital via ambulance. I received 5 days MC from the hospital

I am making this police report for insurance claiming purposes.

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorized

ESTIMATE

11 Pgs B

Running After Paint

9 days

ATTN: ACCIDENT CLAIMS DEPARTMENT

DATE : 07.09.2022
VEHICLE NO : SKC8198P
VEH MAKE/MODEL : KIA CERATO
YOM : 2018
CHASSIS NO : KNAF3416MK5029629
DATE OF ACCIDENT : 02.09.2022

NO	QTY	DESCRIPTION	AMOUNT \$
		LIST PRICE:-	
1	1	FRONT BONNET <i>Rx</i>	
2	1	FRONT BONNET HINGE <i>Rx</i>	
3	1	FRONT BONNET LOCK <i>Diy ✓</i>	
4	1	FRONT BONNET SEAL <i>Rx</i>	
5	1	FRONT BUMPER <i>CM ✓</i>	
6	2	FRONT BUMPER SIDE RETAINER LH & RH <i>Diy ✓</i>	
7	1	FRONT EMBLEM <i>Rx ✓</i>	
8	1	FRONT GRILLE BASE <i>CM ✓</i>	
9	1	FRONT GRILLE <i>CRM</i>	
10	1	FRONT GRILLE CENTRE CHROME <i>CM</i>	
11	1	FRONT BUMPER LOWER GRILLE <i>CM</i>	
12	1	TOWING COVER <i>Rx</i>	
13	1	FRONT HEADLAMP LH <i>CM</i>	
14	1	FRONT HEADLAMP LOWER BRACKET LH ?	
15	1	FRONT HEADLAMP RH <i>CM ✓</i>	
16	1	FRONT HEADLAMP LOWER BRACKET RH ?	
17	1	FRONT LH FOGLAMP <i>CM ✓</i>	
18	1	FRONT LH FOGLAMP GARNISH <i>Rx</i>	
19	1	FRONT RH FOGLAMP ?	
20	1	FRONT RH FOGLAMP GARNISH <i>Rx</i>	
21	1	FRONT LH FENDER <i>Rx</i>	
22	1	FRONT LH FENDER INNER SHIELD <i>Diy ✓</i>	
23	1	FRONT RH FENDER <i>Rx</i>	
24	1	FRONT RH FENDER INNER SHIELD <i>Rx</i>	
25	1	FRONT SUPPORT PANEL <i>Rx ✓</i>	
26	1	FRONT SUPPORT PANEL TOP GARNISH <i>Rx</i>	
27	1	FRONT REINFORCEMENT BAR <i>Rx ✓</i>	
28	2	FRONT REINFORCEMENT ARM <i>Rx</i>	
29	1	HORN ?	
30	1	RADIATOR ?	
31	1	RADIATOR AIRDUCT CENTRE ?	
TOTAL - LIST ITEM			\$ -
LIST 10%			\$ -
TOTAL			\$ -

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

DATE : 07.09.2022
VEHICLE NO : SKC8198P
VEH MAKE/MODEL : KIA CERATO
YOM : 2018
CHASSIS NO : KNAF3416MK5029629
DATE OF ACCIDENT : 02.09.2022

ATTN: ACCIDENT CLAIMS DEPARTMENT

NO	QTY	DESCRIPTION	AMOUNT \$
31	2	RADIATOR AIR GUIDE LH & RH <i>Di</i>	\$ 500.00
32	1	RADIATOR TOP STOPPER <i>Per X</i>	\$ 170.00
33	2	RADIATOR LOWER STOPPER <i>Per X</i>	\$ 299.00
34	1	RADIATOR HOSE *TOP <i>In X</i>	\$ 140.00
35	1	RADIATOR HOSE *2ND TOP <i>?</i>	\$ 190.00
36	1	RADIATOR HOSE *LOWER <i>?</i>	\$ 250.00
37	1	WASHER TANK <i>Per</i>	\$ 155.00
38	1	WASHER TANK CAP <i>In X</i>	\$ 250.00
39	1	WASHER TANK HOSE <i>Per X</i>	\$ 35.00
40	1	ENGINE TOP COVER <i>Per X</i>	\$ 170.00
41	1	AIRCON CONDENSER <i>By</i>	\$ 55.00
42	1	AIRCON CONDENSER PIPE CENTRE <i>?</i>	\$ 190.00
43	1	AIRCON CONDENSER DISCHARGE HOSE/PIPE <i>?</i>	\$ 16.00
44	1	AIRCON FAN <i>CM</i>	\$ 34.00
45	2	RADIATOR FAN MOTOR <i>}</i>	\$ 15.00
46	2	RADIATOR FAN BLADE <i>}</i>	\$ 38.00
47	2	RADIATOR FAN COWLING <i>}</i>	\$ 140.00
48	1	ENGINE TOP COVER <i>Per X</i>	\$ 580.00
49	2	AIRBAG SENSOR *FRONT <i>Per</i>	\$ 90.00
50	1	AIRBAG CONTROL UNIT <i>Per</i>	\$ 110.00
51	1	DASHBOARD <i>To</i>	\$ 38.00
52	1	LH AIRBAG <i>Per</i>	\$ 7.00
53	1	RH AIRBAG <i>Per</i>	\$ 1,026.00
54	1	STEERING COLUMN <i>?</i>	\$ 85.00
55	1	STEERING ANGLE SENSOR SPRING <i>Per</i>	\$ 960.00
56	1	LH SEAT BELT <i>To</i>	\$ 156.00
57	1	LH SEAT BELT BUCKLE <i>?</i>	\$ 280.00
58	1	RH SEAT BELT <i>To</i>	\$ 694.00
59	1	RH SEAT BELT BUCKLE <i>?</i>	\$ 22.00
60	1	FRONT WINDSCREEN <i>Per</i>	\$ 38.00
61	1	FRONT WINDSCREEN MOUNDLING <i>Per</i>	\$ 48.00
62	1	ERP BRACKET <i>Per</i>	\$ 350.00
TOTAL - LIST ITEM			\$ 6,931.00
LIST 10%			\$ 693.10
TOTAL			\$ 6,237.90

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

DATE : 07.09.2022
VEHICLE NO : SKC8198P
VEH MAKE/MODEL : KIA CERATO
YOM : 2018
CHASSIS NO : KNAF3416MK5029629
DATE OF ACCIDENT : 02.09.2022

ATTN: ACCIDENT CLAIMS DEPARTMENT

NO	QTY	DESCRIPTION	AMOUNT \$
63	1	AIR FILTER BOX ↗	
62	1	AIR DUCT ↗	
63	2	AIROCN COWLING MOULDING ↗	
64	1	AMBIENT SENSOR ↗	
65			
66			
67			
68			
69			
70			
71			
72			
73			
74			
75			
76			
77			
78			
79			
80			
81			
82			
83			
84			
85			
86			
87			
88			
89			
90			
91			
92			
TOTAL - LIST ITEM			\$ -
LIST 10%			\$ -
TOTAL			\$ -

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

DATE : 07.09.2022
VEHICLE NO : SKC8198P
VEH MAKE/MODEL : KIA CERATO
YOM : 2018
CHASSIS NO : KNAF3416MK5029629
DATE OF ACCIDENT : 02.09.2022

ATTN: ACCIDENT CLAIMS DEPARTMENT

NO	QTY	DESCRIPTION	AMOUNT \$
SPECIAL NETT ITEMS:-			
1	2 SET	CAR PLATE NUMBER WITH FRAME (FRONT & REAR)	\$ 100.00
2	SET	FRONT BUMPER & GRILLE CLIPS	\$ 50.00
3	SET	FRONT BOTH SIDE FENDER SHIELD CLIPS	\$ 50.00
4	SET	RADIATOR TOP GARNISH & UNDER ENGINE COVER CLIPS	\$ 50.00
5	1	FRONT WINDSCREEN SEALANT	\$ 80.00
6			
Total - SN Item			\$ 330.00
Labour Charges:-			
1		SPRAY PAINT ON ALL AFFECTED AREA	\$ 1,800.00
2		LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	\$ 2,000.00
3		TO CHECK WIRING SYSTEM & LIGHT	\$ 100.00
4		TO REPAIR/ADJUST/REALIGN FRONT MAIN CHASSIS & CROSSMEMBER	\$ 350.00
5		TO REMOVE/REFIX/REPLACE FRONT BOTH SELT & BUCKLE	\$ 200.00
6		TO REMOVE.REFIX.REPLACE THE NECESSARY ATTACHMENT IN CONNECTION LH & RH AIRBAG, UNDER STEERING AIRBAG, DASHBOARD, STEERING COLUMN, CLOCK SPRING & ETC....	\$ 800.00
7		TO REMOVE/REPLACE RADIATOR & AIROCN CONDENSOR (REMOVE PIPE, HOSE & ETC... TOP UP COOLANT, AIRCON GAS & ETC....	\$ 280.00
8		COMPUTER DIAGNOSTIC (RESET AIRBAG CONTROL UNIT & NECESSARY IN CONNECT)	\$ 500.00
9		TO REMOVE/REFIX/REPLACE FRONT WINDSCREEN	\$ 180.00
10			
11			
Total - L/C			\$ 6,210.00
Sub-Total			#REF!
GST			#REF!
Total			#REF!

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ACCOUNT AUTO SERVICES INC LTD

1000 Highway 101, Unit 101, Mississauga, Ontario L4W 5G1
 Tel: (905) 270-1111 Fax: (905) 270-1112
 Email: info@accountauto.com Website: www.accountauto.com

ESTIMATE

DATE: 10/1/11
 TIME: 10:00 AM
 BY: [Signature]
 FOR: [Signature]
 VEHICLE: 2008 Ford Focus
 MAKE: Ford
 MODEL: Focus
 YEAR: 2008
 VIN: 1FADP3A58DL123456
 LICENSE: ABC 123

NO.	DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL PRICE
1	Paint	1	100.00	100.00
2	Labour	1	100.00	100.00
3	Parts	1	100.00	100.00
4	Paint	1	100.00	100.00
5	Labour	1	100.00	100.00
6	Parts	1	100.00	100.00
7	Paint	1	100.00	100.00
8	Labour	1	100.00	100.00
9	Parts	1	100.00	100.00
10	Paint	1	100.00	100.00
11	Labour	1	100.00	100.00
12	Parts	1	100.00	100.00
13	Paint	1	100.00	100.00
14	Labour	1	100.00	100.00
15	Parts	1	100.00	100.00
16	Paint	1	100.00	100.00
17	Labour	1	100.00	100.00
18	Parts	1	100.00	100.00
19	Paint	1	100.00	100.00
20	Labour	1	100.00	100.00
21	Parts	1	100.00	100.00
22	Paint	1	100.00	100.00
23	Labour	1	100.00	100.00
24	Parts	1	100.00	100.00
25	Paint	1	100.00	100.00
26	Labour	1	100.00	100.00
27	Parts	1	100.00	100.00
28	Paint	1	100.00	100.00
29	Labour	1	100.00	100.00
30	Parts	1	100.00	100.00
31	Paint	1	100.00	100.00
32	Labour	1	100.00	100.00
33	Parts	1	100.00	100.00
34	Paint	1	100.00	100.00
35	Labour	1	100.00	100.00
36	Parts	1	100.00	100.00
37	Paint	1	100.00	100.00
38	Labour	1	100.00	100.00
39	Parts	1	100.00	100.00
40	Paint	1	100.00	100.00
41	Labour	1	100.00	100.00
42	Parts	1	100.00	100.00
43	Paint	1	100.00	100.00
44	Labour	1	100.00	100.00
45	Parts	1	100.00	100.00
46	Paint	1	100.00	100.00
47	Labour	1	100.00	100.00
48	Parts	1	100.00	100.00
49	Paint	1	100.00	100.00
50	Labour	1	100.00	100.00
51	Parts	1	100.00	100.00
52	Paint	1	100.00	100.00
53	Labour	1	100.00	100.00
54	Parts	1	100.00	100.00
55	Paint	1	100.00	100.00
56	Labour	1	100.00	100.00
57	Parts	1	100.00	100.00
58	Paint	1	100.00	100.00
59	Labour	1	100.00	100.00
60	Parts	1	100.00	100.00
61	Paint	1	100.00	100.00
62	Labour	1	100.00	100.00
63	Parts	1	100.00	100.00
64	Paint	1	100.00	100.00
65	Labour	1	100.00	100.00
66	Parts	1	100.00	100.00
67	Paint	1	100.00	100.00
68	Labour	1	100.00	100.00
69	Parts	1	100.00	100.00
70	Paint	1	100.00	100.00
71	Labour	1	100.00	100.00
72	Parts	1	100.00	100.00
73	Paint	1	100.00	100.00
74	Labour	1	100.00	100.00
75	Parts	1	100.00	100.00
76	Paint	1	100.00	100.00
77	Labour	1	100.00	100.00
78	Parts	1	100.00	100.00
79	Paint	1	100.00	100.00
80	Labour	1	100.00	100.00
81	Parts	1	100.00	100.00
82	Paint	1	100.00	100.00
83	Labour	1	100.00	100.00
84	Parts	1	100.00	100.00
85	Paint	1	100.00	100.00
86	Labour	1	100.00	100.00
87	Parts	1	100.00	100.00
88	Paint	1	100.00	100.00
89	Labour	1	100.00	100.00
90	Parts	1	100.00	100.00
91	Paint	1	100.00	100.00
92	Labour	1	100.00	100.00
93	Parts	1	100.00	100.00
94	Paint	1	100.00	100.00
95	Labour	1	100.00	100.00
96	Parts	1	100.00	100.00
97	Paint	1	100.00	100.00
98	Labour	1	100.00	100.00
99	Parts	1	100.00	100.00
100	Paint	1	100.00	100.00

Account Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

Not Authorized
 @ 14,721.29
 Running After Paint
 9 days

ESTIMATE

DATE: 07.09.2022
 VEHICLE NO: SKC8198P
 VEH MAKE/MODEL: KIA CERATO
 YOM: 2018
 CHASSIS NO: KNAF3416MK5029629
 DATE OF ACCIDENT: 02.09.2022

ATTN: ACCIDENT CLAIMS DEPARTMENT

NO	QTY	DESCRIPTION	AMOUNT \$
		<u>LIST PRICE:-</u>	
1	1	FRONT BONNET <i>Rx</i>	1659.81
2	1	FRONT BONNET HINGE <i>Rx</i>	32
3	1	FRONT BONNET LOCK <i>Dis ✓</i>	92.28
4	1	FRONT BONNET SEAL <i>Rx</i>	
5	1	FRONT BUMPER <i>CM ✓</i>	633.60
6	2	FRONT BUMPER SIDE RETAINER LH & RH <i>Dis ✓</i>	39.64
7	1	FRONT EMBLEM <i>Rx ✓</i>	24.55
8	1	FRONT GRILLE BASE <i>CM ✓</i>	34.02
9	1	FRONT GRILLE <i>CRM ✓</i>	295.34
10	1	FRONT GRILLE CENTRE CHROME <i>CM ✓</i>	210.14
11	1	FRONT BUMPER LOWER GRILLE <i>CM ✓</i>	236.13
12	1	TOWING COVER <i>Rx</i>	8
13	1	FRONT HEADLAMP LH <i>CRM ✓</i>	1220.12 ✓
14	1	FRONT HEADLAMP LOWER BRACKET LH ? <i>Rx</i>	19.82 X
15	1	FRONT HEADLAMP RH <i>CRM ✓</i>	1220.12 ✓
16	1	FRONT HEADLAMP LOWER BRACKET RH ? <i>Rx</i>	19.82 X
17	1	FRONT LH FOGLAMP <i>CRM ✓</i>	273.18
18	1	FRONT LH FOGLAMP GARNISH <i>Rx</i>	32.44
19	1	FRONT RH FOGLAMP <i>Rx</i>	273.18 X
20	1	FRONT RH FOGLAMP GARNISH <i>Rx</i>	32.44
21	1	FRONT LH FENDER <i>Rx</i>	387.30
22	1	FRONT LH FENDER INNER SHIELD <i>Dis ✓</i>	85.40
23	1	FRONT RH FENDER <i>Rx</i>	387.30
24	1	FRONT RH FENDER INNER SHIELD <i>Rx</i>	85.40
25	1	FRONT SUPPORT PANEL <i>Rx</i>	608.86
26	1	FRONT SUPPORT PANEL TOP GARNISH <i>Rx</i>	34.02
27	1	FRONT REINFORCEMENT BAR <i>Rx ✓</i>	448.28
28	2	FRONT REINFORCEMENT ARM <i>Rx ✓</i>	476.20
29	1	HORN ? <i>Rx</i>	66.02 X
30	1	RADIATOR ?	591.10 ✓
31	1	RADIATOR AIRDUCT CENTRE ? <i>Rx</i>	
TOTAL - LIST ITEM			\$ -
LIST 10%			\$ -
TOTAL			\$ -

6489.06

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

DATE : 07.09.2022
VEHICLE NO : SKC8198P
VEH MAKE/MODEL : KIA CERATO
YOM : 2018
CHASSIS NO : KNAF3416MK5029629
DATE OF ACCIDENT : 02.09.2022

ATTN: ACCIDENT CLAIMS DEPARTMENT

NO	QTY	DESCRIPTION	AMOUNT \$
31	2	RADIATOR AIR GUIDE LH & RH <i>Dis - \$50</i>	\$ 400.00
32	1	RADIATOR TOP STOPPER <i>Per x</i>	\$ 170.00
33	2	RADIATOR LOWER STOPPER <i>Per x \$14.60</i>	\$ 29.20
34	1	RADIATOR HOSE *TOP <i>Per x \$24.30</i>	\$ 140.00
35	1	RADIATOR HOSE *2ND TOP <i>Per \$28</i>	\$ X 190.00
36	1	RADIATOR HOSE *LOWER <i>Per \$36</i>	\$ X 250.00
37	1	WASHER TANK <i>Per \$</i>	\$ 155.00
38	1	WASHER TANK CAP <i>Per x \$</i>	\$ 250.00
39	1	WASHER TANK HOSE <i>Per x \$24.30</i>	\$ 35.00
40	1	ENGINE TOP COVER <i>Per x</i>	\$ 170.00
41	1	AIRCON CONDENSER <i>Per \$620</i>	\$ 55.00
42	1	AIRCON CONDENSER PIPE CENTRE <i>Per \$</i>	\$ X 190.00
43	1	AIRCON CONDENSER DISCHARGE HOSE/PIPE <i>Per \$110</i>	\$ X 16.00
44	1	AIRCON FAN <i>Per \$591.20</i>	\$ 34.00
45	2	RADIATOR FAN MOTOR <i>Per x</i>	\$ 15.00
46	2	RADIATOR FAN BLADE <i>Per x</i>	\$ 38.00
47	2	RADIATOR FAN COWLING <i>Per x</i>	\$ 140.00
48	1	ENGINE TOP COVER <i>Per x</i>	\$ 580.00
49	2	AIRBAG SENSOR *FRONT <i>Per \$92</i>	\$ 90.00
50	1	AIRBAG CONTROL UNIT <i>Per \$1025.60</i>	\$ 110.00
51	1	DASHBOARD <i>Per \$1280</i>	\$ 38.00
52	1	LH AIRBAG <i>Per \$1276</i>	\$ 7.00
53	1	RH AIRBAG <i>Per \$922.30</i>	\$ 1,026.00
54	1	STEERING COLUMN <i>Per \$2997</i>	\$ X 85.00
55	1	STEERING ANGLE SENSOR SPRING <i>Per \$278</i>	\$ 960.00
56	1	LH SEAT BELT <i>Per \$289</i>	\$ 156.00
57	1	LH SEAT BELT BUCKLE <i>Per \$161</i>	\$ X 280.00
58	1	RH SEAT BELT <i>Per \$285.30</i>	\$ 694.00
59	1	RH SEAT BELT BUCKLE <i>Per \$103</i>	\$ X 22.00
60	1	FRONT WINDSCREEN <i>Per \$321.13</i>	\$ 38.00
61	1	FRONT WINDSCREEN MOUNDLING <i>Per \$45.73</i>	\$ 48.00
62	1	ERP BRACKET <i>Per \$100</i>	\$ 330.00
TOTAL - LIST ITEM			\$ 6,931.00
LIST 10%			\$ 693.10
TOTAL			\$ 6,237.90

7531-26

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

DATE : 07.09.2022
 VEHICLE NO : SKC8198P
 VEH MAKE/MODEL : KIA CERATO
 YOM : 2018
 CHASSIS NO : KNAF3416MK5029629
 DATE OF ACCIDENT : 02.09.2022

ATTN: ACCIDENT CLAIMS DEPARTMENT

NO	QTY	DESCRIPTION	AMOUNT \$
63	1	AIR FILTER BOX	\$156.16
62	1	AIR DUCT	\$49
63	2	AIROCN COWLING MOULDING	
64	1	AMBIENT SENSOR	\$41.
65			
66			
67			
68			
69			
70			
71			
72			
73			
74			
75			
76			
77			
78			
79			
80			
81			
82			
83			
84			
85			
86			
87			
88			
89			
90			
91			
92			
TOTAL - LIST ITEM			\$ -
LIST 10%			\$ -
TOTAL			\$ -

ACCORD AUTO SERVICES PTE LTD

10 Ang Mo Kio Industrial Park 2A

#03-11 AMK Autopoint Singapore 568047

Tel: 6481 9518 / 6481 9517 Fax: 6481 9516 email: claims@mycarworkshop.com.sg

ESTIMATE

DATE: 07.09.2022
VEHICLE NO: SKC8198P
VEH MAKE/MODEL: KIA CERATO
YOM: 2018
CHASSIS NO: KNAF3416MK5029629
DATE OF ACCIDENT: 02.09.2022

ATTN: ACCIDENT CLAIMS DEPARTMENT

NO	QTY	DESCRIPTION	AMOUNT \$
<u>SPECIAL NETT ITEMS:-</u>			
1	2 SET	CAR PLATE NUMBER WITH FRAME (FRONT & REAR)	\$ 100.00
2	SET	FRONT BUMPER & GRILLE CLIPS	\$ 50.00
3	SET	FRONT BOTH SIDE FENDER SHIELD CLIPS	\$ 50.00
4	SET	RADIATOR TOP GARNISH & UNDER ENGINE COVER CLIPS	\$ 50.00
5	1	FRONT WINDSCREEN SEALANT	\$ 80.00
6			
Total - SN Item			\$ 330.00
<u>Labour Charges:-</u>			
1		SPRAY PAINT ON ALL AFFECTED AREA	\$ 1,800.00
2		LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	\$ 2,000.00
3		TO CHECK WIRING SYSTEM & LIGHT	\$ 100.00
4		TO REPAIR/ADJUST/REALIGN FRONT MAIN CHASSIS & CROSSMEMBER	\$ 350.00
5		TO REMOVE/REFIX/REPLACE FRONT BOTH SELT & BUCKLE	\$ 200.00
6		TO REMOVE/REFIX/REPLACE THE NECESSARY ATTACHMENT IN CONNECTION LH & RH AIRBAG, UNDER STEERING AIRBAG, DASHBOARD, STEERING COLUMN, CLOCK SPRING & ETC....	\$ 800.00
7		TO REMOVE/REPLACE RADIATOR & AIROCN CONDENSOR (REMOVE PIPE, HOSE & ETC... TOP UP COOLANT, AIRCON GAS & ETC....	\$ 280.00
8		COMPUTER DIAGNOSTIC (RESET AIRBAG CONTROL UNIT & NECESSARY IN CONNECT)	\$ 500.00
9		TO REMOVE/REFIX/REPLACE FRONT WINDSCREEN	\$ 180.00
10			
11			
Total - L/C			\$ 6,210.00
Sub-Total			#REF!
7% GST			#REF!
Total			#REF!

Page 5/5

12.8.2021

2075