Our Ref:

CT0922/SHA1476D/CK(st)

Date:

08.12.2022



OMFORTDELGRO

CHINA TAIPING INSURANCE CO (S)PTE L

3 ANSON ROAD #16-00 Singapore 079909

Dear Sir/Madam

Attn: Motor Claims Department

Without Prejudice

205 Braddell Road Singapore 579701

ComfortDelGro Engineering Pte Ltd

Mainline +65 6383 6280 Facsimilie +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

ACCIDENT ON 06.09.2022 INVOLVING SHA1476D & SLW3782T ALONG PARKWAY PARADE

We are the authorised repair workshop for Comfort Transportation Pte Ltd , the owner of vehicle No SHA1476D, which was involved in the captioned accident with your insured vehicle No SLW3782T.

The vehicle owner and the taxi hirer/driver concerned have requested and authorised us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage of the vehicle.

As the accident was caused by the negligent act of your insured driver, we are submitting these claims for your consideration on behalf of the claimants:

Workshops

Braddell 205 Braddell Road Singapore 579701

Lovang 59 Loyang Drive Singapore 508969

Sin Ming 383 Sin Ming Drive

Singapore 575717

45 Pandan Road Singapore 609286

Ubi 320 Ubi Road 3 Singapore 408649

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

Taxi	Owne	r's	Claim	:
------	------	-----	-------	---

1. Cost of Repairs		S\$	802.50
2. Loss of Rental	2.5 days x S\$ 110.67	S\$	276.68
3. Survey Report Fee		S\$	0.00
4. LTA Search Fee		S\$	0.00
5. GIA / Police Report Fee		S\$	2.00
6. Others		S\$	0.00

Hirer's Claim: 1. Loss of Income 2. Others	2.5	days x S\$ 80.00	S\$ S\$	200.00 0.00	
	[E&OE]	Total Claims	SŚ	1.281.18	
	[-00-]		- +	_,	

A copy each of the following supporting documents marked [X] is enclosed:

[X]	Original Repair Bill	[X]	Letter of Authority from Owner/Hirer/Operator				
[X]	GIA/Police Report(s)	[X]	Rental Rate Letter				
K)	LTA/GIA Search Slip(s)	[X]	Downtime/Mileage Record				
N []	Survey Report / Bill	[]	Witness Statement / Accident Scene Photo(s)				
[]	Driver's IC/DL/VL / Road Tax / Log Card / Certificate of Insurance						
[]	Tow Chit / PIR / Hirer's IRAS / Others:						

Kindly look into the matter and let us hear from you on the settlement of our clients' claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours sincerely Catherine Koh **CDGE Claims Department**

FAX: -DID: 62148733

Email: catherinekoh@cdge.com.sg

This is a computer-generated letter. No signature is required.



LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING i 40 SHA1476D , SLW3782T

PARKWAY PARADE

I / We

ALONG

TAN HOCK CHAI

(Hirer) NRIC No.:

SXXXX465I

ON 06-Sep-22 20:50

and/or

KOH CHEE KIAN

(Relief) NRIC No.: SXXXX145D

Taxi Number

SHA1476D

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of earning (Pending successful recovery), loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

07-Sep-2022

Name of Hirer

TAN HOCK CHAI

Hirer NRIC

SXXXX465I

Signature:

Address

800 YISHUN RING ROAD #08-4383

760800

Contact No.

96780432

Name of Relief

KOH CHEE KIAN

Relief NRIC

SXXXX145D

Signature:

S

Address

406 YISHUN AVENUE 6 07-1314

760406

Contact No.

96393933



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 45 Pandan Road Singapore 609286

ad Singapore 579701
Singapore 508969
Singapore 609286
COMPANY
REG.
NO:: 199506048W

Page: 1

GST REG. NO. M2-8921817-3

TAX INVOICE

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD SPRINGLEAF TOWER

3 ANSON ROAD #16-00 SINGAPORE 079909

CONTACT NO: 62222366

VEHCLE NO SHA1476D

NO/DATE 92828453 02.12.2022

MAKE HYUNDAI JOB NO. 305529193

MODEL I-40

ODOMETER READING

DATE OF REG 11.01.2017

CHASSIS CODE

JOB TYPE

KMHLB41UMHU098211

Description: 3P.06.09.22

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt 7.000

Total Invoice amount

802.50

Issued by : KATHERINETAN 02.12.2022 13:35:16 Repair Type : CLSO/57/57 Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd

Head Office: 205 Braddell Road Singapore 579701

ACCOUNT No. INVOICE No. **AMOUNT** BANK/CHQ No

Kindly note that no receipt shall be issued unless requested.

Our Ref: CT22090094

Date: 09 September 2022



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 06/09/2022 @ 20:50 hrs

ALONG PARKWAY PARADE

INVOLVING SLW3782T

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHA1476D (the "Taxi"). The Taxi was hired to TAN HOCK CHAI IC NO SXXXX465I a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$110.67 per day (inclusive of GST).

Please be advised that the Taxi was insured with **AXA Insurance Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Philip Chia Manager, Fleet Safety

This is a computer generated letter. No signature is required.

					-										1	1
	HOURS OPERATED (TIME)	2	-1271	2) 1	1655	000	1620	713®	777	7	130				
	HOURS OF	FROM	OFFO	1727		12 42	175	0.73C		3	7050	\				
T C A D II M	TRAVELLED	(KM)	202	7.2.5	} ;		424	23	201		1616 1	5 W 6 4	/11 2			
	MILEAGE READING		5888	78 00 66	\$000 b1		2	9 S £ 0 b-	7 9 9 9 9 7	300		\$ \frac{1}{2}				
- The second sec	NAME OF DRIVER		They Hola a	Caren-	Tan HAO CI	No.		Ten Huy Gh	Ken 4	UTLY VHO	10+1-17	ACO'SOM DEBIN				
SOPERATED (TIME)	TO DATE	1 1 1 2 1 1	22/6/14 82	20/1/8 to soll	19th 5/9/22	1700 5/9/32	1	3-30 6 9/22	1615 6/9/22	6600) c	1630 8 (4) 23	2243	757	7) (6	0.516
IS OPER	MQ	CA	3	2		04		2	35	14	2	30	20	36	V	2

INSURER ENQUIRY

Find insurer

Vehicle reg. no.

SLW3782T

Date of Accident

06/09/2022

Reset

% RESULT & RECEIPT

TP Insurer Enquiry	
Insurance	
Period of Insurance	
Requested By	
Requested Date	07/09/2022 13:43

Payment details

Request Amount: **\$\$1.87** GST Amount: **\$\$0.13**

Total Amount Due (GST Inclusive): **\$\$2**

General Insurance Association

Records Management Centre GST Registration No: **M400017735**