

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE I		Ref:	CS3/ASM22008846/Gvy3m4		
	8 SHENTON WAY SINGAPORE 0688	#24-01 AXA TOWER 11		Date:	12/09/2022	
	ATTN: LOW GARN	ET		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMZ 4329K	Veh. Inspected		SMR 729H	
	Policy No.	GA622817	Coverage (\$)		0.00	
	Claim No.	S2M04A5O	Excess (\$)		0.00	
	Assign From	LOW GARNET	Assign Date		08/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model	KIA CERATO 1.6	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	KNAF1416MK5052128	Colour		SILVER	
	Odometer	134550 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	225/45 R17	кимно		6 mm	
	L/H Front Tyre	225/45 R17	кимно		6 mm	
	R/H Rear Tyre	225/45 R17	кимно		6 mm	
	L/H Rear Tyre	225/45 R17	КИМНО		6 mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
5. General Information						
	Accident Date	30/08/2022	Inspect Date /	Time	08/09/2022 ( 04:00 PM )	
	Survey held at	D'S GRAFFITI CONCEPTS PTE	LTD			
		8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKI SINGAPORE 415875	Г			
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	5b. Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					

Report Ref No. CS3/ASM22008846/Gvy3m4

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor