


**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 QD  TP /  S / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s: ETHOZ PROTECT  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: GBC3306J Yr Regn: 23 Dec/2011  
 Type: M.Car / M.Cycle / Bus  Van Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: NISSAN NV200 1.5L c.c. 1461  
 Colour: White A/C: Insured / Std / NI / NA  
 Sp. Reading: 309924 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VSKYBAM20U0026101 \*  
 Gen. Cond:  Good / Fair / Poor / Burnt  
 Steering:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake:  Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi:  Nil / S/Rim / STD A/Rim or \_\_\_\_\_

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**  
 Bal. or Market Value: \$35k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 2 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Tyre Size: F: 175/70R14  
 R: //  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or GITI  

<u>Front</u>	<u>Rear</u>
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>08-09-2022</u>

 Survey held at W/S 5PM  
 Des. of Damages  Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Steve confirmed lump sum: \$1000 and 2 days (red, \$927.86, 48%)

Date/Time, File Pass to?  : Preli. Report  
 : Final Report  
 1) 06/01/23  
 Date/Time, File Return to? \_\_\_\_\_

Days Of Repair: 2  
 Resurvey No. of Trip: \_\_\_\_\_

Report Fee: tp  
 Lump Sum / MP: 1000

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Insp (\$ \_\_\_\_\_)  
 : Washend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
3 + RS. SI	
Photos	
Other:	
TOTAL	