

PRS

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP ☒ N/S / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

KING'S AUTO

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: \$14k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SJN6673B

Yr Regn: 25 Feb/2009

Type ☒ M.Car ☐ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HYUNDAI I30 1.6

c.c 1591

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 279737

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMHDC51DR9U163298 *

Gen. Cond ☒ Good ☐ Fair / Poor / BurntSteering: ☒ Inorder ☐ Jammed / Leaked / Burnt orBrake: ☒ Inorder ☐ Jammed / Leaked / Burnt orModi: Nil / S/Rim / ☒ STD A/Rim or

Tyre Size: F: 195/60R16

R: //

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC ☐ OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 24-03-2022

Survey held at

W/S

4PM

Des. of Damages: Frt / ☒ Rea ☐ O/S / N/S / ☒ U/C ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$7000 - \$8000

COE Expiry Date : 24 Feb 2024

Total Rebate Amount: \$4,931.00

24/11/2022 Submit LS \$8,100.00 ; 10 days (Red. \$1,950.00 ; 19%)

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ W/Weekend (\$

\$ + RS. SI

Photos

Other:

TOTAL

Report Filed:

TP

Long Cond / MPB / LS \$8,100.00