

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No. 19900/190R GS1 Reg. No. 19-900/190-R					
Affiliated to Federation Internationale Des Experts En Automobile					
	AUTO & GENERA	L INSURANCE (S) PL	Ref	: CS/AGI22008889/Avy3m4	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	Dat	e: 18/10/2022	
			Cod	de: AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMK 4712R	Veh. Inspected	SMN 8459E	
	Policy No.	P10714246R00	Coverage (\$)	0.00	
	Claim No.	C10017410/CD	Excess (\$)	0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date	09/09/2022	
2. Vehicle Particulars & Condition					
	Make & Model	SUBARU FORESTER	c.c	1995	
	Engine No.	HIDDEN	Year of Reg.	2019	
	Chassis No.	JF1SK7KL5KG009781	Colour	WHITE	
	Odometer	54477 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	225/60 R17	BRIDGESTONE	6 mm	
	L/H Front Tyre	225/60 R17	BRIDGESTONE	6 mm	
	R/H Rear Tyre	225/60 R17	BRIDGESTONE	6 mm	
	L/H Rear Tyre	225/60 R17	BRIDGESTONE	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5. General Information					
	Accident Date	08/09/2022	Inspection Date	21/09/2022	
	Survey held at SM AUTOMOTIVE				
		BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883			
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				

**6 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: