

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	03/09/2022 10:52 (SGT)
Reported by	Both
Date of Accident	01/09/2022 20:05 (SGT)
Exact Location of Accident	Ophir Rd, Singapore
Additional Location Information	OPHIR ROAD (DIRECTION OF ECP BETWEEN REACH ROAD,NORTH BRIDGE RD)
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGX6628R
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	LAM KUAN HONG COLIN
NRIC No	S7436173J
Email Address	cofe_club@yahoo.com.sg
Mobile Phone No	(Phone) +65-98768188
Alternative Phone No	-

## VEHICLE PARTICULARS

Manufacturer	Mercedes
Model	E200
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2000

## INSURANCE COMPANY

Name of Insurance Company	Sompo Insurance Singapore Pte. Ltd.
Policy Number / Cover Note Number	D21MTPV01012475

## DRIVER

Name of Driver	LAM KUAN HONG COLIN
NRIC No	S7436173J
Date Of Birth	27/10/1974

Occupation .....	Indoor
Date Of Driving Pass .....	04/10/1995
Driving experience .....	26 YEARS AND 11 MONTHS
Gender .....	Male
Mobile Number .....	(Phone) +65-98768188
Alt. Phone Number .....	-
Email Address .....	cofe_club@yahoo.com.sg
Address .....	11A WILTON GARDENS
Address complement .....	-
Postcode .....	455181
Is the driver the policyholder? .....	Yes
If No, Relationship of the Driver with the Insured .....	-
Does Driver Own Other Vehicles? .....	No
Vehicle Registration Number of Other Vehicle Owned by Driver .....	-
Insurance Company of Other Vehicle Owned by Driver .....	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident .....	Collision - Head to Rear
Weather Conditions .....	Clear
Road Surface .....	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? .....	No
Number of vehicles involved in the accident .....	2
Was anybody injured in the Accident? .....	No
Was any injured conveyed to hospital by ambulance? .....	-
Was any other vehicle or property damaged? .....	Yes
Number of Passengers (Including Driver) .....	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? .....	No
Translator's name .....	-
Translator's ID .....	-
Translator's phone number .....	-
Translator's email .....	-
Original language used in the statement .....	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? .....	No
Was notice of intended Prosecution given? .....	No
If yes, against whom? .....	-

#### CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED.

#### ATTACHMENT(S)

Are accident photos available for attachment? .....	Yes
Was there any video captured by Car Camera? .....	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number .....	WC6718
Vehicle Manufacturer .....	Isuzu
Vehicle Model .....	-
Vehicle Variant .....	-
Vehicle Colour .....	-
Vehicle Category .....	Commercial vehicle
Name of Driver .....	GANESAN SANKARAN KARTHIKEYAN



**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that :  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/rail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
02 Sep 2022 1445 hrs

Policyholder's Signature / Date & Time


  
02 Sep 2022 1455 hrs

Driver's Signature (if driver is not the policyholder) / Date & Time

COMFORTDELORO ENGINEERING (PTE) LTD  
320 UDI ROAD 3  
SINGAPORE 408660

Witnessed by Reporting Centre Personnel

**Sketch Plan**



Describe Circumstances of the Accident

Cement Truck Driver : Gransan Sanbaruan Kartikayyan  
 FIN : G325 3795U , S Pass : 03711863 -  
 Sector : Construction ,  
 Employer : Sayoon Builders & Designers Pte Ltd.

At 2005 hrs Ophir Road in direction of ECP. This is wide 5 lane road that was bright, well lit and accident happen at straight side of Ophir Road. Evening was dry weather, there were no rain and road was dry without any debris, oil patch or wet.

Owner car SGX6628E was stationary on lane 3 behind a row of cars as traffic light in front (Ophir road and beach road junction) was red.

Front row of vehicles started to move. Car directly in front of me moved off slowly. I lift my foot off brake pedal slowly, my car moved slightly ahead but I step on brake again because car in front of me braked to complete stop.

My car stopped completely easily because I only lift foot off brake and within 1-2 seconds step on brake again. My car stopped.

As I stop my car, heard sound behind me, vehicle behind slam into my car rear. Look at mirror was a construction vehicle.

Behind me was cement truck Isuzu WC6718E driven by above mentioned truck driver.

Impact was direct into owner car rear, from subsequent inspection and photo taken, rear bumper was bang in, rear boot deform inward and upward, paint work crack, rear light came out and protrude out of body. Truck dark blue paint was on my bumper and boot lid. Impact quite strong to driver (me) and body swing forward and car also pushed forward.

I stop car, press hand brake, shut engine off and came out of car.

Driver in truck, took a while before came down. I ask him if okay, where is he going, is he working or go home. He said truck he step brake but truck cannot stop. He said sorry. I ask for name, identity and insurance company. I ask if he is approved driver but think he does not understand.

He show S pass, gave me name and tell me he try call supervisor.


Supervisor HP 91330058 over driver phone ask to settle private.


I told him no, both parties ought to report and make claims. Call ended.

I told driver take care, drive slowly as vehicle is big, heavy and need big gap in front to have safe brake distance. I went into car and drive back home.

Declaration

I/We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature / Date  
 02 Sep 2022 (1512hr)

  
 Driver's Signature (if driver is not the policyholder) / Date  
 02 Sep 2022 (1512hr)

COMFORTDELGRO ENGINEERING PTE  
 320 UBI ROAD 3  
 SINGAPORE 408649

Witnessed by Reporting Centre  
 Personnel