

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Reg. No. 199007190N GS1 Neg. No. 19-9007190-N | | | | | |
|---|---|--|-----------------|-------|---------------------|--|
| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
| | AUTO & GENERA | L INSURANCE (S) PL | | Ref: | CS/AGI22008910/Avy3 | |
| | | INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE | | Date: | 12/09/2022 | |
| _ | | | | Code: | | |
| 1. | · | | | | | |
| | Insured Veh. | SCW 680E | Veh. Inspected | | SLR 4178H | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | C10017419/JY | Excess (\$) | | 0.00 | |
| | Assign From | MAYBIE CHUA | Assign Date | | 12/09/2022 | |
| 2. | 2. Vehicle Particulars & Condition | | | | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer | - | Steering | | | |
| | Brakes | | Modification | | | |
| | General | | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 09/09/2022 | Inspection Date | е | 12/09/2022 | |
| | Survey held at | PREMIUM CARZ SERVICES PTE LTD | | | | |
| | | 1 KAKI BUKIT AVE 6 # 01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883 | | | | |
| 5a. | 5a. Remarks | | | | | |

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.